



PAINT ADHESION TO BACKSIDE OF WELDS

Application

This procedure is used to measure the paint adhesion at the backside of MIG/GMAW welds.

Materials Required

Adhesion Tape

No. 898 (Minnesota, Mining and Manufacturing Co. - 3M) 24 mm wide.



-or-

An Equivalent 24 mm wide tape can be used if agreed upon by Ford Materials Engineering as long as the peel strength is greater than 0.6 N/mm per ASTM D3330, Method A.

The shelf life of these tapes is 12 months when stored in the original package in a dry, dark location.

Procedure

1. Locate the backside side of a MIG weld.



Date	Action	Revisions	Rev. 0
2017 05 03	Released		

N. Horton & A. Wedepohl (NA)

Documents


Document Sharing Hub

2. Apply the tape by firmly pressing it onto the surface over the area containing the back side of the weld. Remove the tape within 90 +/- 30 seconds of application by pulling it off rapidly (not jerked) back upon itself at as close to an angle of 180° to the sample as possible.

Evaluation

3. Report the percentage of adhesion loss using the Adhesion Loss Table as a visual reference.

Photo of paint adhesion loss on the back side of a weld



Note: The reference images in the Adhesion Loss table are based on a 10 mm wide weld area (light grey lines) a weld length of 40 mm and a tape width of 24 mm. The percent loss is calculated from the weld width and length and not the tape width and length.

Adhesion Loss Table	
Classification	Tape Appearance
0% loss	