

Title: Calibration Of Weir 6 Inch D.C. Voltmeter 0 – 50V

Scope

Work Instruction for the internal calibration of Weir 6 Inch D.C. Voltmeter 0 – 50V. To be used in the absence of a manufacturers calibration instruction

Preparation

Calibration must be carried out using Category A Master instruments as required.

Equipment required;-

- 1.1 Datron 9100 Calibrator.
- 1.2 45⁰ Instrument Balance Stand.

Method

- 2.1 All calibration results must be entered on the results sheets (see appendix A).
- 2.2 Note the lab. temperature / R.H. and enter onto the results sheet.
- 2.3 Carry out test 1.
- 2.4 Carry out test 2 using item 1.2.
- 2.5 Carry out tests 3 to 7 using item 1.1.
- 2.6 Complete the results sheet header and enter Pass / Fail.

- All records must be kept for audit purposes

References

Appendix A Calibration of Weir 6 Inch D.C. Voltmeter 0 – 50V

Title: Calibration Of Weir 6 Inch D.C. Voltmeter 0 – 50V

Appendix A

Calibration of Weir 6 Inch D.C. Voltmeter 0 – 50V

Model Serial No

Date Result

Lab Temp / RH Operator

User Location Certificate No

Accuracies quoted are from manufacturer's specifications or relevant British Standard.

Movement Check

Test 1 Is pointer on zero? Pass / Fail

Test 2 Instrument balance $\pm 1\%$ at 45° all planes Pass / Fail

Voltage Calibration Accuracy $\pm 2\%$ F.S.D.

Test No	UUT Indication Volts	Calibrator Voltage	Allowed Limits	Result
3	10		9 to 11	Pass / Fail
4	20		19 to 21	Pass / Fail
5	30		29 to 31	Pass / Fail
6	40		39 to 41	Pass / Fail
7	50		49 to 51	Pass / Fail

The UUT was calibrated using the following equipment:

1. Datron 9100 Calibrator S/N _____

The uncertainty in the applied value is estimated not to exceed:

D.C. Volts: $\pm 0.03\%$

The uncertainty limits quoted refer to the applied values only and do not relate to the stability of the UUT.