

Task Risk Control Sheet

Jet Washing of Level Crossings

RCS No: NR/L3/MTC/RCS0216/GA23
Issue: 2

Key Risks !

- Struck by Train
- Electrocution
- Manual Handling
- Slips, Trips & Falls

Personnel Involved

E&P	✓
S&T	✓
Track	✓
Off Track	✓
Property	✓

Tools / Equipment

Jet Washing Lance

Plant

Generator

JET WASHING OF LEVEL CROSSINGS SHALL ONLY BE UNDERTAKEN IN A GREEN ZONE

Task Risks	Controls	Implemented By
Struck by Train	<ul style="list-style-type: none"> • See Risk Control Sheets NR/L3/MTC/RCS0216/GA01 - Work on or near the line 	Team Leader / COSS
Manual Handling	<ul style="list-style-type: none"> • See Risk Control Sheets NR/L3/MTC/RCS0216/GH01 – Manual Handling. 	Team Leader / Staff
Slips Trips and Falls	<ul style="list-style-type: none"> • See Risk Control Sheets NR/L3/MTC/RCS0216/GH02 – Underfoot Conditions. • Staff shall pay particular attention to areas where jet washing has been undertaken 	Person in Charge/ Staff
Transport of Water Bowser	<ul style="list-style-type: none"> • Driver of the road vehicle shall take cognizance of the load being unstable. This requires gentle acceleration and braking and avoiding sudden turning at speed. 	Driver
Electrocution	<ul style="list-style-type: none"> • See Risk Control Sheets NR/L3/MTC/RCS0216/GA20 - Working adjacent to DC electrified rail Levels 1-5 • See Risk Control Sheets NR/L3/MTC/RCS0216/GA21 - Working Near electrified overhead line equipment • When working on a line with live DC electrified rails, always work from the edge of the crossing (with back toward the conductor rail/railway) to the centre. The reverse process must be adopted when cleaning the opposite carriageway – edge of crossing toward centre. Never direct the lance toward a conductor rail. • Lance to be secured and angled to prevent spray coming within 2.75 metres of the overhead line catenary. • Any obstructions which are likely to deflect above ground level shall be avoided 	Team Leader / COSS
Chemical Hazard	<ul style="list-style-type: none"> • See Risk control Sheet NR/L3/MTC/RCS0216/GH03 – Chemical and Biological Hazards • Operator shall wear HV foul weather over trousers, HV foul weather coat, gloves impervious to water, visor or safety goggles to BS EN166.B. • Wash exposed parts of body immediately the work is completed and prior to eating, drinking or smoking. • Operator shall set up a 3 metre exclusion zone • All staff in the vicinity of the operation shall be briefed to go to a position of safety whilst the operation is undertaken. 	Team Leader / COSS

Task Risk Control Sheet

Key Risks	Controls	Implemented By
Road Traffic	<ul style="list-style-type: none"> Barriers shall be lowered on local control or by the controlling signaller for the time required to jet wash the level crossing. For planned work the Highways Authority shall be informed and any necessary road signage placed in position prior to work commencing 	Team Leader / COSS Planner / Team Leader
Use of Generator / Small Plant	<ul style="list-style-type: none"> For planned work the Highways Authority shall be informed and any necessary road signage placed in position prior to work commencing 	Planner / Team Leader
Re-fuelling- Fire / Explosion	<ul style="list-style-type: none"> See Risk Control Sheet NR/L3/MTC/RCS0216/GA17 - Decanting Fuel and Fuelling Small Plant 	Team Leader

PPE Required by NR / Maintenance Policy

				<p>If safety glasses introduce a risk (ie weather conditions) then the Team Leader shall assess the risk. The outcome of the assessment shall be recorded on the SSOWPS pack and safety glasses may be removed.</p> <p>This does not supersede the requirements for eye protection detailed on relevant Task Risk Control Sheets.</p>
Wear Head Protection	Wear Foot Protection	Wear Hi Visibility Clothing	Wear Safety glasses to BS EN166.F	

Additional PPE Required by Task Risk Control Sheet

						
Wear Waterproof Hand Protection	Wear eye Protection BS EN166.B	Wear Hi Visibility Waterproof Clothing				