



Document No.	GIS 12-210
Applicability	Group
Date	05 January 2005

Guidance on Industry Standard for Motor Repair (IEEE 1068)

GIS 12-210

BP GROUP
ENGINEERING TECHNICAL PRACTICES

Foreword

This is the first issue of Engineering Technical Practice (ETP) GIS 12-210. This Guidance on Industry Standard (GIS) is based on parts of heritage documents from the merged BP companies as follows:

Amoco (ACES)

A EL-MT-REP-P	Electrical—Motors—Repair—Supply Specification
A EL-MT-REP-G	Electrical—Motors—Repair—Selection Guide

BP Oil US (Refining Practices)

RP 17-23-1	Induction Motor Repair
------------	------------------------

Uncontrolled Copy

Copyright © 2005, BP Group. All rights reserved. The information contained in this document is subject to the terms and conditions of the agreement or contract under which the document was supplied to the recipient's organization. None of the information contained in this document shall be disclosed outside the recipient's own organization without the prior written permission of Manager, Standards, BP Group, unless the terms of such agreement or contract expressly allow.



Table of Contents

	Page
Foreword	2
Introduction	4
2 References	5
2.1 General	5
2.2 Insulation Tests	5
4 Prerepair activity and responsibility	5
4.1 User responsibility	5
4.2 Repair facility responsibility	5
5. Recondition without damage repair	8
6. Repair Period	8
6.1 Repair facility	8
7. Post repair	13
7.1 Repair facility	13



Introduction

- a. Guidance for motor repair is based on IEEE 1068, IEEE Recommended Practice for the Repair and Rewinding of Motors for the Petroleum and Chemical Industry, September 1996.
- b. Guidance statements of this GIS are modifications to IEEE 1068.
- c. Modifications to IEEE 1068 are identified as Add, Modify to Read, or Delete.
- d. Section numbers in this GIS correspond to IEEE 1068.
- e. Sections of IEEE 1068 that are not revised remain applicable.

