

DIMENSIONAL STABILITY OF TEXTILE TRIM MATERIALS

Application

This method is used to determine the dimensional changes of textile trim materials under the influence of heat and humidity.

Apparatus Required

Mechanical Convection Oven

Capable of maintaining any specified temperature between 80 and 100 °C +/- 2 °C.

Humidity Cabinet

Capable of maintaining a constant temperature of 38 +/- 2 °C and a relative humidity of 98 +/- 2%.

Scale or Ruler

With 0.5 mm divisions.

Conditioning and Test Conditions


All test values indicated herein are based on material conditioned in a controlled atmosphere of 23 +/- 2 °C and 50 +/- 5% relative humidity for not less than 24 hours prior to testing and tested under the same conditions unless otherwise specified.

Procedure

1. The test specimen should be approximately 250 x 250 mm in size. Using a pen or sharp pencil on the finished side (i.e., "appearance" side) draw a 200 mm long line approximately 30 mm in from each edge. Mark the two horizontal lines X1 and X2 and the two vertical lines Y1 and Y2. Materials with a rough surface such as carpet may be marked on the opposite side.

Date	Action	Revisions
2002 11 22	Revised	Rev. Procedures paragraph A. Wedepohl
2001 09 11	Revised	Editorial – no technical change A. Cockman
1990 05 18		

Printed copies are uncontrolled



2. Condition the test specimen for 24 hours in the humidity cabinet at 38 +/- 2 °C and a relative humidity of 98 +/- 2%.
3. Remove and immediately measure all four lines and report the average percent change for the X and Y directions. Calculate the percent change as follows:

$$\% \text{ change in X direction} = [(X1_1 - 200\text{mm})/200\text{mm} + (X2_1 - 200\text{mm})/200\text{mm}] / 2$$

X1₁ = new measured length of line X1

X2₁ = new measured length of line X2

4. Then condition the test specimen for 24 hours in a convection oven at 80 +/- 2 °C or at the temperature specified by the Material Engineering Specification.
5. Remove and immediately measure all four lines and report the changes as in step 3.
6. Repeat steps 2 - 5 as often as required by the number of cycles specified in the relevant Material Engineering Specification. Dimensional changes shall always be calculated from the initial 200mm line length.

Chemicals, materials, parts, and equipment referenced in this document must be used and handled properly. Each party is responsible for determining proper use and handling in its facilities.

Copyright © 2002, Ford Global Technologies, Inc.