

Ref:	NR/L2/ELP/27009/MOD C03
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
03	REPLACEMENT OF SOLID 3/16" COPPER 'V' DROPPERS
COMPONENT	Solid 3/16" (4.8mm) copper "V" droppers.
PROBLEM	The 'V' dropper fails due to fatigue. This causes the registration tube to foul the pantograph.
ACTION REQUIRED	Replace existing copper droppers with 4mm solid stainless steel wire.

Reference Information	
Ellipse standard job number	13003
Ellipse standard job description	Replace Solid 3/16" Copper 'V' dropper
Category	Dropper
Priority	Yes
Types of OLE affected	Ex-DC; Mk1
Original equipment dates	Before 1958



Ref:	NR/L2/ELP/27009/MOD C03
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

Blank Page

Copyright Network Rail