

Ref:	NR/L2/ELP/27009/MOD C04
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
04	REPLACEMENT OF SOLID 3/16" COPPER WINDSTAY DROPPERS
COMPONENT	Solid 3/16" (4.8mm) copper windstay droppers.
PROBLEM	The 'V' dropper fails due to fatigue. This causes it to foul the pantograph.
ACTION REQUIRED	Replace existing copper droppers with 4mm solid stainless steel wire.

Reference Information	
Ellipse standard job number	13004
Ellipse standard job description	Replace solid 3/16" copper windstay dropper
Category	Neutral Section
Priority	Yes
Types of OLE affected	Ex-DC
Original equipment dates	Before 1958



Ref:	NR/L2/ELP/27009/MOD C04
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

Blank Page