


Ref:	NR/L2/ELP/27009/MOD C15
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
15	REPLACEMENT OF ROLLER BEARINGS IN TERMINATION PULLEYS
COMPONENT	Seized termination pulley wheels with poor quality roller bearings. The roller bearings concerned are a Chinese produced type and are not Timken bearings.
PROBLEM	These termination pulley wheels are prone to seize. The resulting seized balance weights will lead to poor current collection and over stressing of hard drawn copper conductors and other components.
	
Reference Information	
Ellipse standard job number	13015
Ellipse standard job description	Replace termination and support pulley bearing
Category	Terminations
Priority	No
Types of OLE affected	Mk3b; Mk3c
Original equipment dates	1987 - 1992

Ref:	NR/L2/ELP/27009/MOD C15
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
15	REPLACEMENT OF ROLLER BEARINGS IN TERMINATION PULLEYS
ACTION REQUIRED	Replace any affected stiff or seized pulley wheels with a new wheel incorporating the correct Timken roller bearing.
	

Copyright Network Rail