

Ref:	NR/L2/ELP/27009/MOD C18
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
18	REPLACEMENT OF TAYLOR TUNNICLIFF GAS FILLED HOLLOW SUPPORT INSULATORS PRONE TO FAILURE
COMPONENT	Gas-filled uinsulators manufactured by Taylor Tunncliff, used in support and registration arrangements.
PROBLEM	<p>These insulators are prone to degradation of the porcelain over time. This leads to loss of gas and water ingress to the core, causing and 25kV flashover and catastrophic failure.</p> <p>The insulators can be identified by the manufacturers logo:</p> 
ACTION REQUIRED	Replace with polymeric equivalent insulator.

Reference Information	
Ellipse standard job number	13018
Ellipse standard job description	Replace TT gas filled hollow support INS
Category	Insulators
Priority	No
Types of OLE affected	Mk1
Original equipment dates	1965

Ref:	NR/L2/ELP/27009/MOD C18
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

Blank Page

Copyright Network Rail