

Ref:	NR/L2/ELP/27009/MOD C42
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
42	FAILURE OF IN-SPAN JUMPER SUPPORT STRAPS ' WHITE ARROW' TYPE
COMPONENT	White plastic jumper support straps.
PROBLEM	White plastic support straps crack due to UV radiation and detach from the catenary. This leads to a higher long term risk of jumper fatigue failure.
ACTION REQUIRED	Fit new type STRAP LOK black strapping design.
	

Reference Information	
Ellipse standard job number	13042
Ellipse standard job description	Replace white arrow jumper support straps
Category	Jumper
Priority	Yes
Types of OLE affected	Mk1; Mk2; Mk3 (all); Mk5
Original equipment dates	After 1977



Ref:	NR/L2/ELP/27009/MOD C42
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

Blank page