

Ref:	NR/L2/ELP/27009/MOD C56
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
56	MODIFICATION OF MORRIS LINE TYPE MOTORISED ISOLATORS PRONE TO BLADE MISALIGNMENT
COMPONENT	Morris line type motorised isolators with long operating tubes, where the isolator is prone to blade misalignment due to operating tube misalignment.
PROBLEM	<p>Installations with inclined or long operating tubes are prone to misalignment between blade and jaws, leading to severe arcing at the connection between the isolator blade and the jaw.</p> <p><i>Note: This campaign change was previously reported as completed.</i></p>
ACTION REQUIRED	Fit Morris Line Universal joint kit in operating tube to compensate for misalignment.

Reference Information	
Ellipse standard job number	13056
Ellipse standard job description	Modify Morris Line motorisd ISOL op. tube
Category	Isolators
Priority	No
Types of OLE affected	Ex-DC; Mk1; Mk2; Mk3; Mk3a; Mk3b
Original equipment dates	After 1980



Ref:	NR/L2/ELP/27009/MOD C56
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

[Blank page]