

Ref:	NR/L2/ELP/27009/MOD C68
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
68	RENEW HALF-FLYING-DUCK INSULATORS IN OVERLAP SPANS
COMPONENT	Half flying duck insulators in Mark 1 overlap spans.
PROBLEM	Water penetration at the end cap over time (>40 years) leads to increased risk of catastrophic insulator failure
ACTION REQUIRED	Replace insulator with polymeric equivalent insulator.

Reference Information	
Ellipse standard job number	13068
Ellipse standard job description	Renew 1/2 Flying Duck INS in Mk 1 O/L
Category	Insulators
Priority	No
Types of OLE affected	Mk1
Original equipment dates	After 2002



Ref:	NR/L2/ELP/27009/MOD C68
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

Blank Page
