

Issue:	I
Date:	December 2002

Railtrack Company Code of Practice

Signalling Equipment
Technical Advice
Notice (SIGTAN050)


Western Region Type
Barrier Machine
Hydraulic Ram - Ram Pin
Failure

This document is the property of Railtrack PLC. (Railtrack PLC is part of the Network Rail Group of Companies) It shall not be reproduced in whole or in part, nor disclosed to a third party, without the written permission of the Standard Owner.

© Copyright 2002 Railtrack PLC
(Railtrack PLC is part of the Network Rail Group of Companies)

ENDORSEMENT & AUTHORISATION

Endorsed by:


.....


A Simmons, Professional Head of Signalling

Accepted for issue by:


.....

P. McAleer, Acting Head of Business Standards

Authorised by:


.....

A McNaughton, Chief Engineer

RAILTRACK COMPANY STANDARD

ISSUE RECORD

ISSUE	DATE	COMMENTS
1	December 2002	This Code of Practice describes an in service problem which can occur with Western region hydraulic rams

IMPLEMENTATION

This Code of Practice highlights issues arising from operational experience, concerning the installation and maintenance of signalling equipment. Where appropriate, it gives current best practice for mitigating risk and is for implementation from Dec 2002. Alternative practices may be acceptable providing it can be demonstrated that the practices adopted are as good or better, than those defined in this Code of Practice.

DISCLAIMER

Railtrack PLC has used its best endeavours to ensure that the content, layout and text of this document are accurate, complete and suitable for its stated purpose. It makes no warranties, express or implied, that compliance with the contents of this document shall be sufficient to ensure safe systems of work or operation. Railtrack PLC will not be liable to pay compensation in respect of the content or subsequent use of this document for any purpose other than its stated purpose or for any purpose other than that for which it was prepared except where it can be shown to have acted in bad faith or there has been wilful default.

SUPPLY

Copies of documents are available electronically, within Railtrack's organisation. Hard copies of this document will be available to Railtrack staff on request to the Document Controller and to other organisations from Technical Indexes Ltd (01344 404409).

Published & Issued by

Railtrack plc
Railtrack House
Euston Square
LONDON
NW1 2EE