

IECC Briefing Note

IECC PC Logger

Issue 2

Date 15 March 2004

Installation Engineer Briefing Note

For approval and authorisation of this document, please refer to the IECC Applications Manual Contents, RT/E/S/10040.

This document is the property of Network Rail. It shall not be reproduced in whole or in part, nor disclosed to a third party, without the written permission of the document owner.

**Published and issued by
Network Rail
40 Melton Street
LONDON
NW1 2EE**

© 2004 Network Rail

This page is intentionally blank

Amendment Record

Issue	Date	Description
1	12 February 2004	Initial issue of document.
2	15 March 2004	Updated to include: • Details on actions to be taken with regard to redundant PSM cabling • A review of the hazards that were identified when the PSM was originally installed • Use of solvents when removing redundant PSM display and alarm units and associated safety precautions • Details of changes to spares holding • Details of hardware re-labelling when reverting from a PSM to an IPL

Author

Approved

Date

Authorised

Date

IECC PC LOGGER BRIEFING NOTE
INSTALLATION ENGINEER BRIEFING NOTE

SCS-IPL-UG-1 Issue 2

Copyright Network Rail
Provided by IHS under license with Network Rail
No reproduction or networking permitted without license from IHS

Contents

1	Introduction	1
2	System Overview	2
3	Hardware Installation	3
3.1	NEW INSTALLATIONS	3
3.2	EXISTING INSTALLATIONS	4
4	Software Installation	6
4.1	NEW INSTALLATIONS	6
4.2	EXISTING INSTALLATIONS	8