



American Welding Society

The Practical Reference Guide for

Welding Titanium



THE PRACTICAL REFERENCE GUIDE for WELDING TITANIUM

Compiled/Edited/Written by

Eugene G. Hornberger

Consultant
Hampton, Virginia

This publication is designed to provide information in regard to the subject matter covered. It is made available with the understanding that the publisher is not engaged in the rendering of professional advice. Reliance upon the information contained in this document should not be undertaken without an independent verification of its application for a particular use. The publisher is not responsible for loss or damage resulting from use of this publication. This document is not a consensus standard. Users should refer to the applicable standards for their particular application.



American Welding Society

550 N.W. LeJeune Road, Miami, Florida 33126



Documents

Document Sharing Hub

ACKNOWLEDGMENT

The American Welding Society extends appreciation to John Monsees, Consultant, International Titanium Association, Boulder, Colorado, for both his technical review of, and advice on, this document.

Photocopy Rights

Authorization to photocopy items for internal, personal, or educational classroom use only, or the internal, personal, or educational classroom use only of specific clients, is granted by the American Welding Society (AWS) provided that the appropriate fee is paid to the Copyright Clearance Center, 222 Rosewood Drive, Danvers, MA 01923, Tel: 978-750-8400; online: <http://www.copyright.com>

© 1999 by the American Welding Society. All rights reserved.
Printed in the United States of America.

TABLE OF CONTENTS

	Page No.
Basic Safety Precautions	iv
Introduction	1
Weld Cleaning	2
Gas Shielded Arc Welding Processes	2
Welding in the Open	3
Primary Gas Shielding	3
Secondary Gas Shielding	3
Backing Gas Shielding	4
Welding in a Chamber	4
Joint Design	5
Gas Tungsten Arc Welding	6
Gas Metal Arc Welding	7
Equipment	7
Welding Consumables	7
Filler Metal Transfer	7
Welding Conditions	7
Plasma Arc Welding	8
Other Welding Processes	9
Electron Beam Welding	9
Laser Beam Welding	9
Resistance Welding	9
References	10

BASIC SAFETY PRECAUTIONS

Burn Protection. Molten metal, sparks, slag, and hot work surfaces are produced by welding, cutting, and allied processes. These can cause burns if precautionary measures are not used. Workers should wear protective clothing made of fire-resistant material. Pant cuffs, open pockets, or other places on clothing that can catch and retain molten metal or sparks should not be worn. High-top shoes or leather leggings and fire-resistant gloves should be worn. Pant legs should be worn over the outside of high-top shoes. Helmets or hand shields that provide protection for the face, neck, and ears, and a head covering to protect the head should be used. In addition, appropriate eye protection should be used.

Electrical Hazards. Electric shock can kill. However, it can be avoided. Live electrical parts should not be touched. The manufacturer's instructions and recommended safe practices should be read and understood. Faulty installation, improper grounding, and incorrect operation and maintenance of electrical equipment are all sources of danger.

All electrical equipment and the workpiece should be grounded. The workpiece lead is not a ground lead. It is used only to complete the welding circuit. A separate connection is required to ground the workpiece. The workpiece should not be mistaken for a ground connection.

Fumes and Gases. Many welding, cutting, and allied processes produce fumes and gases which may be harmful to health. Avoid breathing the air in the fume plume directly above the arc. Do not weld in a confined area without a ventilation system. Use point-of-welding fume removal when welding galvanized steel, zinc, lead, cadmium, chromium, manganese, brass, or bronze. Do not weld on piping or containers that have held hazardous materials unless the containers have been inerted properly.

Compressed Gas Cylinders. Keep caps on cylinders when not in use. Make sure that gas cylinders are chained to a wall or other structural support. Do not weld on cylinders.

Radiation. Arc welding may produce ultraviolet, infrared, or light radiation. Always wear protective clothing and eye protection to protect the skin and eyes from radiation. Shield others from light radiation from your welding operation.

AWS also recommends a personal copy of "Arc Welding Safely," "Fire Safety in Welding and Cutting," "Safety in Welding, Cutting, and Allied Processes," and "Standard for the Production, Processing, Handling, and Storage of Titanium."