

Subject 555C

February 03, 2017

SUMMARY OF TOPICS

The following topic for the Standard for Ceiling Dampers, UL 555C, is being recirculated:

1. Alignment of UL 555, UL 555C and UL 555S

COMMENTS DUE: March 6, 2017

For your convenience in review, proposed additions to the previously proposed requirements dated (2016-08-19) are shown underlined and proposed deletions are shown ~~lined-out~~.

1. Alignment of UL 555, UL 555C and UL 555S

RATIONALE

Responses to comments have been posted within the UL 555C Proposal Review Work Area dated (2016-08-19).

PROPOSAL

(REVISED)

9A.10 Upon removing power from the actuators, observe and record the time required for each actuator to return to within ± 12 0.12 inch (3 mm) of its resting position for linear actuator and within ± 3 degrees of its resting position for rotary actuators. All actuators must return to the resting position within their rated time.

Copyright © 2017 Underwriters Laboratories Inc.



No Text on This Page

**UL COPYRIGHTED MATERIAL –
NOT AUTHORIZED FOR FURTHER REPRODUCTION OR
DISTRIBUTION WITHOUT PERMISSION FROM UL**



Documents

Document Sharing Hub