

ERRATA for AASHTO LRFD Bridge Design Guide Specifications for GFRP-Reinforced Concrete, Second Edition

Dear Customer,

Due to errors found after publication had been completed, AASHTO has made the following errata changes to the *AASHTO LRFD Bridge Design Guide Specifications for GFRP-Reinforced Concrete*, Second Edition (GFRP-2B):

<u>Date</u>	<u>Page Number</u>	<u>Affected Article</u>	<u>Errata Change To</u>
July 2019	2-12	Figure C2.5.5.2-1	One value of ϕ was incorrectly given as 0.70 and has been replaced with the correct value, 0.75.
February 2020	6-4	Table 6.6.4-1	“Minimum Inside Bend Diameter” should read “Minimum Inside Bend Radius”

Please substitute the original pages of text with the enclosed pages, which will remain clearly distinguishable as errata pages once they have been inserted due to the large errata page header. Text in ***bold italics*** indicate revisions made since the previous errata was released in July 2019. The previous errata changes are included

We apologize for any inconvenience this may have caused.

AASHTO Publications Staff
February 2020

This page intentionally left blank.