

Field Inspection of New Casing, Tubing, and Plain-end Drill Pipe

ANSI/API RECOMMENDED PRACTICE 5A5
SEVENTH EDITION, JUNE 2005

ERRATA, DECEMBER 2009

REAFFIRMED, JANUARY 2021

**ISO 15463:2003 (Identical), Petroleum and natural
gas industries—Field inspection of new casing,
tubing, and plain-end pipe**



American
Petroleum
Institute



Documents
Document Sharing Hub

Special Notes

API publications necessarily address problems of a general nature. With respect to particular circumstances, local, state, and federal laws and regulations should be reviewed.

API is not undertaking to meet the duties of employers, manufacturers, or suppliers to warn and properly train and equip their employees, and others exposed, concerning health and safety risks and precautions, nor undertaking their obligations under local, state, or federal laws.

Information concerning safety and health risks and proper precautions with respect to particular materials and conditions should be obtained from the employer, the manufacturer or supplier of that material, or the material safety data sheet.

Nothing contained in any API publication is to be construed as granting any right, by implication or otherwise, for the manufacture, sale, or use of any method, apparatus, or product covered by letters patent. Neither should anything contained in the publication be construed as insuring anyone against liability for infringement of letters patent.

Generally, API standards are reviewed and revised, reaffirmed, or withdrawn at least every five years. Sometimes a one-time extension of up to two years will be added to this review cycle. This publication will no longer be in effect five years after its publication date as an operative API standard or, where an extension has been granted, upon republication. Status of the publication can be ascertained from the API Standards department telephone (202) 682-8000.

This document was produced under API standardization procedures that ensure appropriate notification and participation in the developmental process and is designated as an API standard. Questions concerning the interpretation of the content of this standard or comments and questions concerning the procedures under which this standard was developed should be directed in writing to the Director of the Standards department, American Petroleum Institute, 200 Massachusetts Avenue, NW, Suite 1100, Washington, DC 20001. Requests for permission to reproduce or translate all or any part of the material published herein should be addressed to the Director, Business Services.

API standards are published to facilitate the broad availability of proven, sound engineering and operating practices. These standards are not intended to obviate the need for applying sound engineering judgment regarding when and where these standards should be utilized. The formulation and publication of API standards is not intended in any way to inhibit anyone from using any other practices.

Any manufacturer marking equipment or materials in conformance with the marking requirements of an API standard is solely responsible for complying with all the applicable requirements of that standard. API does not represent, warrant, or guarantee that such products do in fact conform to the applicable API standard.

All rights reserved. No part of this work may be reproduced, stored in a retrieval system, or transmitted by any means, electronic, mechanical, photocopying, recording, or otherwise, without prior written permission from the publisher. Contact the Publisher, API Publishing Services, 200 Massachusetts Avenue, NW, Suite 1100, Washington, DC 20001.

Copyright © 2005 American Petroleum Institute

API Foreword

Standards referenced herein may be replaced by other international or national standards that can be shown to meet or exceed the requirements of the referenced standard

This American National Standard is under the jurisdiction of the API Subcommittee on Tubular Goods. This standard is a modified adoption of the English version of ISO 15463. ISO 15463 was prepared by Technical Committee ISO/TC 67, SC5.

In this American National Standard certain technical modifications have been made. These technical modification from the ISO Standard have not been incorporated directly into this API adopt-back version.

These modification have been noted with an arrow (➔) adjacent to the clause, table, figure, etc. that has been modified.

A complete list of modifications can be found in Annex D.

API publications may be used by anyone desiring to do so. Every effort has been made by the Institute to assure the accuracy and reliability of the data contained in them; however, the Institute makes no representation, warranty, or guarantee in connection with this publication and hereby expressly disclaims any liability or responsibility for loss or damage resulting from its use or for the violation of any federal, state, or municipal regulation with which this publication may conflict.

Suggested revisions are invited and should be submitted to API, Standards department, 200 Massachusetts Avenue, NW, Suite 1100, Washington, DC 20001, standards@api.org.

Contents

	Page
API Foreword	ii
Foreword	vi
Introduction	vii
1 Scope	1
2 Conformance	1
2.1 Normative references	1
2.2 Units of measurement	1
2.3 Tables and figures	2
3 Normative references	2
4 Terms, definitions, symbols and abbreviated terms	2
4.1 Terms and definitions	2
4.2 Symbols and abbreviated terms	13
5 Application	15
5.1 Basis for inspection	15
5.2 Applicability of inspections	15
5.3 Repeatability of results	15
5.4 Consequences of variability	15
6 Ordering information	16
7 Quality assurance	16
8 Qualification of inspection personnel	17
8.1 General	17
8.2 Written procedure	17
8.3 Qualification of inspection personnel	17
8.4 Training programs	18
8.5 Examinations	18
8.6 Experience	18
8.7 Requalification	18
8.8 Documentation	18
8.9 NDT personnel certification	19
9 General inspection procedures	19
9.1 General	19
9.2 Documents at job site	19
9.3 Pre-inspection procedures	19
9.4 Records and notification	19
9.5 Post-inspection procedures	20
9.6 Job site checklist	21
9.7 Documentation	21
10 Acceptance criteria, disposition and responsibility	21
10.1 General	21
10.2 Basis for acceptance	21
10.3 Responsibility for Rejections	21
11 Visual and dimensional inspection	22
11.1 General	22
11.2 Application	22
11.3 Drift mandrels	22
11.4 Precision callipers (micrometer, vernier calliper or dial calliper)	22
11.5 Length and diameter-measuring devices (steel rules, steel length or diameter-measuring tapes, and other non-adjustable measuring devices)	22



Documents

Document Sharing Hub

11.6	Depth gauges	22
11.7	External surface illumination	23
11.8	Internal surface illumination	23
11.9	Full-length visual inspection (FLVI) of new OCTG	24
11.10	Outside diameter verification	24
11.11	Straightness	24
11.12	Drift testing	25
11.13	Visual thread inspection (VTI)	26
12	Hardness testing	29
12.1	General	29
12.2	Application	29
12.3	Equipment	30
12.4	Calibration	30
12.5	Standardization	30
12.6	Procedures	31
13	Magnetic particle inspection (MPI)	31
13.1	General	31
13.2	Application	32
13.3	Equipment and materials	32
13.3.1	Internal conductors	32
13.4	Magnetic particles	33
13.5	Illumination equipment and optical aids	33
13.6	General procedures	34
13.7	Calibration	34
13.8	Standardization	35
13.9	Periodic checks	35
13.10	End area inspection (SEA)	36
13.11	Inspection of unattached couplings (UCMPI)	37
13.12	Full-length magnetic particle inspection (FLMPI)	38
14	Electromagnetic inspection (EMI)	38
14.1	General	38
14.2	Equipment	39
14.3	Application	39
14.4	Calibration	39
14.5	Standardization	40
14.6	Equipment requirements and periodic checks	42
14.7	Inspection procedure	42
15	Residual magnetism and demagnetization	42
15.1	General	42
15.2	Application	43
15.3	Services	43
16	Gamma-ray wall thickness inspection	44
16.1	General	44
16.2	Application	44
16.3	Equipment	44
16.4	Calibration and standardization	44
16.5	Inspection procedure	45
17	Electromagnetic grade comparison	45
17.1	General	45
17.2	Application	45
17.3	Equipment	45
17.4	Calibration and Standardization	45
17.5	Inspection procedure	46
18	Ultrasonic inspection	46
18.1	General	46
18.2	Application	47

18.3	General procedures for calibration, standardization, and inspection	47
18.4	Inspection for longitudinal, transverse, and oblique imperfections	48
18.5	Standardization	49
18.6	Procedure for the detection of longitudinal, transverse, and oblique imperfections	49
18.7	Inspection of the body wall for wall thinning	49
18.8	Ultrasonic inspection of longitudinal welds	50
18.9	Manual ultrasonic thickness gauging	52
18.10	Manual ultrasonic shear-wave inspection	54
19	Evaluation of imperfections and deviations	55
19.1	General	55
19.2	Application	55
19.3	Equipment	55
19.4	Calibration and standardization procedures	56
19.5	Procedure for evaluating outside-surface-breaking pipe body imperfections	56
19.6	Procedure for evaluating inside-surface-breaking pipe body imperfections	58
19.7	Procedure for evaluating welds	58
19.8	Procedure for evaluating grinds	59
19.9	Procedure for evaluating large-area wall reduction	59
19.10	Procedure for evaluating imperfections in upsets	60
19.11	Procedure for evaluation of outside surface imperfections on couplings	61
19.12	Procedure for evaluation of visually-located thread imperfections	61
19.13	Procedure for triangle location and coupling makeup position	64
19.14	Procedure for evaluating straightness	64
19.15	Procedure for evaluating pipe diameter	65
20	Hydrostatic pressure testing	65
20.1	General	65
20.2	Application	66
20.3	Equipment, safety, and general procedures	66
20.4	Equipment calibration	67
20.5	Operating procedure	67
21	Marking	68
21.1	General	68
21.2	Authority	69
21.3	Guidelines	69
21.4	Marking of prime OCTG	70
21.5	Marking of no-drift OCTG	70
21.6	Marking of conditioned OCTG	70
21.7	Marking of conditionable OCTG (still to be conditioned)	71
21.8	Marking of non-conditionable OCTG (rejects)	71
21.9	Marking of OCTG not meeting ISO/API standards for hardness	71
21.10	Marking of prime couplings and connectors	72
21.11	Marking of conditioned couplings and connectors	72
21.12	Marking of conditionable couplings and connectors (still to be conditioned)	72
21.13	Marking of non-conditionable couplings and connectors (rejects)	72
Annex A	(normative) Tables in SI units	74
Annex B	(normative) Figures	91
Annex C	(normative) Tables in USC units	96
Annex D	(normative) Identification/explanation of changes	112
Annex E	(informative) Glossary of terms	116
Bibliography		119

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

International Standards are drafted in accordance with the rules given in the ISO/IEC Directives, Part 2.

The main task of technical committees is to prepare International Standards. Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights.

ISO 15463 was prepared by Technical Committee ISO/TC 67, *Materials, equipment and offshore structures for petroleum, petrochemical and natural gas industries*, Subcommittee SC 5, *Casing, tubing and drill pipe*.

Introduction

This International Standard is provided for field inspection and testing of OCTG; it is not intended to restrict the agency or owner from using personal judgement and supplementing the specified inspections with other techniques, extending existing techniques, or re-inspecting certain lengths of OCTG.

Users of this International Standard should be aware that further or differing requirements might be needed for individual applications. This International Standard is not intended to inhibit a vendor from offering, or the purchaser from accepting, alternative equipment or engineering solutions for the individual application. This may be particularly applicable where there is innovative or developing technology. Where an alternative is offered, the vendor should identify any variations from this International Standard and provide details.

Petroleum and natural gas industries — Field inspection of new casing, tubing and plain-end drill pipe

1 Scope

This International Standard specifies requirements and gives recommendations for field inspection and testing of oil country tubular goods (OCTG). This International Standard covers the practices and technology commonly used in field inspection; however, certain practices may also be suitable for mill inspections.

This International Standard covers the qualification of inspection personnel, a description of inspection methods and apparatus calibration and standardization procedures for various inspection methods. The evaluation of imperfections and marking of inspected OCTG are included.

This International Standard is applicable to field inspection of OCTG and is not applicable for use as a basis for acceptance or rejection (for which the relevant purchasing specification is applicable, see 5.4.2).

2 Conformance

2.1 Normative references

In the interests of worldwide application of this International Standard, ISO/TC 67 has decided, after detailed technical analysis, that certain of the normative documents listed in Clause 3 and prepared by ISO/TC 67 or other ISO Technical Committee are interchangeable in the context of the relevant requirement with the relevant document prepared by the American Petroleum Institute (API), the American Society for Testing and Materials (ASTM) or the American National Standards Institute (ANSI). These latter documents are cited in the running text following the ISO reference and preceded by “or”, for example “ISO XXXX or API YYYY”. Application of an alternative normative document cited in this manner may lead to technical results different from the use of the preceding ISO reference. However, both results are acceptable and these documents are thus considered interchangeable in practice.

NOTE ISO 11960 has been back-adopted by API as API Spec 5CT. Therefore, for the purposes of the provisions in this International Standard which cite ISO 11960, API Spec 5CT is equivalent to ISO 11960.

2.2 Units of measurement

In this International Standard, data are expressed in both the International system (SI) of units and the United States Customary (USC) system of units. For specific field inspection and testing, it is intended that only one unit system be used, without combining data expressed in the other system.

Inspection and testing performed using either of these unit systems shall be considered equivalent and totally interchangeable. Consequently, compliance with the requirements of the relevant Product Standard expressed in one of the unit systems provides compliance with the requirements expressed in the other system.

For data expressed in the SI, a comma is used as the decimal separator and a space as the thousands separator. For data expressed in the USC system, a dot (on the line) is used as the decimal separator and a space as the thousands separator.

In the text, data in SI units are followed by data in USC units in brackets.

2.3 Tables and figures

Separate tables for data expressed in SI units and USC units are given in Annex A and Annex C, respectively. For a specific order item, only one unit system shall be used.

In this International Standard, cross-references are made only to the tables in Annex A; if the USC units apply on an order, then any cross-references to tables in Annex A shall be taken to mean the equivalent table in Annex C.

Figures (data expressed in both SI and USC units) are contained in Annex B.

3 Normative references

The following referenced documents are indispensable for the application of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 10405:2000, *Petroleum and natural gas industries — Care and use of casing and tubing*

ISO 11960:2001 (including Technical Corrigendum 1:2002), *Petroleum and natural gas industries — Steel pipes for use as casing or tubing for wells*

ISO 11961:1996, *Petroleum and natural gas industries — Steel pipes for use as drill pipe — Specification*

ISO 13678, *Petroleum and natural gas industries — Evaluation and testing of thread compounds for use with casing, tubing and line pipe*

API RP 5A3¹⁾, *Thread compounds for casing, tubing and line pipe*

API Spec 5B, *Threading, gauging and thread inspection of casing, tubing and line pipe threads*

API RP 5B1, *Threading, gauging and inspection of casing, tubing, and line pipe threads*

API RP 5C1:1999, *Care and use of casing and tubing*

API Spec 5D:2001, *Specification for drill pipe*

API Std 5T1, *Imperfection terminology*

4 Terms, definitions, symbols and abbreviated terms

4.1 Terms and definitions

For the purposes of this document, the following terms and definitions apply.

4.1.1

A-scan

data presentation utilizing a horizontal base line that indicates distance, or time, and a vertical deflection from the base line that indicates amplitude

4.1.2

AC-field

magnetic field induced by alternating current

1) American Petroleum Institute; 1220 L Street NW, Washington DC, 20005, USA

4.1.3**agency**

entity contracted to inspect new OCTG using the methods and criteria specified

4.1.4**ampere-turn**

unit of magnetomotive force which is the product of the number of turns in a coil and the quantity of amperes of current flowing through it, representing the magnetizing strength of the coil

EXAMPLE 800 A in a 6-turn coil gives 4 800 ampere-turns.

4.1.5**arc, verb**

create intense heat and light by passing an electric current across a gap

4.1.6**back-wall reflection**

ultrasonic signal received from the back surface of the pipe wall

4.1.7**black-crested thread**

non-full-crested thread whose original (black) mill surface has not been completely removed

4.1.8**black light**

long-wave ultraviolet light (UV-A) with a wavelength between 320 nm and 400 nm

4.1.9**borescope**

optical instrument with an illuminating lamp, used for inspecting the inside surface of OCTG

4.1.10**box**

internally-threaded end of integral-joint OCTG, or the coupling end of threaded-and-coupled OCTG

4.1.11**calibration**

comparison of an instrument with, or the adjustment of an instrument to, a known reference(s) standard that is often traceable to a national institute such as the National Institute of Standards and Technology

4.1.12**casing**

steel pipe used in oil wells to seal off fluids from the bore hole and to prevent the walls of the hole from sloughing off or caving in

4.1.13**central conductor**

conductor that is passed through the bore of OCTG in order to create a circular or circumferential magnetic field in the OCTG

NOTE This does not imply that the current rod is necessarily centred in the bore of the OCTG.

4.1.14**chamfer**

conical surface at the end of pipe having round or buttress threads

4.1.15**chatter**

wavy surface of the thread flank, root, crest, or chamfer, caused by a vibrating cutter insert

4.1.16

chock

block or wedge used beneath a length of pipe so that it cannot roll

4.1.17

circular magnetic field

circumferential magnetic field

magnetic field in or surrounding a current-carrying conductor, or OCTG, such that the magnetic field is oriented circumferentially within the wall of the OCTG

4.1.18

circular magnetization

circumferential magnetization

production of a magnetic field in a pipe wall or coupling such that the magnetic field is oriented circumferentially

4.1.19

classification

action taken to categorize a length of new OCTG based on conformance with the contracted inspection requirements

4.1.20

contour, verb

taper gradually by filing or grinding to remove abrupt changes in the wall thickness

4.1.21

contour-grind, verb

radius-grind

grind to remove sharp edges and/or abrupt changes in the wall thickness around imperfections or areas of exploratory grinding

4.1.22

couplant

material (usually a liquid) used between an ultrasonic transducer and the test specimen to assist transmission of ultrasonic sound waves between them

4.1.23

crest

top of a thread

4.1.24

cut, noun

gouge or distortion in two or more thread crests in a line, either parallel to the pipe axis or at an angle across the threads

4.1.25

DC-field

residual or active magnetic field induced by direct current

4.1.26

defect

imperfection of sufficient magnitude or properties to warrant rejection of OCTG based on the specified acceptance criteria

4.1.27

demagnetization

process of removing part or all of the residual magnetism from OCTG

4.1.28

detector

detector shoe

scanning shoe carrying one or more transducers, used to protect transducers from mechanical damage

4.1.29

discontinuity

flaw

imperfection

irregularity in the product, such as a lap, seam, pit and lamination

4.1.30

disposition

action taken in accordance with the applicable specification with regard to a defect in a length of OCTG

4.1.31

drift mandrel

cylinder, machined to specified dimensions, that is passed through a pipe to locate obstructions and/or to assess compliance with the appropriate specifications

4.1.32

dual-element transducer

ultrasonic transducer containing two piezoelectric elements, one for transmitting and one for receiving

4.1.33

eddy current

circulating current caused to flow in the OCTG by varying magnetic fields

4.1.34

electromagnetic inspection

EMI

primarily the eddy-current and flux-leakage methods used to detect imperfections

NOTE Field electromagnetic "Inspection Systems" sometimes include equipment for performing additional inspections or services.

4.1.35

evaluation

process of determining the severity of an imperfection which leads to determining whether the OCTG is acceptable or rejectable against the appropriate specification

4.1.36

exploratory grind, noun

probe grind

grind performed to explore or determine the depth of an imperfection

4.1.37

external thread

thread on the outside surface of OCTG

4.1.38

false indication

NDT indication that is interpreted to be caused by a condition other than a discontinuity or imperfection

NOTE False indications are considered non-relevant.

4.1.39

false starting thread

circumferential tool mark on a round-thread chamfer that precedes the actual starting thread

4.1.40**ferromagnetic**

term applied to materials that can be magnetized or strongly attracted by a magnetic field

4.1.41**field end**

pipe end opposite the internally-threaded end

NOTE

Mill identification is at the internally-threaded end.

4.1.42**flank**

side

surface of a thread that connects the crest with the root

4.1.43**fluorescent magnetic particle inspection**

magnetic particle inspection process employing a finely-divided, fluorescent, ferromagnetic inspection medium that fluoresces when exposed to black light

4.1.44**flux density**

strength of a magnetic field

NOTE

In the Gaussian system, flux density is expressed in gauss.

4.1.45**flux leakage**

magnetic field forced out into the air by a distortion of the field within the OCTG, caused by the presence of a discontinuity

4.1.46**full-body inspection**

inspection coverage of the entire surface area of the OCTG within the limitations of the inspection equipment used

4.1.47**furring**

build-up or bristling of dry magnetic particles at the ends of a longitudinally-magnetized length of OCTG, i.e. at its poles

4.1.48**gain**

sensitivity adjustment produced by an amplifier or circuit

4.1.49**gamma-ray**

high-energy, short wavelength, electromagnetic radiation emitted by a nucleus, which is penetrating and is best attenuated by dense material like lead or tungsten

NOTE

The energy of gamma-rays is usually between 0,010 MeV and 10 MeV.

4.1.50**gauss meter**

electronic magnetometer used to measure flux density

4.1.51**grind, verb**

remove material from a surface by abrading, e.g. with a grinding wheel or file

4.1.52

handling damage

damage to the OCTG body, coupling or threads that occurred during loading, unloading, movements in transit, etc.

EXAMPLES cuts, gouges, dents, flattened (mashed) thread crests or similar.

4.1.53

hardness

resistance of a material to indentation, measured by pressing a hardmetal ball or diamond indenter into a smooth surface under standard conditions

4.1.54

hardness value

average of the valid readings taken in the test area for hardness

4.1.55

hydrostatic test

test performed by filling a length of OCTG with water and pressurizing it in order to verify its ability to withstand a specified pressure without leaking or rupturing

NOTE A hydrostatic test is generally considered a method to verify the structural integrity of the pipe but not the threaded connection.

4.1.56

imperfection

flaw

discontinuity or irregularity in the product

NOTE For more detailed definitions and illustrations of specific imperfections, see API Std 5T1.

4.1.57

indication

response or evidence from NDT

4.1.58

indicator

readout

device for displaying a condition, a current or a potential

EXAMPLES Analog and digital galvanometers, A-scan displays, warning lights, alarms.

4.1.59

induction

act of inducing a magnetic field in a ferromagnetic body

4.1.60

inspection

process of examining OCTG for possible defects or for deviation from established standards

4.1.61

inspection job

inspection of one or more lots of OCTG by an agency subject to a single contract or subcontract

4.1.62

inspection system

combination of equipment, procedures and personnel required for the detection of reference indicators

4.1.63

inspector

employee of an agency qualified and responsible for one or more of the inspections or tests specified in the contract

4.1.64**integral joint OCTG**

OCTG with one end threaded externally and the other end threaded internally

4.1.65**internal thread**

thread on the inside surface of OCTG

4.1.66**interpretation**

process of determining the nature or forming an opinion of an indication based on objective data

4.1.67**label 1**

dimensionless designation for the size or specified outside diameter, used when ordering OCTG

4.1.68**label 2**

dimensionless designation for the mass per unit length or wall thickness, used when ordering OCTG

4.1.69**leakage field**

magnetic field forced out of the material into the air by distortion of the field within the material, caused by the presence of a discontinuity

4.1.70**length**

joint

complete section of pipe

4.1.71**longitudinal magnetic field**

magnetic field which runs substantially parallel to the axis of the OCTG

4.1.72**longitudinal imperfection**

imperfection oriented in the longitudinal or approximately longitudinal direction

4.1.73**magnetic particle field indicator**

device containing artificial flaws which is used to verify the adequacy or direction, or both, of a magnetic field

4.1.74**magnetic particle**

finely-divided ferromagnetic material capable of being individually magnetized and attracted to distortions in a magnetic field

4.1.75**magnetizing force**

magnetic field strength

NOTE In the Gaussian system, the symbol is H_s and quantities are expressed in oersteds.

4.1.76**magnetometer**

mechanical or electronic instrument used to measure magnetic field strength

4.1.77**manufacturer**

entity last responsible for manufacturing compliance with the applicable product specification(s)

4.1.78**marking**

assorted marks on tubular products including marks made for inspection with paint sticks and stencils, and ball-point paint tubes

4.1.79**mill end**

pipe end having the coupling, box and/or mill identification

4.1.80**mill scale**

iron oxide that forms on the surface of hot steel

4.1.81**no-drift**

length of pipe through which a drift mandrel of specified diameter will not pass without undue force

4.1.82**non-destructive test****NDT**

test used to detect internal, surface and concealed defects or imperfections in materials, using techniques that do not damage or destroy the items being tested

4.1.83**non-full-crested thread**

thread that does not have a complete thread crest

EXAMPLE Black-crested thread.

4.1.84**notch**

reference indicator with specified geometry

4.1.85**oil country tubular goods****OCTG**

casing, tubing, plain-end casing liners, pup joints, couplings, accessories and plain-end drill pipe

4.1.86**operator**

person present throughout the inspection or testing process who is responsible for the unit, operates the controls and observes the readout to detect imperfections

4.1.87**owner**

entity having ownership of the new OCTG at the time inspection is contracted, specifying the type of inspection or testing to be conducted and authorizing its performance

NOTE The owner might be the purchaser.

4.1.88**perfect thread length**

design length from the end of pipe or coupling to a specified location

4.1.89**permeability**

measure of the ease with which material can become magnetized

NOTE Permeability is the ratio of flux density and magnetizing force, i.e. B/H .

4.1.90**pin end**

externally-threaded end of a pipe without a coupling applied

4.1.91**pipe**

oil field casing, tubing, plain-end casing liners, pup joints and plain-end drill pipe

4.1.92**pit**

depression or cavity that can be caused by corrosion or removal of rolled-in or extraneous material

4.1.93**plain-end pipe**

pipe without threads or tool-joint

4.1.94**planar imperfection**

imperfection lying in one geometric plane that is normally parallel to, and within, the outer and inner surfaces

4.1.95**powder-dry**

sufficiently dry to allow any type of powder, when applied to the surface, to be blown from the surface without residue remaining

4.1.96**power-tight**

threaded connection that has been fully made up by mechanical means, using power tongs or a screw-on machine

4.1.97**prime pipe**

pipe meeting all of the specified inspection and testing requirements

4.1.98**pulse**

wave of short duration

4.1.99**pulser**

electronic device and probe for generating a controlled-magnitude magnetic pulse, used for standardizing transducers

4.1.100**purchaser**

entity that has purchased directly from the manufacturer the new OCTG being inspected

NOTE The purchaser might be the owner.

4.1.101**reference indicator**

real or artificial discontinuity in a reference standard, which provides reproducible sensitivity levels for inspection equipment

EXAMPLES Artificial reference indicators can be holes, notches, grooves or slots.

4.1.102**reference standard**

pipe, or pipe section, containing one or more reference indicators, used as a basis for comparison or for inspection equipment standardization

4.1.103**relevant indication**

NDT indication that is caused by a condition or type of discontinuity that requires evaluation

4.1.104**root**

bottom of a thread

4.1.105**scanner**

detector assembly carrying one or more transducers, used for detecting imperfections and defects in OCTG

NOTE The scanner is often equipped with a magnetizer and is a part of it.

4.1.106**seamless pipe**

wrought steel tubular product made without a welded seam

NOTE Seamless pipe is manufactured by hot-working steel and, if necessary, by subsequently cold finishing the hot-worked tubular product to produce the desired shape, dimensions and properties.

4.1.107**sensitivity**

size of the smallest discontinuity detectable by an NDT method with a reasonable signal-to-noise ratio

4.1.108**signal**

response of electronic NDT equipment to an imperfection or defect

4.1.109**signal-to-noise ratio**

ratio of the signal from a significant imperfection or defect to signals generated from surface noise

4.1.110**source**

origin of radiation, which is an x-ray tube or radioisotope

4.1.111**standardization**

the adjustment of an NDT instrument using an appropriate reference standard, to obtain or establish a known and reproducible response

4.1.112**standardization check**

check of the standardization adjustments to ensure that they remain correct

4.1.113**straightness**

degree to which the longitudinal axis of a length of OCTG is parallel to a straight line

4.1.114**tally, verb**

add up lengths of OCTG to arrive at an aggregate

4.1.15**test**

two or more valid hardness test readings that have been made in the same test area

4.1.116**test area**

area on OCTG that has been ground or filed smooth and flat to remove the decarburized surface material, on which a hardness test is performed

4.1.117**test block**

special precision blocks, used as standards to verify calibration of an inspection instrument

4.1.118**thread form**

profile of a thread in an axial (longitudinal) plane for a length of one pitch

4.1.119**thread protector**

protection device placed on the end of OCTG to protect threads and seals from damage

4.1.120**threshold**

investigation level established during EMI or UT inspection, above which indications are further investigated

4.1.121**tolerance**

permissible deviation from the specified value

4.1.122**transducer**

device which converts one form of energy to another

EXAMPLES Ultrasonic probes, search coils, eddy-current probes and most other detectors.

4.1.123**transverse**

across, usually circumferential or substantially circumferential in direction

4.1.124**tubing**

pipe placed within a well and serving as a conduit for produced well fluids or to inject fluids

4.1.125**ultrasonic test**

NDT method using high-frequency sound waves

4.1.126**ultrasonic**

having a frequency above the audible range, i.e. above 20 kHz

4.1.127**ultrasonic velocity**

speed at which ultrasonic sound waves travel through a medium

4.1.128**upset, noun**

forged metal end of OCTG with increased wall thickness and diameter, later to be threaded or welded

4.1.129**vanish point**

location where the external thread runs out or terminates on the OCTG outside surface

NOTE The vanish point is the point where the lead of the chaser tool makes its final cut.

4.1.130**vernier calliper**

dial calliper

measuring device, usually with two legs or jaws, that can be adjusted to measure the thickness, diameter, and distance between surfaces

NOTE Vernier callipers have a vernier scale readout whereas dial callipers have a dial readout.

4.1.131**wetting agent**

substance which lowers the surface tension of a liquid

4.1.132**yoke**

U-shaped piece of soft magnetic material, either solid or laminated, around which a coil is wound to carry a magnetizing current

4.2 Symbols and abbreviated terms

A_1	length of pin face to base of triangle
D	specified outside diameter for pipe
d	calculated inside diameter
D_{ou}	outside diameter of upset
d_{ou}	inside diameter of upset
I	electric current, expressed in amperes
J	distance from end of pipe to centre of coupling, power-tight make-up
L_c	minimum length full crest threads
L_{eu}	upset external length
L_{iu}	upset internal length
L_1	length from end of pipe to hand-tight plane
L_4	total length of threads: end of pipe to vanish point
N	coupling length
t	specified wall thickness
W	specified outside diameter for ISO/API threaded couplings other than special-clearance couplings
W_c	specified outside diameter of special-clearance couplings

ALTFLD	full-length alternate drifted
BC	buttress thread casing
CPLG	unattached couplings
DC-block	distance calibration block
DSC block	distance sensitivity calibration block
DP	plain end drill pipe
EBW	effective beam width
EMI	electromagnetic inspection
EU	external upset tubing connection
EW	electric-welded casing or tubing (including attached couplings)
FLD	full-length drifted
FLEMI	full-length electromagnetic inspection
FLMPI	full length magnetic particle inspection (wet or dry MPI)
FLVI	full-length visual inspection
IJ	integral joint tubing connection
LC	long round thread casing connection
NDT	non-destructive testing
NU	non-upset tubing connection
OCTG	oil country tubular goods
OD	outside diameter
PD	pulse density
PTL	perfect thread length
SEA	end area inspection (formerly called special end area inspection)
SMLS	seamless casing or tubing (including attached couplings)
STC	short round thread casing connection
T&C	threaded and coupled
TESTED	hydrostatically pressure-tested
UCMPI	unattached coupling magnetic particle inspection
UT	ultrasonic testing
UTFL	full-length ultrasonic inspection

UTW ultrasonic inspection, weld line

VTI Visual thread inspection

5 Application

5.1 Basis for inspection

This International Standard contains practices recommended for use in the inspection of new OCTG subsequent to production by the manufacturer. The basis for performing an inspection has its origin in either ISO 11960, ISO 11961 or API Spec 5D, API Spec 5B, or in a supplemental specification or contract prepared by the owner. The inspections represented by the practices are placed in one of three categories as follows:

- a) inspections specified in ISO 11960, ISO 11961 or API Spec 5D, or API Spec 5B;
- b) inspections specified as one of several options in ISO 11960, ISO 11961 or API Spec 5D, or API Spec 5B;
- c) inspections not specified in ISO 11960, ISO 11961 or API Spec 5D, or API Spec 5B.

5.2 Applicability of inspections

Some of the practices contained in this International Standard are applicable to OCTG regardless of size and type. Other practices typically might have limited applicability. Table A.1 indicates those inspections that are available in the field and covered by this International Standard, in relation to OCTG type. It is the owner's responsibility to specify which inspections shall be used when completing the ordering information (see Clause 6) to accompany an inspection contract.

5.3 Repeatability of results

Every inspection and measurement process is characterized by an inherent variability of results. The NDT methods and measurements included in this International Standard are characterized by additional inherent variability attributable to the following factors.

- a) ISO 11960, ISO 11961 or API Spec 5D, or API Spec 5B permits options in the selection of practices to be used in the inspection for specific attributes.
- b) Within a single practice, ISO 11960 or ISO 11961 or API Spec 5D, or API Spec 5B permits options in the selection of calibration standards.
- c) Each manufacturer of NDT systems uses different mechanical and electronic designs.
- d) Certain practices contained in this International Standard are based on operation of the system at high, and even maximum, sensitivity without the use of the reference standards specified in ISO 11960 or ISO 11961 or API Spec 5D.
- e) Within the performance capability of a single NDT system installation, there will not be perfect repeatability of results.

5.4 Consequences of variability

5.4.1 Disposition

For any of the reasons given in 5.3, the results of field inspection may not replicate corresponding inspections performed during manufacture. Variability within and among the results of practices contained in this International Standard is to be expected. When field inspection results in the classification of OCTG as other than prime, it shall not be presumed that the material is defective until an evaluation has been performed in accordance with Clause 19 to establish final disposition.

5.4.2 Responsibility for rejections

In some cases, an OCTG inspected using practices described in this International Standard may be classified as a reject even though it was inspected in conformance with ISO 11960, ISO 11961 or API Spec 5D, or API Spec 5B and classified by the manufacturer as an acceptable product in conformance with ISO 11960, ISO 11961 or API Spec 5D, or API Spec 5B. Responsibility for a rejection shall be based on the acceptance criteria contained in ISO 11960, ISO 11961 or API Spec 5D, or API Spec 5B, or an additional or more restrictive criteria previously negotiated with the manufacturer. The results of field NDT shall under no circumstances stand alone as a basis for rejection without corroborating evidence that the material is properly classified as defective based on the evaluation(s) performed in accordance with Clause 19 of this International Standard. If disposition is disputed between the purchaser and the manufacturer, the provisions of ISO 11960:2001, Clause 10, or ISO 11961:1996, Clause 8 or API Spec 5D:2001, Clause 10, or API Spec 5B shall apply.

6 Ordering information

6.1 In specifying the application of this International Standard to an order for the inspection of new OCTG, the owner shall specify, for each size and type of OCTG, the following order information:

- a) the inspection(s) to be applied;
- b) the frequency of sampling for inspection;
- c) the reference standard, if applicable;
- d) the acceptance criteria;
- e) the permissible disposition of all classifications of OCTG (see Table A.19);
- f) the instructions for marking.

6.2 The applicability of methods and procedures contained in this International Standard in accordance with ISO 11960, ISO 11961 or API Spec 5D, or API Spec 5B is indicated in 11.2, 12.2, 13.2, 14.3, 15.2, 16.2, 17.2, 18.2, 19.2 and 20.2. Some procedures in this International Standard are beyond the scope of the inspection requirements of ISO 11960, ISO 11961 or API Spec 5D, and API Spec 5B.

7 Quality assurance

7.1 The agency performing field inspection shall have a quality programme consistent with the provisions of a recognized quality standard. The agency's quality programme shall be documented and shall include written procedures for all inspections performed.

7.2 The agency's quality programme shall include documented procedures for the calibration and verification of the accuracy of all measuring, testing and inspection equipment and materials.

7.3 The agency's quality programme shall include records that verify inspection system capability for detecting the required reference indicators. In order to meet the requirements of ISO 11960, and ISO 11961 or API Spec 5D, the verification of inspection system capability shall address the following.

- a) Standardization and operating procedures: The standardization procedures will vary with the different types of equipment, but as a minimum the written procedures shall address the method for assuring coverage (minimum 100 % for longitudinal and transverse flaws), minimum notch response, and maximum signal-to-noise ratio. The written operating procedures shall provide the required steps, control settings and parameter limits, such as use of special electronic circuits, use of special detector array configurations (pig tails), and maximum velocities to be used.
- b) Equipment description: The equipment used to conduct the inspection shall be described in sufficient detail to demonstrate that it meets the requirements of ISO 11960, or ISO 11961 or API Spec 5D.

- c) Personnel qualification: documentation of qualification of inspection personnel shall meet the requirements of Clause 8.
- d) Dynamic test data demonstrating the system capabilities for detecting the reference indicators: there are many methods of verifying system capability, two of which are as follows:
 - 1) Inspection system capability is established by using statistical techniques for assessment of inspection performance. By establishing inspection system setup parameters and response amplitude of the applicable reference flaws, data points are established to determine the distribution of response amplitudes. These data then become the basis for establishing the capability of the inspection system.
 - 2) Inspection system capability is demonstrated for each inspection order by use of a reference standard with the required reference notches. After the system is standardized according to the written procedures, the test standard is inspected at a number of positions to establish the reliability in all quadrants.
- e) Reports: reports shall include all system settings, strip charts (if applicable), traceability of calibration, standardization and setup procedure, and a map of the test standard.

7.4 The agency's quality programme shall include provisions for the education, training and qualification of personnel performing inspections in accordance with this International Standard.

8 Qualification of inspection personnel

8.1 General

This clause sets forth the minimum requirements for qualification and certification (where applicable) of personnel performing field inspection of OCTG.

8.2 Written procedure

Agencies performing inspection of OCTG in accordance with this International Standard shall have a written procedure for education, training and qualification of personnel. The written procedure shall include the following:

- a) establish administrative duties and responsibilities for execution of the written procedure;
- b) establish personnel qualification requirements;
- c) require documentation verifying all qualifications.

8.3 Qualification of inspection personnel

The qualification inspection personnel shall be the responsibility of the agency. ISO 11484 or ASNT SNT-TC-1A may be used as a guideline.

The requirements for each applicable qualification shall include the following as a minimum:

- a) training and experience commensurate with the inspector's level of qualification;
- b) written and practical examinations with acceptable grades;
- c) a vision examination;
- d) knowledge of the related sections of the applicable ISO/API standards and this document.

8.4 Training programmes

8.4.1 All qualified personnel shall have completed a documented training programme designed for that level of qualification. The programme shall include the following:

- a) principles of each applicable inspection method;
- b) procedures for each applicable inspection method, including calibration and operation of inspection equipment;
- c) related sections of the applicable ISO/API standards.

8.4.2 Training may be given by the agency or an outside agent.

8.5 Examinations

8.5.1 All inspection personnel shall have successfully completed the following examinations.

- a) Written examinations addressing the general and specific principles of the applicable inspection method, the inspection procedures, and the applicable ISO/API standards.
- b) A practical examination that shall include apparatus assembly, standardization, inspection techniques, operating procedures, interpretation of results for appropriate levels, and related report preparation.
- c) Natural or corrected vision to read J-2 letters on a Jaeger number-2 test chart at a distance of 304,8 mm to 381,0 mm (12 in to 15 in). Equivalent tests, such as the ability to perceive a Titmus number-8 target, a Snellen fraction 20/25, or vision examinations with optical apparatus administered by physicians, are also acceptable.

8.5.2 Examinations shall be given by the agency or an outside agent.

8.6 Experience

All candidates for qualification shall have the experience required by the written procedure.

8.7 Requalification

8.7.1 Requalification requirements shall be defined in the written procedure.

8.7.2 Requalification is required at least every five years for all personnel.

8.7.3 Requalification of personnel is required if an individual has not performed defined functions within the previous 12 months, or if an individual changes employers.

8.7.4 As a minimum requirement for requalification, all personnel shall achieve an acceptable grade on a written examination addressing the current applicable OCTG inspection procedures, and the applicable ISO/API documents.

8.8 Documentation

8.8.1 Record retention and documentation are required for all qualification programmes. The following are minimum requirements:

- a) all qualified personnel shall receive an attestation of qualification stating their level of qualification;
- b) the records of all qualified personnel showing training program completion, experience, and examinations shall be maintained by the agency for a minimum period of 5 years and made available for review upon request.

8.8.2 All qualifications and related documents shall be approved by authorized agency personnel.

8.9 NDT personnel certification

8.9.1 A programme for certification of NDT personnel shall be developed by the agency. ISO 11484 or ASNT-TC-1A may be used as a guideline.

8.9.2 The administration of the NDT personnel certification programme shall be the responsibility of the agency.

8.9.3 ISO and API are neither responsible for administering the NDT certification programme nor acting as a certifying agent in the programme.

9 General inspection procedures

9.1 General

This clause covers general procedures applicable to all inspection methods contained in this International Standard.

9.2 Documents at job site

The following inspection-related documents shall be available at the job site:

- a) applicable ISO standards listed in Clause 3;
- b) additionally, when ISO/API thread gauging is being conducted, a copy of API RP 5B1;
- c) all applicable agency-controlled and qualified inspection procedure documents;
- d) the field inspection contract or agency inspection order based on the contract.

9.3 Pre-inspection procedures

9.3.1 Each inspection shall start with the correct equipment available and in good working condition.

9.3.2 Prior to equipment setup, the agency shall assure that the OCTG to be inspected is the OCTG the owner has ordered to be inspected by comparing the information on the job order with the OCTG markings, i.e. diameter, nominal mass, grade, manufacturer, and whether seamless or welded.

9.3.3 All inspection shall begin by uniquely numbering or renumbering each length with a paint marker. Place the sequence number on the outside surface, preferably on the coupling end, box end, or identified end and printed in white paint so that it can be read from the end of the length. Do not place numbers over mill paint stencils. Unique numbering of unattached couplings is not required, however rejected couplings shall be identified and segregated from prime couplings. If a defect is found on a length of OCTG, complete all specified inspections on that length unless otherwise stipulated in the inspection contract.

9.4 Records and notification

As inspection progresses, maintain a record of the classification of the OCTG inspected. If at any time after 50 lengths or couplings have been inspected or tested, the reject rate exceeds 10 % of the OCTG inspected, notify the owner or his/her representative. If appropriate, it is suggested that the manufacturer, or his/her representative, be notified in turn through the purchaser.

9.5 Post-inspection procedures

9.5.1 Classification

Classify each length of pipe or coupling into one of the categories listed below (see Clause 21 for details):

- a) prime pipe with good connections, or prime unattached couplings;
- b) prime pipe with defective connections;
- c) pipe that contains conditionable defects;
- d) pipe that contains non-conditionable defects;
- e) non-conditionable unattached couplings (rejects);
- f) unattached couplings requiring conditioning;
- g) pipe or unattached couplings not meeting special owner-specified tests.

9.5.2 Marking

Mark the classification of each pipe and coupling with paint markings and apply all applicable inspection markings as described in Clause 21.

9.5.3 Cleaning

Remove all magnetic powder and cleaning material from the pipe and coupling surfaces. Do not contaminate nearby pipe during this process.

Material Safety Data Sheets should be read and the precautions observed when handling products of this type. Consideration should be given to the storage, transport, use and disposal of excess materials and containers. Observe appropriate regulations relative to disposal of used solvents and generated waste materials.

NOTE Solvents and other cleaning agents might contain hazardous materials. Solvents are normally volatile and can build up pressure in containers.

9.5.4 Count and tally lengths

Count and tally the lengths in each of the classification categories. Be sure to verify the totals after the initial count. Segregate the prime OCTG from all other OCTG if practical. Tally each length of casing and tubing using the overall length (including pin threads and coupling). By agreement between the owner and the agency, a “makeup” tally as described in ISO 10405:2000, 4.1.7 c) or API RP 5C1:1999, 4.1.7 c) shall be substituted on acceptable OCTG. An overall tally shall be used on rejected OCTG.

9.5.5 Thread protection

After inspection, ensure that the threads are clean and dry. Lubricate the threads with a thread compound that meets the performance objectives of ISO 13678 or API RP 5A3 or with a specific thread compound if specified by the owner. Lubricate the entire threaded area, including seals and thread roots, for the full thread circumference. In very cold climates, it might be necessary to warm the thread compound in order to apply it.

The Material Safety Data Sheets for thread compounds should be read and observed. Storage and disposal of containers and unused compound should be in accordance with appropriate regulations.

9.5.6 Thread protectors

Reinstall clean thread protectors and tighten them wrench-tight.

9.6 Job site checklist

Before leaving the job site, the agency shall ensure that the following items have been accomplished.

- a) Pipe racking. The agency shall ensure that each row of pipe has been properly secured (e.g. with chocks) for safety, and that no loose or unsecured pipe is left free to roll or fall from the racks. No pipe shall be left on the ground. Ensure that the pipe has been properly racked, and that all pipe has stripping between layers. Stripping shall be placed directly over the centreline of each sill.
- b) Unattached couplings. Unattached couplings shall be stored for protection against the environment. Unless otherwise specified by the owner, they shall be returned to their original shipping container.
- c) Debris removal. The job site shall be left neatly arranged and clean of all job-related debris.
- d) Solvent disposal. Cleaning solvents used at the job site shall be disposed of properly.

9.7 Documentation

A field copy of the completed inspection report and supporting documents shall be delivered to the customer or specified representative upon completion of the job. Terminology for defects shall comply with API Std 5T1, where applicable.

10 Acceptance criteria, disposition and responsibility

10.1 General

This clause sets forth the principles for determining acceptance criteria, disposition, and responsibility for OCTG inspected in accordance with this International Standard.

10.2 Basis for acceptance

ISO 11960, ISO 11961 or API Spec 5D, or API Spec 5B constitute the basis for acceptance of OCTG inspected in accordance with this International Standard, except that additional or more restrictive criteria may be contracted between the owner and the agency.

10.3 Responsibility for rejections

10.3.1 The manufacturer shall be responsible for rejects which, after evaluation, are demonstrated to be nonconforming to the requirements of ISO 11960, ISO 11961 or API Spec 5D, or API Spec 5B. Manufacturer responsibility for defects attributable to handling or shipping damage shall be limited to those conditions reported to the manufacturer at, or prior to, delivery to the purchaser. Rejection shall not be based solely on unevaluated imperfections or indications (see 10.3.3).

10.3.2 In an identical manner to 10.3.1, the manufacturer shall be responsible for rejects that, after evaluation, are demonstrated to be conforming to the requirements of ISO 11960, ISO 11961 or API Spec 5D, or API Spec 5B but nonconforming to additional or more restrictive criteria for which the manufacturer is contractually liable (see 10.3.3).

10.3.3 In the event the manufacturer may be responsible for the rejection, but the purchaser and manufacturer are unable to agree that the OCTG is defective, a destructive test may be performed. If tests that require the destruction of material are made, any product that is proven to have not met the requirements of the specification shall be rejected. Disposition of rejected product shall be a matter of agreement between the manufacturer and purchaser.

10.3.4 Disposition of defects shall be in compliance with the applicable specification. Dispositions shall be recorded and shall be traceable to the OCTG inspection number (see 9.3.3).

11 Visual and dimensional inspection

11.1 General

This clause provides descriptions, mechanical equipment requirements, and procedures for visual and dimensional inspection of OCTG.

11.2 Application

The inspections described in this clause are applicable to all sizes and all types of OCTG.

11.3 Drift mandrels

The diameter of the drift mandrel shall be measured with a vernier calliper or micrometer having flat contacts.

The instrument used shall be calibrated using a known precision setting standard at least once every 4 months.

The calibration check shall be recorded on the instrument, and in a log book, giving the date of the calibration check, the due date, and the initials of the person who performed the check. Length measurements may be made using one of the devices listed in 11.5.

11.4 Precision callipers (micrometer, vernier calliper or dial calliper)

The instrument shall be calibrated using a known precision reference standard at least once every 4 months. The calibration check shall be recorded on the calliper, and in a log book, giving the date of the calibration check, the due date, and the initials of the person who performed the check.

11.5 Length- and diameter-measuring devices (steel rules, steel length- or diameter-measuring tapes, and other non-adjustable measuring devices)

Accuracy verification shall be defined as a visual check of the legibility of the markings and the general wear of fixed reference points. The verification procedure of these devices shall be documented.

11.6 Depth gauges

11.6.1 General

The following conditions and checks apply to gauges used for imperfection evaluation in Clause 19.

11.6.2 External depth gauges

For external depth gauges the following shall apply.

- a) Set the gauge to zero on a flat surface.
- b) Check measuring accuracy of the gauge over a range of standard depths, at least once every 4 months or after repair or replacement.
- c) Accuracy shall be within 0,025 mm (0.001 in) of actual depths of the reference standard.
- d) The calibration check shall be recorded on the gauge, and in a log book, giving the date of the calibration check, the due date, and the initials of the person who performed the check.

11.6.3 Internal depth gauges

For internal depth gauges and wall thickness callipers the following shall apply.

- a) Set the gauge to read zero or a specified thickness when the contact points touch or when a standard thickness is placed between the contacts.
- b) Check the measuring accuracy of the gauge over a range of standard thicknesses, different from those used in 11.6.2.b), at least once every 4 months or after repair.
- c) Accuracy of readings shall be within 2 % of the actual wall thickness of the thickest standard used.
- d) The calibration check shall be recorded on the gauge, and in a log book, giving the date of the calibration check, the due date, and the initials of the person who performed the check.

11.7 External surface illumination

11.7.1 Direct daylight

Direct daylight conditions do not require a check for surface illumination.

11.7.2 Night and enclosed-facility lighting

The diffused light level at the surfaces being inspected shall be at least 500 lx (50 fc). Illumination shall be checked once every 4 months. The check shall be recorded in a log book, giving the date, the reading, and the initials of the person who performed the check. This record shall be available on site. Illumination shall be checked whenever lighting fixtures change position or intensity, relative to surfaces being inspected.

11.7.3 Night-lighting with portable equipment

The diffused light level at the surfaces being inspected shall be at least 500 lx (50 fc). Proper illumination shall be verified at the beginning of the job to assure that portable lighting is directed effectively for surfaces being inspected. Illumination shall be checked during the job whenever lighting fixtures change positions or intensity relative to the surfaces being inspected.

11.7.4 Light-meter calibration

Light-meters used to verify illumination shall be calibrated at least once a year. The calibration check shall be recorded on the meter, and in a log book, giving the date of the calibration check, the due date, and the initials of the person who performed the check.

11.8 Internal surface illumination

11.8.1 Mirrors for illumination

The reflecting surface shall be a non-tinted mirror that provides a non-distorted image. The reflecting surface shall be flat and clean.

11.8.2 Spotlights

A light source having documented, demonstrated capability shall be used for illumination of inside surfaces. A spotlight producing an illumination greater than 1 000 lx (100 fc) at the maximum inspection distance may be used for this. The lens of the light source shall be kept clean.

11.8.3 Borescope equipment

The borescope lamp shall meet the requirements shown in Table A.2. The resolution of the borescope shall be checked at the start of a job, and whenever all or part of the borescope is assembled or re-assembled during a job. The date on a coin [not to exceed 1,02 mm (0.040 in) in height] or Jaeger J-4 letters placed within 101,60 mm (4 in) of the objective lens, shall be readable through the assembled borescope.

11.9 Full-length visual inspection (FLVI) of new OCTG

11.9.1 Description

A full-length visual inspection of the entire outside and inside surfaces, excluding the threads, shall be conducted to detect gouges, cuts, pits, dents, grinds, mechanical damage, lack of straightness, and other visually detectable imperfections. On electric-welded pipe, special attention should be given to weld flash and trim. Each length shall be rolled and the entire surface viewed. The entire inside surface shall be inspected using a high intensity light, mirror or borescope (depending on size) meeting the requirements of 11.8.

11.9.2 External visual inspection procedure

Inspect lengths in groups by first rolling them together. Observe the pipe while rolling to detect straightness problems. Evaluate bent or bowed pipe in accordance with Clause 19.

Use the following procedure for external visual inspection:

- a) identify the upper one-third of each length with a chalk mark;
- b) examine each pipe surface by walking the length of each pipe from one end to the other. The number of lengths inspected on each pass will depend on the diameter. As each imperfection is found, mark it and evaluate it in accordance with Clause 19;
- c) after the top one-third of this group has been inspected, roll each length one-third of a turn and mark with chalk;
- d) repeat b) and c) until the entire outside surface of the pipe has been inspected.

11.9.3 Internal visual inspection procedures

Inspect the entire inside surface, excluding the threads, for imperfections. Pipe sizes Label 1: 10-3/4 and larger shall be visually inspected from each end using an illumination source meeting the requirements of 11.8.1, 11.8.2 or 11.8.3. For pipe sizes smaller than Label 1: 10-3/4, the best quality inspections are done with a borescope; see 11.8.3 for resolution requirements.

11.10 Outside diameter verification

11.10.1 If requested by the owner, the diameter of each length shall be verified to assure compliance with ISO 11960 and with ISO 11961 or API Spec 5D.

11.10.2 Verification of minimum and maximum diameter may be performed with snap gauges.

11.10.3 Micrometers or mechanical callipers that display the readout in hundredths of a millimetre (thousandths of an inch) shall be used to measure actual diameter.

11.10.4 Diameter tapes shall be used to measure average diameter.

11.11 Straightness

11.11.1 A visual inspection shall be performed to detect hooked ends or bowed pipe. Pipe to be examined shall be placed on a rack or joists where it can be rolled while visually examining for straightness.

11.11.2 Pipe sizes Label 1: 4-1/2 and larger shall be measured to determine the amount of straightness deviation whenever a visual examination has shown them to have hooked ends or to be bowed. This measurement shall be performed using a straight edge or taut string (wire) and a steel scale or rule.

11.11.3 Straightness shall be evaluated in accordance with Clause 19.

11.12 Drift testing

11.12.1 General

Casing or tubing shall be drifted throughout its entire length to detect reduction in inside diameter. Group 1 external upset drill pipe, except sizes Label 1: 3-1/2 to Label 2: 13.30, shall be drifted throughout the length of the end upsets. Drift mandrels manufactured in accordance with ISO 11960, ISO 11961 or API Spec 5D, or this International Standard shall be used for this test.

11.12.2 Drift mandrel specifications

Drift mandrel specifications are as follows.

- a) The minimum diameter of the cylindrical portion of a drift mandrel for bare casing, tubing, and drill pipe shall be in accordance with Table A.4, Table A.5 and Table A.8. Diameters for sizes and masses not included in these tables shall be calculated in accordance with Table A.3. A drift mandrel for internally-coated pipe shall be made of plastic, or hardwood such as oak and, as a guide, should meet the dimensions specified in Table A.6 and Table A.7. Because of the extra thickness added by the coating, a “no-drift” coated length might not need to be classified as a reject.
- b) The drift mandrel shall be cylindrical in shape and may have attachments on one or both ends. Disk and barbell-shaped mandrels shall not be used. The ends of the drift mandrel extending beyond the specified cylindrical portion shall be shaped to permit easy entry into the pipe.

Sometimes pipe is drifted in the field to allow drilling with commonly used bit sizes. Drift sizes that are in use to allow passage of these commonly used bit sizes are shown in Table A.4. Pipe through which this specified drift passes should be marked as recommended in Clause 21.

NOTE Pipe rejected for failure to pass this specified or alternative drift is not the responsibility of the manufacturer unless the pipe was ordered that way.

11.12.3 Drift mandrel verification procedures

The following drift mandrel verification procedures shall be followed.

- a) The length of the cylindrical portion of the drift mandrel shall be measured (a steel scale may be used for this measurement). Specified drift mandrel lengths are tabulated in Table A.3.
- b) The mandrel diameter shall be measured using a micrometer or mechanical calliper that displays the readout in hundredths of a millimetre (thousandths of an inch). These measurements shall be made with the drift mandrel and micrometer at the same temperature. Measurements shall be made at each end of the drift mandrel. Each measurement shall be made in two locations, 90° apart. The allowable mandrel tolerance shall be 0,000 mm to +0,013 mm (0.000 in to +0.005 in) from the specified ISO/API dimensions. Drift mandrels larger than the upper tolerance of +0,013 mm (+0.005 in) may be used for acceptance but not for rejection. In case of dispute, a precision steel drift mandrel made to the appropriate ISO/API dimensions shall be used to resolve whether the lengths are acceptable or rejectable.

11.12.4 Drifting procedures

The following drifting procedures shall be followed.

- a) Select and measure the correct drift mandrel prior to starting the inspection job, and re-measure the mandrel at least once for every 500 lengths thereafter.
- b) The drift mandrel shall be at approximately the same temperature as the pipe being inspected.
- c) Pass the drift mandrel through the entire length of each casing and tubing and through the upset length of drill pipe. The drift mandrel shall pass through the pipe or upset freely using a reasonably exerted force

that does not exceed the weight of the drift mandrel. The drift should be inserted and removed carefully so that neither the threads nor the seals are scratched or damaged.

- d) If the drift does not pass through the entire length of casing or tubing or the drill pipe upset, remove and clean the drift mandrel. Clean out the pipe if necessary. Check the pipe for sagging and provide additional support if needed.
- e) Attempt the drift test again from the other end of the pipe. If the drift mandrel does not pass through the entire length on the second attempt, the length shall be considered a reject and identified immediately as a "no-drift."

11.13 Visual thread inspection (VTI)

11.13.1 General

Visual thread inspection is a method for locating thread imperfections without the use of magnetic particle inspection or thread gauges other than a profile gauge. This inspection applies to exposed round threads on casing and tubing and exposed buttress threads on casing. Visually evident manufacturing defects or mechanical damage to the threads are detected by this inspection method.

NOTE Extreme-line threads are excluded from these inspection procedures. For extreme-line threads, refer to API Spec 5B.

11.13.2 Evaluation tools

Though imperfections can be visually located during this inspection, the following tools shall be used to evaluate the magnitude of the imperfections found:

- a) a steel scale for accurately determining the L_c area on the pin and the perfect thread length of internal threads [see 11.13.4c)];
- b) mirror for inspection of load flanks and roots of internal threads;
- c) bright light, meeting the requirements of 11.8.2, for inspection of internal threads;
- d) profile gauge, for detection of thread profile errors;
- e) flexible steel measuring tape for measuring circumferential nonfull-crested or black-crested thread length on buttress threads.

A copy of API Spec 5B and this International Standard shall be available on location.

11.13.3 Thread repair

Repair of threads is not a part of this inspection. However, by agreement between the owner and the agency, cosmetic (minor) repair of threads may be made.

11.13.4 Visual thread inspection procedures

Proceed as follows.

- a) Remove the thread protectors and stack them out of the way so that they will not be a work hazard. From this step, until the thread protectors are reinstalled, great care shall be taken to ensure that two lengths of pipe do not strike each other and damage the unprotected threads. Pipe shall never be loaded, unloaded, or removed to another rack without thread protectors installed. Never leave threads unprotected from moisture or condensation overnight. Use of a light corrosion inhibitor is recommended.

NOTE 1 Martensitic chromium steels (ISO 11960, grades L80-9Cr and L80-13Cr) are sensitive to galling. Special precautions might be necessary for thread surface treatment and/or lubrication to minimize galling.

- b) Clean all exposed threads thoroughly. Ensure that no thread compound, dirt, or cleaning material remains on the threads.
- c) Determine the L_c length of pin end threads and record this number. Refer to Table A.9 and Table A.10 of this International Standard, or to API Spec 5B from which these tables were taken.

Internal threads do not have an L_c area. All of the threads within the interval from the counterbore to a plane located at a distance J plus one thread turn from the centre of the coupling or small end of integral joint OCTG shall be inspected to the L_c area requirements. This area is defined as the internal perfect thread length (PTL). The calculated perfect threads are listed in the Table A.9 and Table A.10.

NOTE 2 Thread classification depends on the location of an imperfection. Imperfections located in the L_c area of external threads or in the PTL of internal threads have different criteria for acceptance and rejection than those outside these regions. Measurement might be required to determine if imperfections are in the L_c or box PTL.

- d) Slowly roll individual lengths at least one full revolution while examining the threads.
- e) For external threads, inspect for imperfections on the face, chamfer, L_c area and non- L_c area. The thread profile gauge shall be applied to the threads to detect machining errors.
- f) For internal threads, inspect for imperfections in the counterbore, PTL, and threaded area beyond the PTL. Seal-ring grooves shall be inspected for fins, wickers, and ribbons that are loose, or could become loose, on each side of the groove. The profile gauge shall be applied to the threads to detect machining errors. Caution shall be exercised when applying the profile gauge to avoid damaging thread coating. Exploratory grinding or filing to determine the depth of an imperfection is not permitted in the L_c area of external threads or the total length of internal threads.

11.13.5 Categories of imperfections

Types of imperfections that may cause thread rejection are listed below. Refer to 19.12 or API Spec 5B for dimensional data for acceptance and rejection.

- a) Threaded area imperfections:
 - 1) broken threads;
 - 2) cuts;
 - 3) grinds;
 - 4) shoulders or steps;
 - 5) seams;
 - 6) non-full-crested threads (including black-crested threads);
 - 7) laps;
 - 8) pits;
 - 9) dents;
 - 10) tool marks;
 - 11) fins;
 - 12) dings;

- 13) burrs;
- 14) torn threads (tears);
- 15) handling damage;
- 16) thick threads;
- 17) narrow threads (shaved threads);
- 18) galls;
- 19) improper thread height;
- 20) wicker (or whisker);
- 21) cracks;
- 22) chattered threads;
- 23) wavy or drunken threads;
- 24) improper thread form;
- 25) arc burns;
- 26) threads not extending to the centre of the coupling (threads within the *J*-area may not be perfect);
- 27) imperfections, other than those listed above, that break the continuity of the thread.

NOTE 1 Non-full-crested threads have historically been, and continue to be, referred to as black-crested threads because the original mill surface has not been removed. The term black-crested thread is a useful descriptive term, however, it should be understood that there can also be non-full-crested threads that are not black.

b) Conventional chamfer area:

- 1) not present 360°;
- 2) thread running out on the face;
- 3) razor edge;
- 4) feather edge;
- 5) burrs;
- 6) false starting thread engaging actual starting thread;
- 7) mashes;
- 8) cuts.

NOTE 2 The surfaces of the chamfers need not be perfectly smooth. Chamfers on the pipe ends have no effect on the sealing capability of the threads.

c) Round or bullet nose for tubing:

- 1) radius transition not smooth;
- 2) sharp corners;
- 3) burrs;
- 4) slivers;
- 5) false starting thread engaging actual starting thread;
- 6) mashes;
- 7) cuts.

NOTE 3 Dimensions are not subject to measurement to determine acceptance or rejection of the product.

d) Pipe end imperfections (inside and outside):

- 1) burrs;
- 2) fins;
- 3) dents/mashes.

e) Box face and counterbore imperfections:

- 1) tool marks;
- 2) mashes;
- 3) burrs;
- 4) arc burns.

f) Mill end makeup: Coupling makeup measurement is not part of visual thread inspection. However, if visual inspection reveals obvious makeup errors, evaluate in accordance with Clause 19.

All imperfections listed in a) through e), if detected, shall be evaluated in accordance with 19.12.

12 Hardness testing

12.1 General

This clause covers methods for hardness testing under field conditions. This test may also be used to determine compliance with contractual hardness specifications.

NOTE Brinell-type testing using visually measured impression diameters is outside the scope of this International Standard.

12.2 Application

ISO 11960, and ISO 11961 or API Spec 5D, contain no direct provision for surface hardness testing. The owner shall specify the test locations and acceptance criteria (hardness range).

NOTE The steel grade cannot be reliably determined by hardness testing alone.

12.3 Equipment

A wide variety of portable hardness testing equipment is available. Some types of hardness testers are suitable only for general information and vary in accuracy (as explained in ASTM E 110:2002, Note 2). Other types of hardness testers as described in ASTM E 110 may also be employed.

12.4 Calibration

12.4.1 Annual calibration

Hardness testers shall be calibrated at least once a year and after each repair. The calibration shall be conducted by a certified agency issuing a certificate showing traceability to a statutory authority. The certificate shall identify the date of the check, the specified values of each certified hardness test block, the mean value of the tester readings on each block, and the initials of the person performing the check.

12.4.2 Four-month verification

The accuracy of hardness testers that were used during any four-month period shall be verified at the end of that four-month period. This shall be accomplished by taking five readings on each of two certified hardness test blocks of different hardness values on the scale to be used. The mean of the five readings on any certified hardness test block shall be within the specified range of that block for the tester to be acceptable for use. Certified hardness test blocks shall never be used on both sides. One of the test blocks shall be within ± 5 hardness numbers at the low end of the range of values specified for the OCTG being tested. The other test block shall be within ± 5 hardness numbers at the high end of the specified range of values for the OCTG being tested. Each Rockwell Hardness C-scale (HRC) certified hardness test block shall have a mean value of not less than 20 HRC. Each Rockwell Hardness B-scale (HRB) certified hardness test block shall have a mean value of not more than 100 HRB.

12.5 Standardization

12.5.1 Standardization shall be performed prior to each job or when the hardness range changes for the OCTG being tested. The hardness tester instructions supplied by the tester manufacturer shall be followed. For all types of testers, the procedure for checking the tester prior to performing tests is the same except for attaching the tester to the OCTG or the certified hardness test block.

12.5.2 The hardness testing equipment shall be checked to determine if the proper load cell has been installed and if the correct indenter is being used for the hardness range specified.

12.5.3 The indenter shall be examined prior to use. If it is chipped, spalled, distorted or deformed, it is defective and requires replacement, in accordance with the manufacturer's instructions.

12.5.4 The test block shall have a hardness within the specified range of the OCTG to be tested.

12.5.5 The hardness test block shall be placed onto the anvil with the calibration (indented) side up. If both sides of the test block show use, the test block is not suitable for further use.

12.5.6 Indentations shall be spaced no closer than $2\frac{1}{2}$ diameters from their centre to the edge of the test block or 3 diameters from another indentation, measured centre-to-centre.

12.5.7 Contact surfaces and/or shoulders of a hardness test block, anvil, or indenter shall be clean and free from oil film.

12.5.8 Three readings shall be made on the certified hardness test block. The average of these readings shall be within the specified range of the test block. Any single reading shall not vary more than two Rockwell numbers from the specified mean value of the test block. No more than the first two readings may be discarded, in order to reduce the probability of errors, before the next three readings are used for averaging.

12.6 Procedures

12.6.1 The acceptable hardness range, number of readings made on each prepared test area, and the location of the test areas are by agreement between the owner and the agency. Unless otherwise specified, grind, machine or file the OCTG surface approximately 0,25 mm (0.010 in) deep, for a length of approximately 50 mm (2 in) to remove any possible decarburized layer. Before grinding, machining or filing, the wall thickness shall be determined to prevent reducing the wall thickness below that allowable. If the wall thickness is at, or close to, the allowable minimum, an alternative location shall be selected. Ensure that the area is smooth and flat so that accurate readings can be obtained. Caution shall be taken during grinding to avoid overheating the test area. A blue colour indicates grinding practices are causing excessive heating. Contact surfaces of the test area and indenter shall be clean and free from oil film.

12.6.2 Attach the tester to the OCTG and test the OCTG according to the instrument operating procedures as specified by the hardness tester manufacturer.

12.6.3 Indentations shall be more than 3 diameters from each other and in the prepared area, no closer than 6,35 mm (1/4 in) from the edge of the prepared area.

12.6.4 A test shall consist of two or more valid readings that have been made in the same test area. Readings are valid when they are within two Rockwell C numbers (HRC) of one another or four Rockwell B numbers (HRB) of one another. The readings, to the nearest whole number, shall be recorded on the OCTG surface adjacent to the test area using chalk or paint.

12.6.5 The hardness value shall be the average of the valid readings taken in the test area. The hardness value and/or the readings shall be recorded to the nearest whole number on the appropriate report form.

12.6.6 Standardization checks shall be performed periodically on the tester, using a certified hardness test block as defined in 12.5.4, taking two or more readings on the test block in accordance with 12.5. The tester shall be checked at the following times:

- a) after every 100 readings;
- b) whenever the hardness tester is subjected to abnormal mechanical shock;
- c) at the end of the inspection job;
- d) prior to rejection of any OCTG.

12.6.7 All tests that have been made between the last acceptable periodic check and an unacceptable check shall be repeated.

12.6.8 Rockwell readings that are below 20 HRC require that the readings be made again using the Rockwell B scale, unless readings below 20 HRC are permitted by an agreement between the inspection agency and the owner.

12.6.9 Rockwell readings above 100 HRB require that the readings be made again using the Rockwell C scale, unless readings above 100 HRB are permitted by agreement between the inspection agency and the owner. To prevent indenter damage, caution shall be taken when readings above 100 HRB are encountered. Re-standardization shall be done after such readings.

13 Magnetic particle inspection (MPI)

13.1 General

This clause provides material requirements, equipment requirements, descriptions and procedures for wet fluorescent and dry magnetic particle inspection of new ferromagnetic OCTG.

OCTG subjected to MPI may retain significant residual magnetism. See Clause 15 for measurement of residual magnetism and for demagnetization.