

STANDARDS AUSTRALIA/STANDARDS NEW ZEALAND

**Amendment No. 2
to
AS/NZS 3350.2.97:2000
Safety of household and similar electrical appliances
Part 2.97: Particular requirements for drives for rolling shutters, awnings, blinds
and similar equipment**

CORRECTION

The 2000 edition of AS/NZS 3350.2.97 is amended as follows; the amendment should be inserted in the appropriate place.

SUMMARY: This amendment applies to the Foreword and Annex ZZ

Published on 25 May 2007

Approved for publication in New Zealand by the Standards Council of New Zealand on 27 April 2007

All parts of this amendment take effect from the date of publication.

Foreword

Add the following as a new second paragraph:

This Standard incorporates Amendment No. 1 (November 2001) and Amendment No. 2 (May 2007). The changes required by the amendments are indicated in the text by a marginal bar and amendment number against the clause, note, table, figure or part thereof affected. Where an application date other than immediate is applicable to an amendment the date of application (DOA) is indicated by the marginal bar against the part affected or by a footnote relating to the part affected.

Replace the existing fourth paragraph by the following:

This Standard is an adoption with national modifications and contains the full text of the first edition of IEC 60335-2-97:1998, Safety of Household and Similar Electrical Appliances – Part 2-97: Particular requirements for drives for rolling shutters, awnings, blinds and similar equipment and has been varied as indicated to take account of Australian and New Zealand conditions. It is to be used in conjunction with the latest edition of AS/NZS 3350.1, Safety of household and similar electrical appliances - Part 1: General requirements and its Amendments. It was established on the basis of AS/NZS 3350.1:2002.

Annex ZZ

Replace the second paragraph by the following:

No indication is given of the variations between AS/NZS 3350.1:2002 and IEC 60335-1:1991. For these variations refer to AS/NZS 3350.1.

ISBN 0-7337-8205-1

This page has been left intentionally blank.