



Standard Test Methods for Felt¹

This standard is issued under the fixed designation D 461; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ε) indicates an editorial change since the last revision or reapproval.

1. Scope

1.1 These test methods are applicable to all types of felt covered by Specification D 2475 and as defined in Section 3 herein.

1.2 The procedures appear in the following sections:

	Section
Acid Content	27
Air Permeability	18
Referenced Documents	2
Ash	26
Bursting Strength	13
Conditioning	7
Terminology	3
Dimensional Changes (Relaxation Shrinkage) in Boiling Water—Length and Width	15
Fiber Identification	24
Flame Resistance	20
Length of Roll	8
Matter Extracted by 1,1,1-Trichloroethane	22
Matter Extracted by Water	23
Oil Retention	21
Oil Wicking	29
pH	28
Sampling Lots and Test Specimens	6
Splitting Resistance	14
Stiffness	19
Summary of Test Methods	4
Tensile Strength, “Breaking Load,” and “Specific Strength”	12
Thickness of Conditioned Specimens	10
Thickness Change After Exposure to Boiling Water and Subsequent Drying	16
Significance and Use	5
Water Retained	17
Weight per Unit Area	11
Width of Roll or Sheet	9
Wool Content (Matter Soluble in a Solution of Sodium Hydroxide)	25

1.3 The values stated in SI units are to be regarded as the standard.

1.4 *This standard should be used to measure and describe the properties of materials, products, or assemblies in response to heat and flame under controlled laboratory conditions and should not be used to describe or appraise the fire hazard or fire risk of materials, products, or assemblies under actual fire conditions. However, results of this test may be used as elements of a fire risk assessment which takes into account all of the factors which are pertinent to an assessment of the fire hazard of a particular end use.*

1.5 *This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use. Specific warning statements are given in Note 9 and 25.4.*

NOTE 1—The word “weight” is used in these test methods because of common trade practice, in place of the technically correct word “mass.”

2. Referenced Documents

2.1 ASTM Standards:

- D 76 Specification for Tensile Testing Machines for Textiles²
 - D 123 Terminology Relating to Textiles²
 - D 276 Test Method for Identification of Fibers in Textiles²
 - D 629 Test Methods for Quantitative Analysis of Textiles²
 - D 737 Test Method for Air Permeability of Textile Fabrics²
 - D 774 Test Method for Bursting Strength of Paper³
 - D 1388 Test Methods for Stiffness of Fabrics²
 - D 1574 Test Method for Extractable Matter in Wool²
 - D 1776 Practice for Conditioning Textiles for Testing²
 - D 2165 Test Method for pH of Aqueous Extracts of Wool and Similar Animal Fibers²
 - D 2475 Specification for Wool Felt²
 - E 70 Test Method for pH of Aqueous Solutions with the Glass Electrode⁴
- ### 2.2 Other Standards:
- TT-I-563a Federal Specifications for Ink, Writing⁵
 - U. S. Military Standard MIL-105D Sampling Procedures and Tables for Inspection by Attributes⁵

3. Terminology

3.1 Definitions:

3.1.1 *acid content, n—of felt*, the number of milliequivalents of acid present per unit weight of felt, measured under prescribed conditions.

3.1.2 *dimensional change in boiling water in felt, n—the change in length and width with any associated change in thickness produced by immersion in boiling water under specified conditions.*

² Annual Book of ASTM Standards, Vol 07.01.

³ Annual Book of ASTM Standards, Vol 15.09.

⁴ Annual Book of ASTM Standards, Vol 15.05.

⁵ Available from Standardization Documents Order Desk, Bldg. 4 Section D, 700 Robbins Ave., Philadelphia, PA 19111-5094, Attn: NPODS.

¹ These test methods are under the jurisdiction of ASTM Committee D-13 on Textiles and are the direct responsibility of Subcommittee D13.13 on Felt.

Current edition approved Feb. 15, 1993. Published March 1993. Originally published as D 461 – 37 T. Last previous edition D 461 – 87.

3.1.3 *extractable matter, n*—nonfibrous material in or on a textile, not including water, which is removable by a specified solvent or solvents, as directed in a specified procedure.

3.1.3.1 *Discussion*—Nonfibrous material is usually oily, waxy, resinous, or polymeric in nature, but may also include other material such as protein, particularly if ethyl alcohol is used as, or in, the extracting solvent.

3.1.4 *flame resistance, n*—the property of a material whereby flaming combustion is prevented, terminated, or inhibited following application of a flaming or nonflaming source of ignition, with or without subsequent removal of the ignition source.

3.1.5 *part wool felt, n*—a felt composed of any one of or a combination of new and recycled wool fibers mixed with one or more man-made fibers, vegetable fibers, or animal fibers other than wool.

3.1.6 *pH, n*—in common usage, a measure of acidity or alkalinity of a solution, on a logarithmic scale, with neutrality represented by a value of 7, with increasing acidity represented by decreasingly smaller values, and with increasing alkalinity represented by increasingly larger values.

3.1.7 *shrinkage, n*—a decrease in one or more dimensions of an object or material.

3.1.8 *splitting resistance, n*—of felt, the force required to overcome the interfacial strength of a material and specifically to separate a felt into two layers (of approximately equal thickness).

3.1.9 *supported needled felt, n*—a needled felt that is composed entirely of fibers physically interlocked and reoriented in combination with interlay, scrim, or foundation of knitted, stitched, bonded, or extruded structure.

3.1.10 *unsupported needled felt, n*—a needled felt that is composed entirely of fibers physically interlocked and reoriented with, and of themselves without an interlay, scrim, or foundation of knitted, stitched, bonded, or extruded structure.

3.1.11 *water retained, n*—in textiles, the amount of water absorbed by the fibers, adsorbed on the surface of the fibers, and held within the voids of the fabric after immersion, measured under specified conditions.

3.1.12 *wool felt, n*—a felt composed wholly of any one of or a combination of new or recycled wool fibers.

3.1.13 For definitions of other textile terms used in these test methods, refer to Terminology D 123.

4. Summary of Test Methods

4.1 These test methods include a number of specific test procedures designed to measure specific properties. Individual summaries are included in specific sections where pertinent (see, for example, 20.2).

5. Significance and Use

5.1 Except where specifically noted, these test methods cannot be formally recommended for acceptance testing of commercial shipments, because reliable data on the between-laboratory precision has not been established. The test methods

are nevertheless used extensively in the trade to rate materials with respect to their conformance with Specification D 2475. In cases of dispute, the statistical bias, if any, between the laboratory of the purchaser and the laboratory of the seller should be determined with each comparison based on testing randomized specimens from one sample of material.

5.2 Unless otherwise specified, no justifiable statements on the bias of the procedures in these test methods can be made since the true values of the properties cannot be established by accepted referee methods.

6. Sampling Lots and Test Specimens

6.1 Take a lot sample as directed in an applicable material specification, or as agreed upon by the purchaser and the seller. In the absence of a material specification or other agreement, take a lot sample and laboratory samples as follows:

Lot Size in Yards or Sheets ^A	Sample size in	
	Rolls /lot	Sheets /lot
Up to 1200	3	7
1201 up to and including 3200	5	10
3201 up to and including 10 000	7	15
10 001 up to and including 35 000	10	25
35 001 up to and including 150 000	15	35
150 001 and over	25	50

^A If a lot contains fewer than the required number of rolls or sheets, sample each role or sheet in the lot.

6.2 Take three samples, mark them “edge No. 1,” “center,” and “edge No. 2,” but do not take samples from areas within 6 in. (150 mm) from the edges of the roll, piece, or sheet; in the case of roll felt, omit the area within a distance from the end of the roll equal to the width of the roll. Mark the sampling areas with indelible ink, or by other means, to indicate the lengthwise direction of the original piece. The size and number of specimens cut will be determined by the number of tests to be run.

NOTE 2—In some cases the same specimens may be used for more than one test. For example, the specimens tested for thickness may also be used for weight, air permeability, wool content, or ash tests.

7. Conditioning

7.1 Bring the samples or specimens from the prevailing atmosphere to moisture equilibrium for testing in the standard atmosphere for testing textiles as defined in Practice D 1776, for tests made as directed in the following sections:

	Sections
Bursting Strength	13
Fire Retardance	20
Oil Retention	21
Splitting Resistance	14
Stiffness	19
Tensile Strength, “Breaking Load,” and “Specific Strength”	12
Thickness Change After Exposure to Boiling Water and Subsequent Drying	16
Thickness of Conditioned Specimens	10
Water Retained	17
Weight per Unit Area	11

7.2 Specimens need not be conditioned for the following tests:

	Sections
Air Permeability	18
Ash	26
Dimensional Change in Boiling Water—Length and Width	15
Fiber Identification	24
Matter Extracted by 1,1,1-Trichloroethane	22
Matter Extracted by Water	23
pH	28
Wool Content	25

8. Length of Roll

8.1 *Apparatus*—Measuring drum of known circumference driven by a chain or other positive nonslip mechanism that registers the yardage on a dial or counter.

8.2 *Procedure*—Measure the length of a roll or piece by running it over the measuring drum, applying just enough tension uniformly to keep the felt running flat and true. Record the indicated length to the nearest 0.1 m or $\frac{1}{8}$ yd.

8.3 *Report*:

8.3.1 State that the specimens were tested as directed in Section 8 of ASTM Test Methods D 461. Describe the material or product sampled and the method of sampling used.

8.3.2 Report the length to the nearest 0.1 m or $\frac{1}{8}$ yd.

8.4 *Precision and Bias*:

8.4.1 *Precision*—The precision of the test method for length of roll is being established.

8.4.2 *Bias*—See 5.2.

9. Width of Roll or Sheet

9.1 *Apparatus*—Steel Rule, graduated in 1 mm or $\frac{1}{8}$ in.

9.2 *Procedure*—Measure the width of a roll, piece, or sheet to the nearest 5 mm or 0.25 in. at five different places uniformly distributed along its full length, but in the case of a roll or piece, omit the ends for a distance equal to the width of the roll.

9.3 *Calculation*—Average the five width measurements.

9.4 *Report*:

9.4.1 State that the specimens were tested as directed in Section 9 of ASTM Test Methods D 461. Describe the material or product sampled and the method of sampling used.

9.4.2 Report the average width to the nearest 5 mm or 0.25 in. In the case of sheet felt, report both directions as width.

9.5 *Precision and Bias*:

9.5.1 *Precision*—Since the procedures in Test Methods D 461 for testing the width of felt involve only the reading of a steel rule, the precision of the procedure has not been established.

9.5.2 *Bias*—The procedures in Test Methods D 461 for testing the width of felt have no known bias and are generally used as a referee method.

10. Thickness of Conditioned Specimens

10.1 *Significance and Use*—This test is used to determine if the sample felt in roll, sheet and cut part form meets specific tolerances for thickness. Thickness is a critical dimensional characteristic of felt.

10.2 *Apparatus*:

10.2.1 *Dial Micrometer*, consisting of an anvil for supporting the specimen, a circular presser foot acting under a

dead-weight load and a dial graduated to read 0.02 mm (0.001 in.) in increments of 0.02 mm.

10.2.2 *Supporting Anvil*—A flat horizontal surface with a minimum diameter of 50 mm (2 in.).

10.2.3 *Presser Foot*—The lower surface of the presser foot shall be parallel to the plane of the anvil and have an area of $6.45 \pm 2 \text{ mm}^2$ ($1 \pm 0.0025 \text{ in.}^2$), that is 28.6 mm (1.129 in.) in diameter. It shall be sufficiently thick to ensure rigidity, and the edges shall be rounded off with a radius of $0.40 \text{ mm} \pm 0.02 \text{ mm}$ ($0.016 \pm 0.001 \text{ in.}$). The surface of the presser foot shall be actuated by a freely acting total dead weight of $283 \pm 14 \text{ g}$ ($10 \pm 0.5 \text{ oz}$), except that when the felt has a density less than 0.14 g/cm^3 (0.08 oz/in.^3) the dead weight load shall be $57 \pm 2.8 \text{ g}$ ($2 \pm 0.1 \text{ oz}$).

10.3 *Sampling*—Use specimens having an area of at least 258 cm^2 (40 in.^2) taken from the center and side areas described in Section 6.

10.4 *Procedure for Roll and Sheet Specimens*—Place the conditioned specimen on the supporting anvil of the dial micrometer in a flat and relaxed condition. For large, heavy or stiff felts, provide large additional supports at the same level as the anvil to avoid tendencies for the felt to curve or buckle. Apply the load to the specimen gradually and without shock. After approximately 10 s read the thickness on the dial to the nearest 0.025 mm (0.001 in.). Measure the thickness in five locations evenly distributed over each specimen.

10.5 *Calculation and Report for Roll and Sheet Specimens*:

10.5.1 Calculate the average of the five thickness readings on each specimen of roll and sheet felt.

10.5.2 State that the specimens were tested as directed in Section 10 of ASTM Test Methods D 461. Describe the material or product sampled and the method of sampling used.

10.5.3 Report the average thickness of all specimens to the nearest 0.025 mm (0.001 in.).

10.6 *Precision and Bias for Roll and Sheet Specimens*:

10.6.1 *Precision*—The precision of the test method for thickness is being established.

10.6.2 *Bias*—See 5.2.

10.7 *Procedure for Cut Parts*:

10.7.1 Take samples of cut felt parts at random from throughout the entire lot. Take a lot size of the sample as directed in MIL-STD-105D, General Inspection Level II, Multiple Sampling Plan for Normal Inspection.

10.7.2 When the cut part is large enough to provide a continuous flat felt surface under the 28.66-mm (1.129-in.) diameter foot, proceed as in 10.4.

10.7.3 When the area of the cut part is insufficient to provide completely a continuous flat felt surface under the 28.66-mm (1.129-in.) diameter presser foot, adjust the weight of the freely acting total dead weight made to provide a constant loading of $4300 \pm 215 \text{ Pa}$ ($10 \pm 0.5 \text{ ozf/in.}^2$) on the individual cut felt part (see Table 1). Proceed to measure the individual cut part thickness as directed in 10.4, except take only a single reading.

10.8 *Calculation and Report for Cut Parts*:

10.8.1 Use an Allowable Quality Level (AQL) of 4.0 for all felt whose classification is listed in Table 1 of Specification D 2475.

10.8.2 Also use the appropriate cut part thickness tolerances

TABLE 1 Load Adjustments for Cut Part Thickness

Area Under Presser Foot		Required Loading on Felt	
in. ²	mm ²	ozf	N
0.000 to 0.200	0 to 130	2.00 ± 0.10	0.556
0.201 to 0.300	130 to 194	3.00 ± 0.15	0.834
0.301 to 0.400	195 to 258	4.00 ± 0.20	1.112
0.401 to 0.500	259 to 323	5.00 ± 0.25	1.390
0.501 to 0.600	324 to 387	6.00 ± 0.30	1.668
0.601 to 0.700	388 to 452	7.00 ± 0.35	1.946
0.701 to 0.800	453 to 516	8.00 ± 0.40	2.224
0.801 to 0.900	517 to 580	9.00 ± 0.45	2.502
0.901 to 1.000	581 to 645	10.00 ± 0.50	2.780

as listed in Table 1 for Specification D 2475 under cut felt part tolerances.

10.8.3 Determine if the lot is acceptable or rejectable from the appropriate table in MIL-STD-105D under Normal Inspection, General Inspection Level II, Multiple Sampling Plan for Normal Inspection.

10.8.4 State that the specimens were tested as directed in Section 10 of ASTM Test Methods D 461 and in the Sampling Procedures and Tables for Inspection by Attributes, MIL-STD-105D. Describe the material or product sampled and the method of sampling used.

10.8.5 Report that the lot is either accepted or rejected on the basis of observed thickness and applicable thickness tolerances.

10.9 *Precision and Bias for Cut Parts*—The acceptance or rejection of a lot for the thickness of cut parts is an attribute, and the usual statements on precision and bias do not apply.

11. Weight per Unit Area

11.1 *Significance and Use*—This test is used to determine if the felt meets specifications for weight per unit area.

11.2 *Test Specimens*—Cut rectangular specimens of not less than 250 cm² (40 in.²) from the three sampling areas described in Section 6.

11.3 *Procedure*—Weigh each conditioned specimen separately in grams or ounces to the nearest 0.1 % of its weight.

11.4 *Calculation*—Calculate the weight of each specimen in ounces per square yard using Eq 1.

$$\begin{aligned} \text{Weight, oz/yd}^2 &= \frac{\text{weight of specimen in g} \times 45.72}{\text{length of specimen in in.} \times \text{width in in.}} \\ &= \frac{\text{oz/yd}^2 \times 33.9}{\text{g/m}^2} \end{aligned} \quad (1)$$

11.5 Report:

11.5.1 State that the specimens were tested as directed in Section 11 of ASTM Test Methods D 461. Describe the material or product sampled and the method of sampling used.

11.5.2 Report the average weight of the three specimens tested to the nearest 3 g (0.1 oz).

11.6 Precision and Bias:

11.6.1 *Precision*—The precision of the test method for weight per unit area is being established.

11.6.2 *Bias*—See 5.2.

12. Tensile Strength, “Breaking Load,” and “Specific Strength”

12.1 *Scope*—The same procedure is used for both properties, but the results are calculated and reported in two different

ways: first as breaking load expressed as N (lbf)/2 in. width of specimen, and second as specific strength (Note 3) expressed as pounds-force per square inch of cross section of the original specimen.

NOTE 3—In the table in Specification D 2475, specific strength is referred to as “tensile strength, psi.”

12.2 *Significance and Use*—Strength is a measure of the ability of the felt to withstand tensile stresses in handling and in use. Strength and elongation are frequently related to the felt density, fiber quality, and fiber length. Strength measurements may also serve as a measure of the degree of felting.

12.3 *Apparatus—Tensile Testing Machine*, conforming to Specification D 76 CRT, CRE, and CRL type.

12.4 *Test Specimens*—Cut two specimens 50 by 150 mm (2 by 6 in.) from the center and from both sides of sampling areas described in Section 6 with the long dimension parallel to the length of the piece. Cut two specimens of the same size from each of the three areas with the long dimension crosswise of the piece.

12.5 Procedure:

12.5.1 Adjust the testing machine, if necessary, so that the breaking load will be between 20 and 90 % of its scale capacity. Use clamps having jaws not less than 64 mm (2.5 in.) in width. Set the speed of the pulling clamp at 305 mm ± 10 mm (12 ± ½ in.)/min in the CRE and CRT-type machine. Adjust the CRL-type testing machine so that the time-to-break is within 90 % of the machine’s rated time to full-load. Set the distance between the clamps at the start of the test at 75 ± 1 mm (3 ± 0.05 in.). Insert the conditioned specimen in the central part of the clamps with approximately the same length of fabric extending beyond the jaws at each end. Activate the testing machine and apply an increasing load to the specimen until it breaks. Record the indicated load to the nearest 0.44 N (0.1 lbf).

12.5.2 Test the remaining specimens as directed in 12.5.1.

12.5.3 Determine the thickness of each specimen as directed in Section 10.

12.6 Calculation:

12.6.1 Calculate the average thickness of all the specimens.

12.6.2 Calculate the “specific strength” using Eq 2 or Eq 3.

$$\text{Specific strength, kgf/cm}^2 = B/5T \quad (2)$$

where:

B = average breaking load (strength) in N/5 cm width of test specimen, and

T = average thickness of test specimen, cm.

$$\text{Specific strength, psi} = B/2T \quad (3)$$

where:

B = average breaking load (strength) in lbf/2 in. width of test specimen, and

T = average thickness of test specimen, in.

12.7 Report:

12.7.1 State that all specimens were tested as directed in Section 12 of ASTM Test Methods D 461. Describe the material or product sampled and the method of sampling used.

12.7.2 Report the “breaking load” and the “specific