



Designation: D 4687 – 95

Standard Guide for General Planning of Waste Sampling¹

This standard is issued under the fixed designation D 4687; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ε) indicates an editorial change since the last revision or reapproval.

INTRODUCTION

The analysis and testing of solid waste requires collection of adequately sized, representative samples. Wastes are found in various locations and physical states. Therefore, each sampling routine must be tailored to fit the waste and situation. Wastes often occur as nonhomogeneous mixtures in stratified layers or as poorly mixed conglomerations. For example, wastes are commonly stored or disposed of in surface impoundments with stratified or layered sludges covered by ponded wastewater. In these situations, the collector may be faced with sampling the wastewater, the sludge, and some depth of soil beneath the sludges. Collecting representative samples in these situations requires a carefully assessed, well-planned, and well-executed sampling routine.

Currently, Subcommittee D34.01 is working on practices for sampling wastes from a variety of different sampling locations and situations. Also in progress is a practice for containerization, preservation, and holding times for waste samples. As these documents are approved by ASTM, reference to these standards will be made in this general guide on waste sampling. Further, Subcommittee D34.01 recommends this guide be used in conjunction with the new waste sampling practices when available in print by ASTM.

1. Scope

1.1 This guide provides information for formulating and planning the many aspects of waste sampling (see 1.2) which are common to most waste sampling situations.

1.2 The aspects of sampling which this guide addresses are as follows:

	Section
Safety plans	4
Sampling plans	5
Quality assurance considerations	6
General sampling considerations	7
Preservation and containerization	8
Cleaning equipment	9
Labeling and shipping procedures	10
Chain-of-custody procedure	11

1.3 This guide does not provide comprehensive sampling procedures for these aspects, nor does it serve as a guide to any specific application. It is the responsibility of the user to assure that the procedures used are proper and adequate.

1.4 *This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.* For more specific precautionary statements see 3.2, 3.3, and Section 4.

¹ This guide is under the jurisdiction of ASTM Committee D34 on Waste Management and is the direct responsibility of Subcommittee D34.01.01 on Planning for Sampling.

Current edition approved March 15, 1995. Published May 1995. Originally published as D 4687 – 87. Last previous edition D 4687 – 87.

2. Referenced Documents

2.1 ASTM Standards:

E 122 Practice for Choice of Sample Size to Estimate a Measure of Quality for a Lot or Process²

2.2 Other Document:

EPA-SW-846 Test Methods for Evaluating Solid Waste, Physical/Chemical Methods³

3. Significance and Use

3.1 The procedures covered in this guide are general and provide the user with information helpful for writing sampling plans, safety plans, labeling and shipping procedures, chain-of-custody procedures, general sampling procedures, general cleaning procedures, and general preservation procedures.

3.2 For purposes of this guide, it is assumed that the user has knowledge of the waste being sampled and the possible safety hazards.

3.3 This guide is not to be used when sampling sites or wastes where safety hazards are unknown. In such cases, the user must use other more appropriate procedures.

4. Hazards

4.1 Proper safety precautions must always be observed when sampling wastes. Persons collecting samples must be

² *Annual Book of ASTM Standards*, Vol 14.02.

³ Available from Superintendent of Documents, U.S. Printing Office, Washington, DC 20402.

aware that the waste can be a strong sensitizer and can be corrosive, flammable, explosive, toxic, and capable of releasing extremely poisonous gases. The background information obtained about the waste should be helpful in deciding the extent of safety precautions to be observed and in choosing protective equipment to be used. The information obtained should be checked for hazardous properties against such references as “Dangerous Properties of Industrial Materials” the “March Index,” the “Condensed Chemical Dictionary,” and the “Toxic and Hazardous Industrial Chemicals Safety Manual for Handling and Disposal with Toxicity and Hazardous Data.”

NOTE 1—The following safety precautions are not comprehensive. Rather, they provide additional guidance on health and safety to complement professional judgment and experience.

4.2 Personnel should wear protective equipment when response activities involve known or suspected atmospheric contamination; when vapors, gases, or airborne particulates may be generated; or when direct contact with skin-affecting substances may occur. Respirators can protect lungs, gastrointestinal tract, and eyes against air toxicants. Chemical-resistant clothing can protect the skin from contact with skin-destructive and -absorbable chemicals. Good personal hygiene limits or prevents ingestion of material.

4.2.1 Equipment to protect the body against contact with known or anticipated chemical hazards has been divided into four categories according to the degree of protection afforded:

4.2.1.1 *Level A*—Should be worn when the highest level of respiratory, skin, and eye protection is needed.

4.2.1.2 *Level B*—Should be selected when the highest level of respiratory protection is needed, but a lesser level of skin protection. Level B protection is the minimum level recommended on initial site entries until the hazards have been further defined by on-site studies and appropriate personnel protection utilized.

4.2.1.3 *Level C*—Should be selected when the type(s) of airborne substance(s) is (are) known, the concentrations(s) is measured, and the criteria for using air-purifying respirators are met.

4.2.1.4 *Level D*—Should not be worn on any site with respiratory or skin hazards. It is primarily a work uniform providing minimal protection.

4.2.2 The level of Protection selected should be based primarily on the following:

4.2.2.1 Type(s) and measured concentration(s) of the chemical substance(s) in the ambient atmosphere and its toxicity and

4.2.2.2 Potential or measured exposure to substances in air, splashes of liquids, or other direct contact with material due to work being performed.

4.2.2.3 In situations where the type(s) of chemical(s), concentration(s), and possibilities of contact are not known, the appropriate Level of Protection must be selected based on professional experience and judgment until the hazards can be better characterized.

4.2.3 *Level A Protection—Personnel Protective Equipment:*

(a) (a) Pressure-demand, self-contained breathing apparatus, approved by the Mine Safety and Health Administration (MSHA) and National Institute of Occupational Safety and Health (NIOSH),

- (b) (b) Fully encapsulating chemical-resistant suit,
- (c) (c) Coveralls,⁴
- (d) (d) Long cotton underwear,⁴
- (e) (e) Gloves (outer), chemical-resistant,
- (f) (f) Gloves (inner), chemical-resistant,
- (g) (g) Boots, chemical-resistant, steel toe and shank. (Depending on suit construction, worn over or under suit boot),
- (h) (h) Hard hat⁴ (under suit),
- (i) (i) Disposable protective suit, gloves, and boots⁴ (worn over fully encapsulating suit), and
- (j) (j) Two-way radio communications (intrinsically safe).

4.2.3.1 The fully encapsulating suit provides the highest degree of protection to skin, eyes, and respiratory system if the suit material is resistant to the chemical(s) of concern during the time the suit is worn or at the measured or anticipated concentrations, or both. While Level A provides maximum protection, the suit material may be rapidly permeated and penetrated by certain chemicals from extremely high air concentrations, splashes, or immersion of boots or gloves in concentrated liquids or sludges. These limitations should be recognized when specifying the type of chemical-resistant garment. Whenever possible, the suit material should be matched with the substance it is used to protect against.

4.2.3.2 Many toxic substances are difficult to detect or measure in the field. When such substances (especially those readily absorbed by or destructive to the skin) are known or suspected to be present and personnel contact is unavoidable, Level A protection should be worn until more accurate information can be obtained.

4.2.4 *Level B Protection—Personnel Protective Equipment:*

- (a) (a) Pressure-demand, self-contained breathing apparatus (MSHA/NIOSH approved),
- (b) (b) Chemical-resistant clothing (coveralls and long-sleeved jacket; coveralls; hooded, one- or two-piece chemical-splash suit; disposable chemical-resistant coveralls),
- (c) (c) Coveralls,⁴
- (d) (d) Gloves (outer), chemical-resistant,
- (e) (e) Gloves (inner), chemical-resistant,
- (f) (f) Boots, chemical-resistant, steel toe and shank,
- (g) (g) Boots (outer), chemical-resistant (disposable, worn over permanent boots),⁴
- (h) (h) Hard hat (face shield),⁴ and
- (i) (i) Two-way radio communications (intrinsically safe).

4.2.4.1 Level B equipment provides a high level of protection to the respiratory tract, but a somewhat lower level of protection to skin. The chemical-resistant clothing required in Level B is available in a wide variety of styles, materials, construction detail, permeability, etc. These factors all affect the degree of protection afforded. Therefore, a specialist should select the most effective chemical-resistant clothing (and fully encapsulating suit) based on the known or anticipated hazards or job function, or both.

4.2.4.2 For initial site entry and reconnaissance at an open

⁴ Equipment is optional.

site, approaching whenever possible from the upwind direction, Level B protection (with good quality, hooded, chemical-resistant clothing) should protect response personnel, providing the conditions described in selecting Level A are known or judged to be absent.

4.2.5 Level C Protection—Personnel Protective Equipment:

(a) (a) Full-face, air purifying, canister-equipped respirator (MSHA/NIOSH approved),

(b) (b) Chemical-resistant clothing (coveralls; hooded, two-piece chemical splash suit; chemical-resistant hood and apron; disposable chemical-resistant coveralls),

(c) (c) Coveralls,⁴

(d) (d) Gloves (outer), chemical-resistant,

(e) (e) Gloves (inner), chemical-resistant,⁴

(f) (f) Boots, chemical resistant, steel toe and shank,

(g) (g) Boots (outer), chemical-resistant (disposable, worn over permanent boots),⁴

(h) (h) Hard hat (face shield),⁴

(i) (i) Escape mask⁴, and

(j) (j) Two-way radio communications (intrinsically safe).

4.2.5.1 Level C protection is distinguished from Level B by the equipment used to protect the respiratory system, assuming the same type of chemical-resistant clothing is used. The main selection criterion for Level C is that conditions permit wearing air-purifying devices.

4.2.5.2 Total unidentified vapor/gas concentrations of 5 ppm above background require Level B protection. Only a qualified individual should select Level C (air-purifying respirators) protection for continual use in an unidentified vapor/gas concentration of background to 5 ppm above background.

4.2.6 Level D Protection—Personnel Protective Equipment:

(a) (a) Coveralls,

(b) (b) Gloves,⁴

(c) (c) Boots/shoes, leather or chemical-resistant, steel toe and shank,

(d) (d) Boots, chemical-resistant (disposable worn over permanent boots),⁴

(e) (e) Safety glasses or chemical splash goggles,⁴

(f) (f) Hard hat (face shield),⁴ and

(g) (g) Escape mask.⁴

4.2.6.1 Level D protection is primarily a work uniform. It should be worn in areas where: (1) only boots can be contaminated, or (2) there are no inhalable toxic substances.

4.3 Personnel should not eat, drink, or smoke during or after sampling until after decontamination steps are taken. Sampling personnel should be trained in safety aspects of hazardous waste sampling.

4.4 Testing air emission for determining the vapor/gas concentrations can be accomplished through the use of a portable organic vapor analyzer. The probe should be held 1 to 2 in. above the sampling point. Follow manufacturers operating instructions for proper calibration, use, and care.

5. Sampling Plans

5.1 A sampling plan is a scheme or design to locate sampling points so that suitable representative samples descriptive of the waste body can be obtained. Development of sampling plans requires the following:

5.1.1 Review of background information about the waste and site.

5.1.2 Knowledge of the waste location and situation.

5.1.3 Decisions as to the types of samples needed.

5.1.4 Decisions as to the sampling design required.

5.2 Background data on the waste is extremely helpful in preassessment of the waste's composition, hazards, and extent. (See Notes 2 and 3.)

NOTE 2—If after researching the available background information the user cannot obtain from the material enough information about the waste to determine the probable composition and probable hazards, then the user should use other procedures. Such situations are beyond the scope of this guide.

NOTE 3—The background information is needed to determine necessary safety equipment, safety procedures, sampling equipment and sampling design, and procedures to be used.

5.2.1 Possible sources of information on the site and waste include the following:

5.2.1.1 File searches of state and local records including waste manifests, waste approvals, land permit applications.

5.2.1.2 File searches of generator records (if the generator can be identified) including chemical analyses, safety data sheets, design drawings, and manufacturing process information.

5.2.1.3 File searches of treatment, storage, disposal, and transport facilities. Records involved with handling the waste.

5.2.1.4 Researching published data concerning the site such as scientific journal articles, EPA publications, and newspaper stories. Newspapers are the most likely source but the information is seldom very technical.

5.2.1.5 Interviews of key people such as past and present employees of the site or generator, state and local officials, residents of the area, etc.

5.2.1.6 Aerial photographs provide a historical record of the site development. Many federal agencies conduct aerial surveys that are available to the public. Some of these agencies include the following:

(a) (a) U. S. Department of Agriculture

(b) (b) Soil Conservation Service (USDA-SCS).

(c) (c) U. S. Geological Survey.

(d) (d) U. S. Forest Service.

(e) (e) National Air and Space Administration (NASA).

(f) (f) National Oceanic and Atmospheric Administration (NOAA).

(g) (g) National Weather Service.

(h) (h) Corps of Engineers.

(i) (i) Agricultural Stabilization and Conservation Service.

5.2.1.7 Published maps can also provide a historical record of the site development such as topographic, soil, and county maps.

5.3 Waste location and site conditions greatly influence a sampling plan. The most common waste locations may include lagoons, landfills, pipes, point discharges, piles, drums, bins, tanks, and trucks. The site conditions include the physical condition of the waste; that is, whether it is a solid (granular, consolidated, or cohesive), liquid (slurry or flowable sludge), or gas, and it describes under what conditions it was disposed; that is, does it exist as a multiphased waste in a lagoon, tank or drum; is it stratified solids in a lagoon; is it purely liquid