

Glossary of

Terms used in non-destructive testing —

Part 1: Penetrant flaw detection

UDC 001.4:620.179.111

NO COPYING WITHOUT BSI PERMISSION EXCEPT AS PERMITTED BY COPYRIGHT LAW

BSI
Documents

AVA

Document Sharing Hub

Committees responsible for this British Standard

The preparation of this British Standard was entrusted by the General Mechanical Engineering Standards Committee (GME/-) to Technical Committee GME/23, upon which the following bodies were represented:

- Aluminium Federation
- Associated Offices Technical Committee
- BNF Metals Technology Centre
- British Airways
- British Chemical Engineering Contractors' Association
- British Electrical and Allied Manufacturers' Association (BEAMA)
- British Institute of Non-destructive Testing
- British Non-Ferrous Metals Federation
- British Steel Industry
- Department of Trade and Industry (National Engineering Laboratory)
- Electricity Supply Industry in England and Wales
- Engineering Equipment and Materials Users' Association
- Health and Safety Executive
- Institute of Quality Assurance
- Institution of Production Engineers
- Ministry of Defence
- National Coal Board
- Non-destructive Testing Centre
- Society of British Aerospace Companies Limited
- Society of Motor Manufacturers and Traders Limited
- Steel Castings Research and Trade Association
- United Kingdom Atomic Energy Authority
- Water-tube Boilermakers' Association
- Welding Institute
- Coopted members

This British Standard, having been prepared under the direction of the General Mechanical Engineering Standards Committee, was published under the authority of the Board of BSI and comes into effect on 31 May 1985

© BSI 07-1999

First published December 1963
First revision May 1985

The following BSI references relate to the work on this standard:
Committee reference GME/23
Draft for comment 84/72549 DC

ISBN 0 580 14465 8

Amendments issued since publication

Amd. No.	Date of issue	Comments

Contents

	Page
Committees responsible	Inside front cover
Foreword	ii
Glossary	1
Publications referred to	Inside back cover