

BS ISO 1143:2010



BSI Standards Publication

Metallic materials — Rotating bar bending fatigue testing

bsi.

...making excellence a habit.
AVA Documents™
Document Sharing Hub

National foreword

This British Standard is the UK implementation of ISO 1143:2010. It supersedes BS 3518-2:1962 which is withdrawn.

The UK participation in its preparation was entrusted to Technical Committee ISE/101/6, Fatigue testing of metals and metal matrix composites.

A list of organizations represented on this committee can be obtained on request to its secretary.

This publication does not purport to include all the necessary provisions of a contract. Users are responsible for its correct application.

© BSI 2010

ISBN 978 0 580 53936 7

ICS 77.040.10

Compliance with a British Standard cannot confer immunity from legal obligations.

This British Standard was published under the authority of the Standards Policy and Strategy Committee on 31 December 2010.

Amendments issued since publication

Date	Text affected
------	---------------

INTERNATIONAL STANDARD

BS ISO 1143:2010

ISO
1143

Second edition
2010-11-01

Metallic materials — Rotating bar bending fatigue testing

*Matériaux métalliques — Essais de fatigue par flexion rotative de
barreaux*



Reference number
ISO 1143:2010(E)

AVA Documents
Document Sharing Hub
© ISO 2010

PDF disclaimer

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below.



COPYRIGHT PROTECTED DOCUMENT

© ISO 2010

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents

Page

Foreword	iv
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols and designations	2
5 Principle of test.....	2
6 Shape and size of specimen	3
6.1 Forms of the test section.....	3
6.2 Dimensions of specimens	3
7 Preparation of specimens.....	4
7.1 General	4
7.2 Selection of the specimen	4
7.3 Machining procedure	4
7.4 Sampling and marking	5
7.5 Storage and handling.....	6
8 Accuracy of the testing apparatus	6
9 Heating device and temperature measurement	6
10 Test procedure.....	6
10.1 Mounting the specimen	6
10.2 Application of force.....	7
10.3 Frequency selection.....	8
10.4 End of test	8
10.5 Procedure for testing at elevated temperature	8
10.6 Construction of the $S-N$ diagram.....	9
11 Presentation of fatigue test results	9
11.1 Tabular presentation.....	9
11.2 Graphical presentation	10
12 Test report.....	10
Annex A (normative) Verification of the bending moment of rotating bar bending fatigue machines	17
Bibliography.....	26

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

International Standards are drafted in accordance with the rules given in the ISO/IEC Directives, Part 2.

The main task of technical committees is to prepare International Standards. Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights.

ISO 1143 was prepared by Technical Committee ISO/TC 164, *Mechanical testing of metals*, Subcommittee SC 5, *Fatigue testing*.

This second edition cancels and replaces the first edition (ISO 1143:1975), which has been technically revised.

Metallic materials — Rotating bar bending fatigue testing

1 Scope

This International Standard specifies the method for rotating bar bending fatigue testing of metallic materials. The tests are conducted at room temperature or elevated temperature in air, the specimen being rotated.

2 Normative references

The following referenced documents are indispensable for the application of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 376, *Metallic materials — Calibration of force-proving instruments used for the verification of uniaxial testing machines*

ISO 1099, *Metallic materials — Fatigue testing — Axial force-controlled method*

ISO 12106, *Metallic materials — Fatigue testing — Axial-strain-controlled method*

ISO 12107, *Metallic materials — Fatigue testing — Statistical planning and analysis of data*

ISO 23718, *Metallic materials — Mechanical testing — Vocabulary*

3 Terms and definitions

For the purposes of this document, the terms and definitions given in ISO 1099, ISO 12106, ISO 12107, ISO 23718 and the following apply.

3.1

fatigue

process of changes in properties which can occur in a metallic material due to the repeated application of stresses or strains and which can lead to cracking or failure

3.2

fatigue life

N_f

number of cycles of a specified character that a given specimen sustains before failure of a specified nature occurs

3.3

***S-N* diagram**

diagram that shows the relationship between stress and fatigue life

3.4

bending moment

M

multiplication between force and force arm length

3.5 section modulus

W

ratio of the moment of inertia of the cross-section of a beam undergoing flexure to the greatest distance of an element of the beam from the neutral axis

3.6 machine lever ratio

M_{lr}

ratio between the force applied to the weight hangar and the force applied to the specimen

3.7 force arm length

L

distance between the supporting point and the loading point

See Figures 1 to 7.

NOTE L_1 should equal L_2 for the four-point loading condition.

3.8 endurance stress limit

fatigue limit

cyclic stress range applied to specimens that do not fail upon application of a given number of cycles

NOTE 1 The cycle number limit selected, e.g. 10^7 or 10^8 cycles, shall be specified along with the stress range.

NOTE 2 For a specified fatigue life, “endurance stress limit” has been supplanted by “fatigue limit” as the preferred term.

4 Symbols and designations

Symbols and corresponding designations are given in Table 1, or elsewhere in this International Standard where they appear.

Table 1 — Symbols and designations

Symbol	Designation	Unit
D	Diameter of gripped or loaded end of specimen	mm
d	Diameter of specimen where stress is maximum	mm
N_f	Fatigue life, cycles to failure	cycle
r	Radius at ends of test section which starts transition from test diameter, d	mm

5 Principle of test

Nominally identical specimens are used, each being rotated and subjected to a bending moment. The forces giving rise to the bending moment do not rotate. The specimen may be mounted as a cantilever, with single-point or two-point loading, or as a beam, with four-point loading. The test is continued until the specimen fails or until a pre-determined number of stress cycles have been achieved.

6 Shape and size of specimen

6.1 Forms of the test section

The test section may be

- a) cylindrical, with tangentially blending fillets at one or both ends (see Figures 1, 4 and 5),
- b) tapered (see Figure 2), or
- c) hourglass-type (see Figures 3, 6 and 7).

In each case, the test section shall be of circular cross-section.

The form of test section may be dependent on the type of loading to be employed. While cylindrical or hourglass-type specimens may be loaded as beams, or as cantilevers with either single-point or double-point loading, the tapered form of specimen is used only as a cantilever with single-point loading. Figures 1 to 7 show, in schematic form, the bending moment and nominal stress diagrams for the various practical cases.

The volumes of material subjected to greatest stresses are not the same for different forms of specimen, and they may not necessarily give identical results. The test in which the largest volume of material is highly stressed is preferred.

Experience has shown that a ratio of at least 3:1 between the cross-sectional areas of the test portion and the gripping regions of the specimen is desirable.

In tests on certain materials, a combination of high stress and high speed may cause excessive hysteresis heating of the specimen. This effect may be reduced by subjecting a smaller volume of the material to the specified stress. If the specimen is cooled, the test medium should be reported.

6.2 Dimensions of specimens

All the specimens employed in a test series for a fatigue-life determination shall have the same size, shape and tolerance of diameter.

For the purpose of calculating the force to be applied to obtain the required stress, the actual minimum diameter of each specimen shall be measured to an accuracy of 0,01 mm. Care shall be taken during the measurement of the specimen prior to testing to ensure that the surface is not damaged.

On cylindrical specimens subject to constant bending moment (see Figures 4 and 5), the parallel test section shall be parallel within 0,025 mm. For other forms of cylindrical specimen (see Figure 1), the parallel test section shall be parallel within 0,05 mm. For material property determination, the transition fillets at the ends of the test section should have a radius not less than $3d$. For hourglass-type specimens, the section formed by the continuous radius should have a radius not less than $5d$.

Figure 8 shows the shape and dimensions of a typical cylindrical specimen. The recommended values of d are 6 mm, 7,5 mm and 9,5 mm. The tolerance of diameter should be $\leq 0,005d$. Figure 9 shows a typical hourglass specimen suitable for fatigue testing at elevated temperature.

Fatigue tests on notched specimens are not covered by this International Standard, since the shape and size of notched specimens have not been standardized. However, fatigue test procedures described in this International Standard may be applied to fatigue tests of notched specimens.

7 Preparation of specimens

7.1 General

In any rotating bar bending fatigue test programme designed to characterize the intrinsic properties of a material, it is important to observe the following recommendations in the preparation of specimens. A possible reason for deviation from these recommendations is if the test programme aims to determine the influence of a specific factor (surface treatment, oxidation, etc.) that is incompatible with the recommendations. In all cases, any deviation shall be noted in the test report.

7.2 Selection of the specimen

The location, orientation and type of specimen shall be taken from the related product standard, or by agreement with the customer.

The sampling of test materials from a semi-finished product or a component may have a major influence on the results obtained during the test. It is therefore necessary for this sampling to be recorded and a sampling drawing be prepared. This shall form part of the test report and shall indicate clearly

- the position of each of the specimens removed from the semi-finished product or component,
- the characteristic directions in which the semi-finished product has been worked (direction of rolling, extrusion, etc., as appropriate), and
- the unique identification of each of the specimens.

The unique mark or identification of each specimen shall be maintained at each stage of its preparation. This may be applied using any reliable method in an area not likely to disappear during machining or likely to adversely affect the quality of the test. Upon completion of the machining process, it is desirable for both ends of each specimen to be uniquely marked so that, after failure of a specimen, each half can still be identified.

7.3 Machining procedure

7.3.1 Heat treatment of test material

If heat treatment is to be carried out after rough finishing of the specimens, it is preferable that the final polishing be carried out after the heat treatment. If that is not possible, the heat treatment should be carried out in a vacuum or in inert gas to prevent oxidation of the specimen. Stress relief is recommended in this case. This treatment shall not alter the micro-structural characteristic of the material under study. The specifics of the heat treatment and machining procedure shall be reported with the test results.

7.3.2 Machining criteria

The machining procedure selected may produce residual stresses on the specimen surface likely to affect the test results. These stresses may be induced by heat gradients at the machining stage or they may be associated with deformation of the material or micro-structural alterations. Their influence is less marked in tests at elevated temperatures because they are partially or totally relaxed once the temperature is attained. However, they should be reduced by using an appropriate final machining procedure, especially prior to a final polishing stage. For harder materials, grinding rather than turning or milling may be preferred.

- Grinding: from 0,1 mm above the final diameter, at a rate of no more than 0,005 mm/pass.
- Polishing: remove the final 0,025 mm with abrasives of decreasing grit size. The final direction of polishing shall be along the test specimen axis.

The phenomenon of alteration in the microstructure of the material may be caused by the increase in temperature and by the strain hardening induced by machining. It may be a matter of a change in phase or,

more frequently, of surface re-crystallization. The immediate effect of this is to make the test specimen no longer representative of the initial material. Hence, every precaution should therefore be taken to avoid this risk.

Contaminants can be introduced when the mechanical properties of certain materials deteriorate in the presence of certain elements or compounds. An example of this is the effect of chlorine on steels and titanium alloys. These elements should therefore be avoided in the products used (cutting fluids, etc.). Rinsing and degreasing of specimens prior to storage is also recommended.

7.3.3 Inspection of specimens

The surface condition of specimens has an effect on the test results. This effect is generally associated with one or more of the following factors:

- the specimen surface roughness;
- the presence of residual stresses;
- alteration in the microstructure of the material;
- the introduction of contaminants.

The recommendations below allow the influence of these factors to be reduced to a minimum.

The surface condition is commonly quantified by the mean roughness or equivalent (e.g. 10 point roughness or maximum height of irregularities). The importance of this variable on the results obtained depends largely on the test conditions, and its influence is reduced by surface corrosion of the specimen or plastic deformation.

It is preferable, whatever the test conditions, to specify a mean surface roughness, R_z , of less than 0,2 μm (or equivalent).

Another important parameter not covered by mean roughness is the presence of localized machining scratches. A low-magnification check (at approximately $\times 20$) shall not show any circumferential scratches or abnormalities.

7.3.4 Dimensional checks

The diameter shall be measured on each specimen. In the case of specimens with a parallel gauge length, the diameter shall be measured at a minimum of three positions along the gauge length. The measurement shall be performed using a method that does not damage the specimen.

7.4 Sampling and marking

The sampling of test materials from a semi-finished product or a component may have a major influence on the results obtained during the test. It is therefore necessary for this sampling to be recorded and a sampling drawing to be prepared. This shall form part of the test report and shall indicate clearly

- the position of each of the specimens removed from the semi-finished product or component,
- the characteristic directions in which the semi-finished product has been worked (direction of rolling, extrusion, etc., as appropriate), and
- the unique identification of each of the specimens.

The unique mark or identification of each specimen shall be maintained at each stage of their preparation. This may be applied using any reliable method in an area not likely to disappear during machining or likely to adversely affect the quality of the test. Upon completion of the machining process, it is desirable for both ends of each specimen to be uniquely marked so that, after failure of a specimen, each half can still be identified.