



BSI Standards Publication

Plain bearings — Wrapped bushes

Part 7: Measurement of wall thickness of thin-walled bushes

National foreword

This British Standard is the UK implementation of ISO 3547-7:2020. It supersedes BS ISO 3547-7:2007, which is withdrawn.

The UK participation in its preparation was entrusted to Technical Committee MCE/12, Plain bearings.

A list of organizations represented on this committee can be obtained on request to its secretary.

This publication does not purport to include all the necessary provisions of a contract. Users are responsible for its correct application.

© The British Standards Institution 2020

Published by BSI Standards Limited 2020

ISBN 978 0 539 00743 5

ICS 21.100.10

Compliance with a British Standard cannot confer immunity from legal obligations.

This British Standard was published under the authority of the Standards Policy and Strategy Committee on 31 May 2020.

Amendments/corrigenda issued since publication

Date	Text affected
------	---------------

**Plain bearings — Wrapped bushes —
Part 7:
Measurement of wall thickness of
thin-walled bushes**

Paliers lisses — Bagues roulées —

Partie 7: Mesurage de l'épaisseur de paroi des bagues minces





COPYRIGHT PROTECTED DOCUMENT

© ISO 2020

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
CP 401 • Ch. de Blandonnet 8
CH-1214 Vernier, Geneva
Phone: +41 22 749 01 11
Fax: +41 22 749 09 47
Email: copyright@iso.org
Website: www.iso.org

Published in Switzerland

Contents

Page

Foreword	iv
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols and units	2
5 Purpose of checking	2
6 Checking methods	2
6.1 Measuring principle	2
6.2 Line measurement around the circumference	3
6.3 Point measurement	4
7 Requirements for measuring equipment for the contact method	4
7.1 Radius of the measuring pin on the outside surface	4
7.2 Radius of the measuring pin on the inside surface	5
7.3 Measuring pin load	5
8 Checking of measuring equipment	5
Bibliography	6