

X and gamma reference radiation for calibrating dosimeters and doserate meters and for determining their response as a function of photon energy —

Part 4: Calibration of area and personal dosimeters in low energy X reference radiation fields

ICS 17.240

Confirmed July 2008

National foreword

This British Standard reproduces verbatim ISO 4037-4:2004 and implements it as the UK national standard.

The UK participation in its preparation was entrusted to Technical Committee NCE/2, Radiation protection and measurement, which has the responsibility to:

- aid enquirers to understand the text;
- present to the responsible international/European committee any enquiries on the interpretation, or proposals for change, and keep the UK interests informed;
- monitor related international and European developments and promulgate them in the UK.

A list of organizations represented on this committee can be obtained on request to its secretary.

Cross-references

The British Standards which implement international publications referred to in this document may be found in the *BSI Catalogue* under the section entitled “International Standards Correspondence Index”, or by using the “Search” facility of the *BSI Electronic Catalogue* or of British Standards Online.

This publication does not purport to include all the necessary provisions of a contract. Users are responsible for its correct application.

Compliance with a British Standard does not of itself confer immunity from legal obligations.

Summary of pages

This document comprises a front cover, an inside front cover, the ISO title page, pages ii to v, a blank page, pages 1 to 19 and a back cover.

The BSI copyright notice displayed in this document indicates when the document was last issued.

Amendments issued since publication

Amd. No.	Date	Comments

This British Standard was published under the authority of the Standards Policy and Strategy Committee on 18 October 2004

© BSI 18 October 2004

ISBN 0 580 44619 0

INTERNATIONAL STANDARD

ISO
4037-4

First edition
2004-10-15

X and gamma reference radiation for calibrating dosimeters and dose rate meters and for determining their response as a function of photon energy —

Part 4:

Calibration of area and personal dosimeters in low energy X reference radiation fields

*Rayonnements X et gamma de référence pour l'étalonnage des
dosimètres et des débitmètres et pour la détermination de leur réponse
en fonction de l'énergie des photons —*

*Partie 4: Étalonnage des dosimètres de zone (ou d'ambiance) et
individuels dans des champs de référence X de faible énergie*



Reference number
ISO 4037-4:2004(E)

AVA Documents
Document Sharing Hub

Contents

Page

Foreword.....	iv
Introduction	v
1 Scope.....	1
2 Normative references	1
3 Terms and definitions.....	2
4 Symbols (and abbreviated terms)	2
5 General procedures for calibrating and determining response.....	4
6 Characterisation and production of low energy X-ray reference radiations	4
6.1 General	4
6.2 Tube potential.....	4
6.3 Field uniformity and scattered radiation	5
6.4 Spectral fluence and conversion coefficients	5
7 Dosimetry of low energy reference radiations.....	6
7.1 General	6
7.2 Operation of the standard instruments	6
7.2.1 Instruments for the measurement of air kerma	6
7.2.2 Instruments for the measurement of the dose-equivalent quantities defined in ICRU 51	6
8 Calibration and determination of the response as a function of photon energy and angle of radiation incidence	6
8.1 General	6
8.2 Selection of calibration method	7
8.3 Calibration by using reference instruments for K_a	7
8.3.1 General	7
8.3.2 Conventionally true value of the measurand air kerma	7
8.3.3 Conventionally true value of the measurands dose-equivalent quantities $H_p(0,07)$ and $H'(0,07)$	8
8.3.4 Conventionally true value of the measurands dose-equivalent quantities $H_p(10)$ and $H^*(10)$	8
8.3.5 Performing the calibration	10
8.4 Calibration by using reference instruments which measure the ICRU dose-equivalent quantities	10
8.4.1 General	10
8.4.2 Conventionally true value of the measurands dose-equivalent quantities $H_p(10)$ and $H^*(10)$	10
8.4.3 Performing the calibration	12
8.5 Statement of uncertainty	12
Annex A (normative) Correction for air density	13
Annex B (informative) Measurement of pulse height spectra.....	17
Bibliography	19

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

International Standards are drafted in accordance with the rules given in the ISO/IEC Directives, Part 2.

The main task of technical committees is to prepare International Standards. Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights.

ISO 4037-4 was prepared by Technical Committee ISO/TC 85, *Nuclear energy*, Subcommittee SC 2, *Radiation protection*.

ISO 4037 consists of the following parts, under the general title *X and gamma reference radiation for calibrating dosimeters and dose rate meters and for determining their response as a function of photon energy*:

- *Part 1: Radiation characteristics and production methods*
- *Part 2: Dosimetry for radiation protection over the energy ranges from 8 keV to 1,3 MeV and 4 MeV to 9 MeV*
- *Part 3: Calibration of area and personal dosimeters and the measurement of their response as a function of energy and angle of incidence*
- *Part 4: Calibration of area and personal dosimeters in low energy X reference radiation fields*

Introduction

This part of ISO 4037 is closely related to the three other parts of ISO 4037. The first, ISO 4037-1, describes the methods of production and characterisation of the photon reference radiations. The second, ISO 4037-2, describes the dosimetry of the reference radiations and the third, ISO 4037-3, describes procedures for calibrating and determining the response of dosimeters and doserate meters in terms of the International Commission on Radiation Units and Measurements (ICRU) operational quantities [1, 2, 3] for radiation protection purposes.

This part of ISO 4037 is the fourth part of the series, and it describes special procedures for low energy X reference radiation fields. In ISO 4037-3, all the dose quantities used are based on the air kerma K_a free in air. Either K_a is the selected measuring quantity, or one of the dose-equivalent quantities $H'(0,07)$, $H_p(0,07)$, $H_p(10)$ and $H^*(10)$ is determined using conversion coefficients from air kerma K_a to the appropriate dose-equivalent quantity. For the dose-equivalent quantities $H'(0,07)$ and $H_p(0,07)$, this procedure is associated with only a small additional uncertainty, because the conversion coefficients depend only slightly on the photon energy and angle of radiation incidence for the ranges given in ISO 4037-3. Therefore, for these dose-equivalent quantities, no special attention is given for the low energy X reference radiation fields. For the two other dose-equivalent quantities $H_p(10)$, and $H^*(10)$, this is different. For them, the use of conversion coefficients can be associated with large additional uncertainties if low energy X reference radiation fields are considered; see the remark already given in these cases in ISO 4037-3. This is because the conversion coefficients depend strongly on the photon energy and the angle of radiation incidence. For nominally the same radiation quality as defined in ISO 4037-1, the conversion coefficients can differ by several tens of percent. A detailed description of all the measurements and methods necessary to avoid these additional uncertainties is given by Ankerhold *et al.* [4, 5] and by Behrens [6].

NOTE For irradiation of the whole body, $H_p(10)$ and $H^*(10)$ are relevant for radiation protection, as long as they are closer to their limit than $H'(0,07)$ and $H_p(0,07)$. This is the case down to about 15 keV.

X and gamma reference radiation for calibrating dosimeters and dose rate meters and for determining their response as a function of photon energy —

Part 4: Calibration of area and personal dosimeters in low energy X reference radiation fields

1 Scope

This part of ISO 4037 gives guidelines on additional aspects of the characterization of low energy photon radiations. This part of ISO 4037 also describes procedures for calibration and determination of the response of area and personal dose(rate)meters as a function of photon energy and angle of incidence. This part of ISO 4037 concentrates on the accurate determination of conversion coefficients from air kerma to $H_p(10)$ and $H^*(10)$ for the spectra of low energy photon radiations. As an alternative to the use of conversion coefficients, the direct calibration in terms of these quantities by means of appropriate reference instruments is described.

2 Normative references

The following referenced documents are indispensable for the application of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 4037-1:1996, *X and gamma reference radiation for calibrating dosimeters and dose rate meters and for determining their response as a function of photon energy — Part 1: Radiation characteristics and production methods*

ISO 4037-2:1997, *X and gamma reference radiation for calibrating dosimeters and dose rate meters and for determining their response as a function of photon energy — Part 2: Dosimetry for radiation protection over the energy ranges from 8 keV to 1,3 MeV and 4 MeV to 9 MeV*

ISO 4037-3:1999, *X and gamma reference radiation for calibrating dosimeters and dose rate meters and for determining their response as a function of photon energy — Part 3: Calibration of area and personal dosimeters and the measurement of their response as a function of energy and angle of incidence*

BIPM, IEC, IFCC, ISO, IUPAC, IUPAP, OIML, *Guide to the Expression of Uncertainty in Measurement*, 1995

ICRU Report 51:1993, *Quantities and Units in Radiation Protection Dosimetry*, International Commission on Radiation Units and Measurements, Bethesda, Maryland 20814, USA