

CGA V-19 — 2018

1ST EDITION

REAFFIRMED 2024

**MARKING
REQUIREMENTS
TO MITIGATE
POTENTIAL
CYLINDER AND
CYLINDER VALVE
THREAD
MISMATCHES
(FORMERLY TB-16)**



PLEASE NOTE:

The information contained in this document was obtained from sources believed to be reliable and is based on technical information and experience currently available from members of the Compressed Gas Association, Inc. and others. However, the Association or its members, jointly or severally, make no guarantee of the results and assume no liability or responsibility in connection with the information or suggestions herein contained. Moreover, it should not be assumed that every acceptable commodity grade, test or safety procedure or method, precaution, equipment or device is contained within, or that abnormal or unusual circumstances may not warrant or suggest further requirements or additional procedure.

This document is subject to periodic review, and users are cautioned to obtain the latest edition. The Association invites comments and suggestions for consideration. In connection with such review, any such comments or suggestions will be fully reviewed by the Association after giving the party, upon request, a reasonable opportunity to be heard. Proposed changes may be submitted via the Internet at our web site, www.cganet.com.

This document should not be confused with federal, state, provincial, or municipal specifications or regulations; insurance requirements; or national safety codes. While the Association recommends reference to or use of this document by government agencies and others, this document is purely voluntary and not binding.

A listing of all publications, audiovisual programs, safety and technical bulletins, and safety posters is available via the Internet at our website at www.cganet.com. For more information contact CGA at Phone: 703-788-2700, ext. 799. E-mail: customerservice@cganet.com

Work Item 23-044
Cylinder Valve Committee

NOTE—No technical information has been changed from the 2018 edition. This reaffirmed edition may include minor editorial changes.

NOTE—Technical changes from the TB-16—2010 are underlined.

REAFFIRMED: 2024
FIRST EDITION: 2018

© 2018 The Compressed Gas Association, Inc. All rights reserved.

All materials contained in this work are protected by United States and international copyright laws. No part of this work may be reproduced or transmitted in any form or by any means, electronic or mechanical including photocopying, recording, or any information storage and retrieval system without permission in writing from The Compressed Gas Association, Inc. All requests for permission to reproduce material from this work should be directed to The Compressed Gas Association, Inc., 8484 Westpark Drive, Suite 220, McLean, VA 22102. You may not alter or remove any trademark, copyright or other notice from this work.

Contents	Page
1 Introduction.....	1
2 Purpose and scope	1
3 Definitions.....	1
4 Potential valve thread and cylinder thread mismatch.....	2
5 Thread codes	3
6 Potential straight thread O-ring groove configuration mismatch	5
7 References	5
 Figures	
Figure 1—Comparison of NGT and ISO 25E tapered threads.....	2
Figure 2—Illustration of valve threads.....	3
 Tables	
Table 1—Cylinder valve inlet code.....	4
Table 2—Cylinder valve inlet code, selected international inlet specification	4