

Windows and rooflights —

Part 3: Sound insulation

UDC 69.028.2 + 69.024.98]:699.844:534.833.5

NO COPYING WITHOUT BSI PERMISSION EXCEPT AS PERMITTED BY COPYRIGHT LAW

BSI
Documents

AVA

Document Sharing Hub

Foreword

This Code of Practice makes reference to the following British Standard Codes of Practice:

CP 3: Chapter III, *Sound insulation and noise reduction*.

CP 352, *Mechanical ventilation and air conditioning in buildings*.

To avoid unnecessary delay, information collected for the Code is being issued in a series of separate parts covering particular aspects of the work. The final decision on whether to assemble the separate parts of the Code, with any necessary amendments and editing, into one volume to form the complete Code, will be taken later.

This Code of Practice represents a standard of good practice and therefore takes the form of recommendations. Compliance with it does not confer immunity from relevant legal and statutory requirements.

This Part of the Code of Practice has been prepared by a Committee convened by the Codes of Practice Committee for Building on behalf of the Council for Codes of Practice. Having been approved by the Codes of Practice Committee for Building and endorsed by the Council for Codes of Practice, it was published under the authority of the Executive Board on 7 April 1972

© BSI 02-2000

The following BSI references relate to the work on this Code of Practice:
Committee references BLCP/2 and BLCP/2/4
Draft for comment 69/11296

ISBN 0 580 07031 X

Summary of pages

This document comprises a front cover, an inside front cover, pages i to iv, pages 1 to 11 and a back cover.

This standard has been updated (see copyright date) and may have had amendments incorporated. This will be indicated in the amendment table on the inside front cover.

Amendments issued since publication

Amd. No.	Date	Comments

Contents

	Page
Foreword	Inside front cover
Code Drafting Committee BLCP/2	ii
1 General	1
1.1 Scope	1
1.2 Performance and costs	1
1.3 Types of windows	1
2 Measurement of sound	1
2.1 The decibel scale	1
2.2 Loudness	1
2.3 The dB(A) scale	1
3 Control of noise	2
3.1 Transmission of sound	2
3.2 Sound insulation	2
4 The sound insulation performance of windows and rooflights	3
4.1 Effect of openings	3
4.2 Ventilation	3
4.3 Performance categories	3
4.4 Field and laboratory measurements	3
4.5 Design principles	4
4.6 Rooflights	5
4.7 Thermal effects of double windows installed primarily for sound insulation	5
5 Noise levels	5
5.1 External noise climate	5
5.2 Desirable limits for intrusive noise in buildings	6
5.3 Sound insulation requirements	7
5.4 Effects of height of buildings	7
6 The selection of window types and sizes	8
6.1 Effects of building design and siting	8
6.2 Curtain walling	8
6.3 Fixed and openable windows	8
6.4 Use of double windows	9
6.5 Automatically controlled windows	9
7 Sonic booms	9
7.1 Effects on windows	9
Appendix A Further reading	10
Figure 1 — Analysis of traffic noise and window insulation	11
Table 1 — Sound insulation values for closed windows	4
Table 2 — Range of noise levels at locations in which traffic noise predominates	6
Table 3 — Tolerable noise levels (not exceeded for more than 10 % of the time)	7
Table 4 — Effect of window size on the sound insulation of 40 dB and 50 dB external walls	8

Code Drafting committee BLCP/2 windows, doors and frames

Mr. H. E. Beckett (*Chairman*)

Mr. E. Tuite	<i>British Door Association</i>
Mr. J. B. Austin, O.B.E., J.P. (Resigned December 1969)	<i>British Woodwork Manufacturers' Association</i>
*Mr. T. Sibthorp	
*Mr. J. W. Temple	
Mr. G. H. Merrell	<i>Chief Fire Officers' Association</i>
Mr. R. J. Stepney, M.B.E. (Resigned May 1970)	
Mr. A. Wilkinson	<i>City and Borough Architects' Society</i>
*Mr. L. C. Lomas	<i>Country Architects' Society</i>
Mr. J. C. Calderhead	<i>Department of Health and Social Security</i>
*Mr. W. Howard (Resigned May 1969)	<i>Department of the Environment</i>
*Mr. P. B. Whiteley	
Mr. G. H. Wigglesworth	
*Mr. J. A. Godfrey	<i>Department of the Environment Building Research Station</i>
Mr. R. Goodchild (Resigned June 1970)	<i>Department of the Environment Forest Products Research Laboratory</i>
*Mr. N. P. Skinner	
*Mr. J. G. Sunley	
Dr. H. D. Taylor	<i>Fire Protection Association</i>
*Mr. J. E. Bullough (Resigned December 1969)	<i>Flat Glass Manufacturers' Association</i>
*Mr. D. R. Goodall	
*Mr. P. K. Nicoll	<i>Greater London Council</i>
Mr. A. A. Winning	<i>Institution of Fire Engineers</i>
Mr. K. Hewett	<i>Joinery Managers' Association Limited</i>
*Mr. S. R. Armsdon	<i>Metal Window Federation of Great Britain</i>
*Mr. R. G. D. Brown	
*Mr. E. J. Collins	
*Mr. K. R. Peplow (Resigned October 1969)	
*Mr. H. L. Watts (Resigned November 1969)	
Mr. E. Corker	<i>Modular Society</i>
*Mr. H. H. Hayns	<i>Royal Institute of British Architects</i>

The Drafting Sub-committee BLCP/2/4, Windows, consists of the members of BLCP/2 Committee, marked with an asterisk, under the Chairmanship of Mr. H. E. Beckett with the following additional members:

The Secretary		<i>The Agrément Board</i>
Mr. J. E. Douglas		<i>Association of Builders' Hardware Manufacturers</i>
Mr. C. A. Brighton (Resigned May 1970)	}	<i>British Plastics Federation</i>
Dr. H. J. Sharp		
Mr. A. F. Pyne		
Mr. S. K. Finch	}	<i>British Woodwork Manufacturers' Association</i>
Mr. R. Slattery (Resigned December 1969)		
Mr. J. Jobson		<i>Department of the Environment</i>
Miss Margaret Law		<i>Department of the Environment Joint Fire Research Organization</i>
Mr. P. J. Peters (Resigned January 1969)	}	<i>Metal Window Federation of Great Britain</i>
Mr. J. F. R. White		
Mr. S. Leith		<i>Scottish Development Department</i>

