



ASSOCIATION CONNECTING
ELECTRONICS INDUSTRIES

3000 Lakeside Dr.
Bannockburn, IL 60015

IPC-TM-650 TEST METHODS MANUAL

2.4.1E Adhesion, Tape Testing

2.4.1.1B Adhesion, Marking Paints and Inks

2.4.1.2 Adhesion of Conductors on Hybrid Substrates

2.4.1.3 Adhesion, Resistors (Hybrid Circuits)

2.4.1.4 Adhesion, Overglaze (Hybrid Circuits)

2.4.1.5A Determination of Treatment Transfer

2.4.1.6 Adhesion, Polymer Coating

2.4.2A Ductility of Copper Foil

2.4.2.1D Flexural Fatigue and Ductility, Foil

2.4.3D Flexural Fatigue, Flexible Printed Wiring Materials

2.4.3.1C Flexural Fatigue and Ductility, Flexible Printed Wiring

2.4.3.2C Flexural Fatigue and Ductility, Flexible Metal Clad Dielectrics

2.4.4B Flexural Strength of Laminates (at Ambient Temperature)

2.4.4.1A Flexural Strength of Laminates (at Elevated Temperature)

2.4.5 Folding Endurance, Flexible Printed Wiring Materials

2.4.5.1 Flexibility, Conformed Coating

2.4.6 Hot Oil

2.4.7A Machinability, Printed Wiring Materials

2.4.7.1 Solder Mask - Determination of Machineability

2.4.8C Peel Strength of Metallic Clad Laminates

Number 2.4	
Subject Mechanical Test Methods	
Date 10/07	Revision Z
Originating Task Group	

2.4.8.1 Peel Strength, Metal Foil (Keyhole Method for Thin Laminates)

2.4.8.2A Peel Strength of Metallic Clad Laminates at Elevated Temperature (Hot Fluid Method)

2.4.8.3A Peel Strength of Metallic Clad Laminates at Elevated Temperature (Hot Air Method)

2.4.8.4 Carrier Release, Thin Copper

2.4.9D Peel Strength, Flexible Printed Wiring Materials

2.4.9.1 Peel Strength of Flexible Circuits

2.4.9.2 Bonding Process

2.4.11 Shear Strength, Flexible Dielectric Materials

2.4.12A Solderability, Edge Dip Method

2.4.13F Solder Float Resistance Flexible Printed Wiring Materials

2.4.13.1 Thermal Stress of Laminates

2.4.14 Solderability of Metallic Surfaces

2.4.14.1 Solderability, Wave Solder Method

2.4.14.2A Liquid Flux Activity, Wetting Balance Method

2.4.15A Surface Finish, Metal Foil

2.4.16A Initiation Tear Strength, Flexible Insulating Materials

2.4.17 Tear Strength (Propagation)

2.4.17.1A Propagation, Tear Strength, Flexible Insulating Material

2.4.18B Tensile Strength and Elongation, Copper Foil

Material in this Test Methods Manual was voluntarily established by Technical Committees of IPC. This material is advisory only and its use or adaptation is entirely voluntary. IPC disclaims all liability of any kind as to the use, application, or adaptation of this material. Users are also wholly responsible for protecting themselves against all claims or liabilities for patent infringement.

Copyright IPC-Association Connecting Electronics Industries
Provided by IHS under license with IPC
No reproduction or networking permitted without license from IHS

Full document details: IPC TM-650 2.4 2007

Licensee=Sandia National Lab/5932237100, User=sam, albert
Not for Resale, 05/28/2014 10:54:14 MDT



Documents
Page 1 of 3
Document Sharing Hub

IPC-TM-650		
Number 2.4	Subject Mechanical Test Methods	Date 10/07
Revision Z		

2.4.18.1A Tensile Strength and Elongation, In-House Plating

2.4.18.2 Hot Rupture Strength, Foil

2.4.18.3 Tensile Strength, Elongation, and Modulus

2.4.19C Tensile Strength and Elongation, Flexible Printed Wiring Materials

2.4.20 Terminal Bond Strength, Flexible Printed Wiring

2.4.21F Land Bond Strength, Unsupported Component Hole

2.4.22C Bow and Twist

2.4.22.1C Bow and Twist-Laminate

2.4.22.2 Substrate Curvature: Silicon Wafers with Deposited Dielectrics

2.4.23 Soldering Resistance of Laminate Materials

2.4.24C Glass Transition Temperature and Z-Axis Thermal Expansion by TMA

2.4.24.1 Time to Delamination (TMA Method)

2.4.24.2 Glass Transition Temperature of Organic Films – DMA Method

2.4.24.3 Glass Transition Temperature of Organic Films – TMA Method

2.4.24.4 Glass Transition and Module of Materials Used in High Density Interconnection (HDI) and Microvias – DMA Method

2.4.24.5 Glass Transition Temperature and Thermal Expansion of Materials Used in High Density Interconnection (HDI) and Microvias – TMA Method

2.4.24.6 Decomposition Temperature (T_d) of Laminate Material Using TGA

2.4.25C Glass Transition Temperature and Cure Factor by DSC

2.4.26 Tape Test for Additive Printed Boards

2.4.27.1B Abrasion (Taber Method) Solder Mask and Conformal Coating

2.4.27.2A Solder Mask Abrasion (Pencil Method)

2.4.28B Adhesion, Solder Mask (Non-Melting Metals)

2.4.28.1F Solder Mask Adhesion - Tape Test Method

2.4.29C Solder Mask - Adhesion to Flexible Circuits

2.4.30 Impact Resistance, Polymer Film

2.4.31A Folding, Flexible Flat Cable

2.4.32A Fold Temperature Testing, Flexible Flat Cable

2.4.33C Flexural Fatigue and Ductility, Flat Cable

2.4.34 Solder Paste Viscosity - T-Bar Spin Spindle Method (Applicable for 300,000 to 1,600,000 Centipoise)

2.4.34.1 Solder Paste Viscosity - T-Bar Spindle Method (Applicable at Less Than 300,000 Centipoise)

2.4.34.2 Solder Paste Viscosity - Spiral Pump Method (Applicable for 300,000 to 1,600,000 Centipoise)

2.4.34.3 Solder Paste Viscosity - Spiral Pump Method (Applicable at Less Than 300,000 Centipoise)

2.4.34.4 Paste Flux Viscosity - T-Bar Spindle Method

2.4.35 Solder Paste - Slump Test

2.4.36C Rework Simulation, Plated-Through Holes for Leaded Components

2.4.37A Evaluation of Hand Soldering Tools for Terminal Connections

2.4.37.1A Evaluation of Hand Soldering Tools for Printed Wiring Board Applications