

INTERNATIONAL STANDARD

**ISO
9497**

First edition
1993-07-01

Fluorspar — Experimental methods for evaluation of quality variation

*Spaths fluor — Méthodes expérimentales pour l'évaluation de la variation
de qualité*



Reference number
ISO 9497:1993(E)

AVA Documents
Document Sharing Hub

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

International Standard ISO 9497 was prepared by Technical Committee ISO/TC 175, *Fluorspar*.

© ISO 1993

All rights reserved. No part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from the publisher.

International Organization for Standardization
Case Postale 56 • CH-1211 Genève 20 • Switzerland

Printed in Switzerland

Fluorspar — Experimental methods for evaluation of quality variation

1 Scope

This International Standard specifies experimental methods for the evaluation of quality variation of fluorspar lots from the same source. These methods are to be used in conjunction with the sampling procedures specified in ISO 8868.

2 Normative reference

The following standard contains provisions which, through reference in this text, constitute provisions of this International Standard. At the time of publication, the edition indicated was valid. All standards are subject to revision, and parties to agreements based on this International Standard are encouraged to investigate the possibility of applying the most recent edition of the standard indicated below. Members of IEC and ISO maintain registers of currently valid International Standards.

ISO 8868:1989, *Fluorspar — Sampling and sample preparation*.

3 General conditions

3.1 Quality variation

The quality variation of fluorspar shall be determined by standard deviation within strata on stratified sampling and systematic sampling (denoted σ_w).

Two-stage sampling is employed in the sampling of wagons of fluorspar, in accordance with ISO 8868. However for the purposes of this International Standard an acceptable approximation of the formula for stratified sampling and systematic sampling will be used for sampling from wagons. Accordingly, the method for evaluation of variance between wagons by the two-stage sampling method is not specified in this International Standard.

3.2 Quality characteristics

The quality characteristics chosen for determining the quality variation are generally the calcium fluoride (CaF_2) content and the silica (SiO_2) content; however, it should be recognized that the moisture content, particle size distribution and other quality characteristics may have to be taken into account.

3.3 Sampling, sample preparation and testing

Sampling, sample preparation and testing of the sample for this investigation shall be carried out in accordance with the relevant International Standards.

3.4 Execution of investigation

The sample taken for routine determination of the quality of the lot may also be used for the present investigation.

The quality may vary as a result of changes in the following:

- a) ore bodies in a mine;
- b) method of mining;
- c) method of ore dressing;
- d) method of forming and reclaiming a pile;
- e) method of loading and unloading;
- f) mass of the lot.

Accordingly, it is recommended that the quality variation of lots of any given fluorspar be checked from time to time.

4 Method of investigation

The procedures for evaluating the standard deviation within strata (σ_w), applicable to both stratified sampling and systematic sampling, are described below.

4.1 Type of investigation

4.1.1 Type 1

When large lots are infrequently delivered, the quality variation may be determined from a single lot.

Divide the lot into a minimum of 10 parts of approximately equal mass. Then compose a pair of partial samples for each part by combining the increments involved in each part as shown in figure 1 and example 1.

4.1.2 Type 2

When small lots are frequently delivered, the quality variation is derived from several lots of approximately equal mass.

Divide each lot into a minimum of 10 parts of approximately equal mass. Then compose a pair of partial samples for each part by combining the increments involved in each part as shown in figure 2 and example 2.

4.1.3 Type 3

When lots are frequently delivered and the investigation by type 1 or type 2 is uneconomical, the quality variation is derived from a larger number of lots of approximately equal mass.

Compose a pair of partial samples for each lot as shown in figure 3 and example 3.

4.1.4 Type 4

In the case of sampling from a wagon-borne lot and when the increments are collected from all of the wagons of the lot or the wagons selected from the lot, the sampling scheme may be regarded as being equivalent to the method of stratified sampling.

Compose a pair of partial samples for each lot as shown in figure 4 and example 4.

In the case of sampling from a bagged lot, the sampling scheme may be regarded as being the same as sampling from a wagon-borne lot.

4.2 Number of increments and composition of partial samples

4.2.1 Number of increments

The number of increments to be collected from one or several lots for this investigation shall be twice the number of increments specified in ISO 8868:1989, table 3 and the increments shall be combined as specified in ISO 8868:1989, clause 7. The number of increments, N , shall never be less than 20.

4.2.1.1 In the case of investigation type 1, the increments shall be divided into at least 10 parts, each comprising a pair of partial samples (see figure 1 and example 1).

The number of increment(s) in a partial sample is then determined by the equation


$$\bar{n} = \frac{2N}{2k_a} \quad \dots (1)$$

where

$\bar{n}$ is the number of increment(s) in a partial sample;

$2N$ is the number of increments to be taken from a lot for the investigation, where N is the minimum number of increments given in ISO 8868:1989, table 3;

k_a is the number of parts to be created for a lot.



Key

 = One lot

 = One part

 = A pair of partial samples

Figure 1 — Schematic diagram of investigation type 1 — One lot (example for 10 parts)

4.2.1.2 In the case of investigation type 2, the increments taken from each lot shall be subdivided into several parts on a stratum basis, with at least 10 parts in total, each comprising a pair of partial samples (see figure 2 and example 2).