



ISO/IEC GUIDE 98-3/Suppl.1:2008
TECHNICAL CORRIGENDUM 1

Published 2009-05-15

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION • МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ • ORGANISATION INTERNATIONALE DE NORMALISATION
INTERNATIONAL ELECTROTECHNICAL COMMISSION • МЕЖДУНАРОДНАЯ ЭЛЕКТРОТЕХНИЧЕСКАЯ КОМИССИЯ • COMMISSION ÉLECTROTECHNIQUE INTERNATIONALE

Uncertainty of measurement —

Part 3:

Guide to the expression of uncertainty in measurement (GUM:1995)

Supplement 1:

Propagation of distributions using a Monte Carlo method

TECHNICAL CORRIGENDUM 1

Incertitude de mesure —

Partie 3: Guide pour l'expression de l'incertitude de mesure (GUM:1995)

Supplément 1: Propagation de distributions par une méthode de Monte Carlo

RECTIFICATIF TECHNIQUE 1

Technical Corrigendum 1 to ISO/IEC Guide 98-3/Suppl.1:2008 was prepared by Working Group 1 of the JCGM.

Page 68, Table C.5

Replace Table C.5 with the following. The symbols have been corrected.

ICS 17.020

© ISO/IEC 2009 – All rights reserved

Published in Switzerland

**Ref. No. ISO/IEC GUIDE 98-3/
Suppl.1:2008/Cor.1:2009(E)**

Documents
AVA Document Sharing Hub

Table C.5 — A t -distribution pseudo-random number generator (Clause C.6)

Input parameter	
ν	Degrees of freedom
Output parameter	
t	Draw from a t -distribution with ν degrees of freedom
Computation	
a) Generate two draws r_1 and r_2 independently from the rectangular distribution $R(0, 1)$ b) If $r_1 < 1/2$, form $t = 1/(4r_1 - 1)$ and $v = r_2/t^2$; otherwise form $t = 4r_1 - 3$ and $v = r_2$ c) If $v < 1 - t /2$ or $v < (1 + t^2/\nu)^{-(\nu+1)/2}$, accept t as a draw from the t -distribution; otherwise repeat from step a)	

NOTE
finite.

ν must be greater than two for the standard deviation of the t -distribution with ν degrees of freedom to be