

ERRATA

(continued to the next page)

1/2

Page	Position	Error	Correct																
15 to 20	In the column of “(Information)” of the following tables: Attached table 8, Attached table 9, Attached table 10, Attached table 11, Attached table 11 (concluded), Attached table 12, Attached table 13 and Attached table 14	$B_8^{(6)}$ $i^{(6)}$	B_8 i																
21	Attached table 15 In the column of “G”, for nominal number AHX3096	Tr520×5	Tr520×6																
22	Attached table 16 In the column of “G”, for nominal numbers AHX3130, AH3132 and AH3134	<table><tr><th>Nominal number</th><th>G</th></tr><tr><td>AHX3130</td><td>M165×3</td></tr><tr><td>AH3132</td><td>M180×3</td></tr><tr><td>AH3134</td><td>M190×3</td></tr></table>	Nominal number	G	AHX3130	M165×3	AH3132	M180×3	AH3134	M190×3	<table><tr><th>Nominal number</th><th>G</th></tr><tr><td>AHX3130</td><td>M165×3</td></tr><tr><td>AH3132</td><td>M180×3</td></tr><tr><td>AH3134</td><td>M190×3</td></tr></table>	Nominal number	G	AHX3130	M165×3	AH3132	M180×3	AH3134	M190×3
Nominal number	G																		
AHX3130	M165×3																		
AH3132	M180×3																		
AH3134	M190×3																		
Nominal number	G																		
AHX3130	M165×3																		
AH3132	M180×3																		
AH3134	M190×3																		
23	Attached table 16 (concluded) In the column of “G”, for nominal numbers AHX3192 and AHX3196	<table><tr><th>Nominal number</th><th>G</th></tr><tr><td>AHX3192</td><td>Tr510×5</td></tr><tr><td>AHX3196</td><td>Tr530×5</td></tr></table>	Nominal number	G	AHX3192	Tr510×5	AHX3196	Tr530×5	<table><tr><th>Nominal number</th><th>G</th></tr><tr><td>AHX3192</td><td>Tr510×6</td></tr><tr><td>AHX3196</td><td>Tr530×6</td></tr></table>	Nominal number	G	AHX3192	Tr510×6	AHX3196	Tr530×6				
Nominal number	G																		
AHX3192	Tr510×5																		
AHX3196	Tr530×5																		
Nominal number	G																		
AHX3192	Tr510×6																		
AHX3196	Tr530×6																		
	Attached table 17 In the column of “G”, for nominal numbers AH213, AH214 and AH215	<table><tr><th>Nominal number</th><th>G</th></tr><tr><td>AH213</td><td>M70×2</td></tr><tr><td>AH214</td><td>M75×2</td></tr><tr><td>AH215</td><td>M80×2</td></tr></table>	Nominal number	G	AH213	M70×2	AH214	M75×2	AH215	M80×2	<table><tr><th>Nominal number</th><th>G</th></tr><tr><td>AH213</td><td>M75×2</td></tr><tr><td>AH214</td><td>M80×2</td></tr><tr><td>AH215</td><td>M85×2</td></tr></table>	Nominal number	G	AH213	M75×2	AH214	M80×2	AH215	M85×2
Nominal number	G																		
AH213	M70×2																		
AH214	M75×2																		
AH215	M80×2																		
Nominal number	G																		
AH213	M75×2																		
AH214	M80×2																		
AH215	M85×2																		
24	Attached table 17 (concluded) In the column of “Nominal number of locknut to be combined”, for nominal number AH240	HN43	HNL43																
25	Attached table 19 In the column of “Nominal number of locknut to be combined”, for nominal number AHY3292	HN98	HN96																
	Attached table 19 In the column of “G” for nominal number AHX3296	Tr530×5	Tr530×6																

ERRATA

2/2

Page	Position	Error	Correct																
27	Attached table 21 In the column of "G", for nominal numbers AH2321, AH2352 and AH2356	<table><tr><th>Nominal number</th><th>G</th></tr><tr><td>AH2321</td><td>M120 × 2</td></tr><tr><td>AH2352</td><td>Tr280 × 4</td></tr><tr><td>AH2356</td><td>Tr300 × 4</td></tr></table>	Nominal number	G	AH2321	M120 × 2	AH2352	Tr280 × 4	AH2356	Tr300 × 4	<table><tr><th>Nominal number</th><th>G</th></tr><tr><td>AH2321</td><td>M115 × 2</td></tr><tr><td>AH2352</td><td>Tr290 × 4</td></tr><tr><td>AH2356</td><td>Tr310 × 5</td></tr></table>	Nominal number	G	AH2321	M115 × 2	AH2352	Tr290 × 4	AH2356	Tr310 × 5
Nominal number	G																		
AH2321	M120 × 2																		
AH2352	Tr280 × 4																		
AH2356	Tr300 × 4																		
Nominal number	G																		
AH2321	M115 × 2																		
AH2352	Tr290 × 4																		
AH2356	Tr310 × 5																		
28	Attached table 22 In the columns of "G" and "Nominal number of locknut to be combined", for nominal number AH3948	<table><tr><th>Nominal number</th><th>G</th><th>Nominal number of locknut to be combined</th></tr><tr><td>AH3948</td><td>Tr260 × 4</td><td>HNL52</td></tr></table>	Nominal number	G	Nominal number of locknut to be combined	AH3948	Tr260 × 4	HNL52	<table><tr><th>Nominal number</th><th>G</th><th>Nominal number of locknut to be combined</th></tr><tr><td>AH3948</td><td>Tr250 × 4</td><td>HN50</td></tr></table>	Nominal number	G	Nominal number of locknut to be combined	AH3948	Tr250 × 4	HN50				
Nominal number	G	Nominal number of locknut to be combined																	
AH3948	Tr260 × 4	HNL52																	
Nominal number	G	Nominal number of locknut to be combined																	
AH3948	Tr250 × 4	HN50																	
31	Attached table 25 In "Over" and "Or less" columns of " d_1 "	200	180																
32	Attached table 27 In "Over" and "Or less" columns of " d_1 "	70 200	75 170																
	Attached table 28 In the column of "Over" of d_1 (mm)	70	75																
	Attached table 28 In the column of "Or less" of d_1 (mm)	y	45																

Remarks: This erratum is for correcting the first edition of this Standard.

Japanese Standards Association