

April, 2004

ERRATA

Page 30, 31

Table 29

2 a) 1), 2 a) 2), 3 a)

Error : V terminal of secondary winding

Correct : v terminal of secondary winding

4 b)

Error : When carried out after connection in enclosure⁽²⁵⁾

Correct : When carried out after connection in enclosure

4 b) 1)

Error : When voltage transformer is unearthed type

Correct : When voltage transformer is unearthed type⁽²⁵⁾

4 b) 1.1), 4 b) 1.2)

Error : V terminal of voltage transformer secondary winding

Correct : v terminal of voltage transformer secondary winding

4 b) 2)

Error : When voltage transformer is earthed type⁽²⁵⁾

Correct : When voltage transformer is earthed type

4 b) 2.1)

Error : Secondary O terminal

Correct : Secondary o terminal

Remarks: This erratum is for correcting the first edition of this Standard.

Japanese Standards Association

Copyrighted material

April, 2004

ERRATA

Page 33

Fig. 3

Error : CT_X : current transformer under test

Correct: C_K : coupling capacitor

Page 37

Fig. 8

Error : k

Correct : kw

Remarks: This erratum is for correcting the first edition of this Standard.

Japanese Standards Association