

KES

Ferrochromium

KES R – C603A

(EST.) 1979 – 01 – 13
(REV.) 1986 – 12 – 24

Contents

1. Scope of Application
 2. Inspection Items and Inspection Method
 3. Inspection Lot
 4. Method of Sample Picking
 5. Test and Inspection
 6. Making Decision
 7. Management after Inspection
 8. Miscellaneous
- Additional Rule

1. Scope of Application

This standard determines the import inspection for Fe-Mn.

2. Inspection Items and Inspection Method

The inspection items and inspection method are as table 1.

Table 1

Inspection items	Inspection method	Remarks
Weight	Checking Inspection	
Chemical Contents	"	n = 100g each lot
Mesh	"	n = 5000g each lot

3. Inspection Lot

Consider the all products of one time delivery, less than 8 ton, as 1 inspection lot.

If the amount of one time delivery exceeds 8 ton, classify the inspection lot for every 8-ton.

4. Method of Sample Picking

(1) Sample Picking of Chemical Contents Inspection

Pick the sample up dividing randomly into 10 from a lot. After picking up 10g from each division, sample 100g.

(2) Mesh Inspection

Pick the sample up dividing randomly into 10 from a lot. After picking up 50g from each division, sample 500g.

5. Test and Inspection

5.1 Weight Inspection

It is the rule to submit a weighing certification issued by measuring place.

5.2 Chemical Contents Inspection

(1) Inspection Method

Inspection method is as table 2 following.