

KES

Carbonic Acid calcium

KES R – C610B

(EST.) 1979 – 01 – 13

(REV.) 1986 – 12 – 29

(REV.) 1991 – 06 – 18

Contents

1. Scope of Application
2. Inspection Items and Inspection Method
3. Inspection Lot
4. Method of Sample Picking
5. Test and Inspection
6. Making Decision
7. Management after Inspection
8. Miscellaneous

1. Scope of Application

This standard determines the import inspection for carbonic acid calcium, which is used for a Device material of casting Cyl'Head of our company.

2. Inspection Items and Inspection Method

The inspection items and inspection method are as table 1.

Table 1

No	Inspection items	Inspection method	Remarks
1	External appearance	Coefficient adjustment one time sampling inspection	Special inspection standard S – 2, AQL : 1.0
2	Residue on screen	Checking method	Inspected by the supplier
3	Fraction heat reduction	“	Submit the Inspection records

3. Inspection Lot

Consider the all products of one time delivery as 1 inspection lot.

4. Method of Sample Picking

(1) External Appearance

Follow the simple random sampling method of KS A 3151(Random sampling method) from a lot.

(2) Residue on Screen, fraction heat reduction

After sampling 10% of lumps of the sample by the simple random sampling method of KS A 3151 from a lot, divide them as the total sample amount to be 200g and pick up the sample and mix it well.
Here, quantity of the sampled containers shall be more than 2 EA.