

KES

Zinc Oxide

KES R – C612B

(EST.) 1979 – 01 – 13

(REV.) 1986 – 12 – 29

(REV.) 1991 – 06 – 18

Contents

1. Scope of Application
2. Inspection Items and Inspection Method
3. Inspection Lot
4. Method of Sample Picking
5. Test and Inspection
6. Making Decision
7. Management after Inspection
8. Miscellaneous

1. Scope of Application

This standard determines the import inspection for zinc oxide, which is used for a subsidiary of device material of hurry bathtub Ladle of our company.

2. Inspection Items and Inspection Method

The inspection items and inspection method are as table 1.

Table 1

Inspection items	Inspection method	Remarks
External appearance	Coefficient adjustment one time sampling inspection	Special inspection standard S – 2, AQL : 1.0
Mesh	Checking method	Inspected by the supplier
Content	o	Submit the Inspection records

3. Inspection Lot

Consider the all products of one time delivery as 1 inspection lot.

4. Method of Sample Picking

(1) External Appearance

Follow the simple random sampling method of KS A 3151(Random sampling method) from a lot.

(2) Mesh, Content

After sampling 10% of the sample by the simple random sampling method of KS A 3151 from a lot, divide them as the total sample amount to be 200g and pick up the sample and mix it well.

5. Test and Inspection

(1) Mesh

Follow KS A 5101 (Standard screen).

(2) External Appearance

Inspect the changing state with eyes.