

Guidance

G3230 A1

What good looks like – Noise

Purpose:

The purpose of this guidance document is to show examples of good practice for work activities that produce noise.

Scope:

This document is for anyone who manages or supervises work activities that produce noise.

What good looks like: Control measures to mitigate noise

Various acoustic barriers and enclosure options



Radio communication



Key points

- Use acoustic barriers to stop noise travelling
- Manage noisy process by maintaining plant and equipment being used
- Identify and sourcing out quieter equipment and machinery
- Reduce exposure time spent in a noisy environment
- Consider radio communication and noise monitoring.

Links

- [Noise management](#)
- [Noise](#)
- [Noise at work – A brief guide to controlling the risks](#)

What good looks like: Control measures to mitigate noise

Acoustic barriers noise curtain



Rubber matting on vehicles



Super silenced generator



Battery power pack



Key points

- Identify and source silent equipment and machinery
- Use acoustic barriers to stop noise travelling
- Manage noisy process by maintaining plant and equipment being used
- Reduce noise created during work activities by using rubber matting.

Links

- [Noise management](#)
- [Noise](#)
- [Noise at work – A brief guide to controlling the risks](#)