


Patrol Route Plan

Central Line Route CD24 2: Ruislip Depot (West)



R2747, Issue: A1, January 2014

Ruislip Depot



CD24 2 West

Central Line Route CD24 2: Ruislip Depot (West)

Note: This Patrol Plan contains 3 pages

Patrol starts at the west end of Ruislip Depot at the toes of 39A points

Obtain briefing from supervisor and travel to Ruislip Depot.

- Start patrol at 39A points and patrol eastwards along siding 34, past 7 points to 25 points.
- Patrol the left-hand turnout to 26 points and 27 points and 31 siding to the middle walk board.
- Cross over to 32 siding and patrol back to 27 points.
- Walk to 26 points and patrol back down 33 siding to middle walk board.
- Cross over to 34 siding and patrol back to 7 points.
- Cross over to 40A points patrol 35 siding, past 6 points, 7 points diamonds, 23 and 24 points to middle walk board.
- Cross over to 36 siding and patrol to 23 points.
- Patrol 37 siding to the back of 48 points.
- Patrol 38 to 45 sidings between maintenance buildings, to include 28, 29, 30, 31, 32 and 35 points this area.
- Walk from 35 points to the 6 foot between 37 and 38 sidings and continue west along the side of the maintenance building to the start of 38 siding.
- Patrol along 38 siding from boarded walkway to 22 points.
- Walk back to 21 points and patrol 39 siding until the boarded walkway outside the maintenance building.
- Cross over to 40 siding and patrol to 20 points.
- Walk back to 19 points and patrol 41 siding until the boarded walkway outside the maintenance building.
- Cross over to 42 siding and patrol past 18, 20 and 22 points to 7 points.
- Cross over to 6 points and patrol past 8 points to 9 points.
- Cross to 18 points and patrol 43 siding to the boarded walkway outside the maintenance building.
- Cross over to 44 siding and patrol to 9 points.
- Walk back to 13 points and patrol to 14 points and then 45 siding until the boarded walkway outside the maintenance building.
- Cross over to 46 siding and patrol up to 13 points.
- Walk to 15 points and patrol along 47 siding until the boarded walkway outside the maintenance building.
- Cross over to 48 siding and patrol past 16 points to 10 points.
- Walk back to 16 points and patrol 49 siding until the boarded walkway outside the maintenance building.
- Cross over to 50 siding and patrol past 17 points to 11 points.
- Walk back to 17 points and patrol 51 siding until the boarded walkway outside the maintenance building.
- Cross over to 52 siding and patrol past 11 points to 8 points.
- Patrol back through 3 points, 2 and 1A points to the toes of 1 points (patrol boundary with the south depot patrol).
- Inspect all P&C associated with 1 points.
- Patrol up to 1B points and along A siding to the end.
- Cross over to B siding and patrol back to 1B points.
- Cross to 94 points and patrol B1 siding to the end.