

NOTICE BOARDS

NB 000
Issue 37
December 2015



NETWORK RAIL – CONTROL COMMAND AND SIGNALLING

Current Index of Notice Boards Contained in NR/L2/SIG/11120

PUBLISHED UNDER NR/L2/SIG/11120

Document Number	Document Description	Issue	Published On
NB 123	Signalling alterations/renewal: 'Taking reasonable opportunity'	3	23/04/2015
NB 125	'Simple is Effective'	3	23/04/2015
NB 135	Returning Faulty BR930 series Relays	1	13/02/2015
NB 136	Use of Cable Ties	1	13/02/2015
NB 137	Cable and Wire Degradation: Replacement of Covers	1	13/02/2015
NB 138	Dark Mode events at MSL LC's	1	23/04/2015
NB 139	Track Circuit Bonding in S&C	1	23/04/2015
NB 140	Variation in Signal Spacing	1	23/04/2015
NB 141	AWS – Checking for Correct Height	1	23/04/2015
NB 142	Requirements for Whistle Boards	1	14/08/2015
NB 143	Level Crossing Road Traffic Lights – synchronisation of flashing red aspects	1	14/08/2015
NB 144	2BA Terminal Block Captive Link – Delamination of Plating	1	08/12/2015

NOTICE BOARDS - Cont.

NB 000
Issue 37
December 2015



NETWORK RAIL – CONTROL COMMAND AND SIGNALLING Historic Notice Boards

Document Number	Document Description	Issue	Published On
NB-001	~~Always the "Fringe"?~~ Withdrawn 25/02/2009 - Expired	1	June 2003
NB-002	~~Track Circuit Cables – Where does that Cable Go?~~ Withdrawn 25/02/2009 - Expired	1	June 2003
NB-003	~~Secondhand 'Scarce Equipment'~~ Withdrawn 25/02/2009 - Expired	1	June 2003
NB-004	~~All Aspects Shown~~ Withdrawn 25/02/2009 - Expired	1	July 2003
NB-005	~~Dorman LED Position Lights~~ Withdrawn 17/04/2009 - Expired	1	August 2003
NB-006	~~Track Circuit Tail Cables: Disconnection Box To Rails Arrangement.~~ Withdrawn 24/02/2014 – Expired and entered onto change database ref CRL0075	1	October 2003
NB-007	~~Positioning Of Signs~~ Withdrawn 25/02/2009 - Expired	1	October 2003
NB-008	~~Signalling Disconnections~~ Withdrawn 25/02/2009 - Expired	1	October 2003
NB-009	~~Double Wound Relays~~ Withdrawn 25/02/2009 - Expired	1	October 2003
NB-010	~~Yodalarm Y03~~ Withdrawn 25/02/2009 - Expired	1	October 2003
NB-011	~~Clamp Lock Power Packs – Incorrect Wiring~~ Withdrawn 25/02/2009 - Expired	1	November 2003
NB-012	~~Covers on Serviced BR030 – Style Relays 1~~ Withdrawn 25/02/2009 - Expired	1	January 2004
NB-013	~~Covers on Serviced BR030 – Style Relays 2~~ Withdrawn 25/02/2009 - Expired	1	January 2004
NB-014	~~Mechanical Signal Box Lever Locks – Copper Filings Cause Failure~~ Withdrawn 25/02/2009 - Expired	1	January 2004
NB-015	~~Route Indicators Erroneously Remaining Off~~ Withdrawn 25/02/2009 - Expired	1	March 2004
NB-016	~~Incorrect Fluid in RCPL Power Packs~~ Withdrawn 25/02/2009 - Expired	1	June 2004
NB-017	~~P Style Relay Springs~~ Withdrawn 25/02/2009 - Expired	1	June 2004
NB-018	~~AC Phase Sensitive Circuits~~ Withdrawn 25/02/2009 - Expired	1	June 2004
NB-019	~~Aspect Sequences~~ Withdrawn 25/02/2009 - Expired	1	June 2004
NB-020	~~RT/SMS Test 31~~ Withdrawn April 2005 – Incorporated into SMS Test 31	2	August 2004
NB-021	~~Preparation and Return of SSI Data EPROM's to National Records Group~~ Withdrawn 02/06/2012 – Expired	1	July 2004
NB-022	~~Western Region Type Barriers – Correct Adjustment of Counter Balance Weights~~ Withdrawn April 2005 – Incorporated into SMS LC29 App B	1	August 2004
NB-023	~~Clamp Lock Microswitches – Incorrect Wiring~~ Withdrawn 17/04/2009 - Expired	2	November 2004
NB-024	~~Servicing of Track Relays~~ Withdrawn April 2005 – Incorporated into RT/E/S/11129, issue 4	1	September 2004
NB-025	~~Wrong Side Failure Recovery of Equipment~~ Withdrawn 17/04/2009 - Expired	2	October 2004