


Ref	NR/GN/SIG/19101
Issue	I
Date	August 2005

Business Process Document

Good Practice Guide - ACIC Track Circuit Leaf Fall Detection Unit


Endorsement & Authorisation

Endorsed by:



A Simmons, Professional Head of Signal Engineering

Authorised by:



A McNaughton, Chief Engineer

Accepted for issue by:



P McAleer, Head of Standards Development Process

This document is the property of Network Rail. It shall not be reproduced in whole or part nor disclosed to a third party without the written permission of the Standard Owner.

©Copyright 2005 Network Rail

Uncontrolled copy once printed from its electronic source.

Published & Issued by: Network Rail 40 Melton Street, London NW1 2EE



Ref:	NR/GN/SIG/19101
Issue:	I
Date:	August 2005

Issue record

Issue	Date	Comments
I	August 2005	Initial Issue

Disclaimer

In issuing this document for its stated purpose, Network Rail makes no warranties, express or implied, that compliance with all or any documents it issues is sufficient on its own to ensure safe systems of work or operation. Users are reminded of their own duties under health and safety legislation.

Supply

Copies of documents are available electronically, within Network Rail's organisation. Hard copies of this document will be available to Network Rail employees on request to the Document Controller and to other organisations from Technical Indexes Ltd (01344 404409)

Ref:	NR/GN/SIG/19101
Issue:	1
Date:	August 2005

Contents

1	Background	4
2	Fitment Sites	4
3	The Leaf Fall Detector Hardware	5
4	Operations	5
5	Software	5
6	Installation and Commissioning	5
7	Maintenance	5
8	Product Acceptance	5

