

Ref:	NR/L2/ELP/27009/MOD C05
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
05	REPLACEMENT OF ILLEGIBLE STRUCTURE NUMBER PLATES (STENCILLED TYPES)
COMPONENT	Various stencilled types of structure number plate.
PROBLEM	Illegible structure number plates lead to lost time due to inaccurate location reports of incidents or defects; this is also a safety issue due to incorrect identification of switching or earth locations.
	

Reference Information	
Ellipse standard job number	13005
Ellipse standard job description	Replace stencilled structure number plate
Category	Structure
Priority	Yes (on structures with switches or DEPs)
Types of OLE affected	Mk1; Mk2
Original equipment dates	Before 1964



Ref:	NR/L2/ELP/27009/MOD C05
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
05	REPLACEMENT OF ILLEGIBLE STRUCTURE NUMBER PLATES (STENCILLED TYPES)
ACTION REQUIRED	<p>1. Replace the illegible structure number plates with die pressed aluminium plates to drawing 1/148/812.</p>  