

Ref:	NR/L2/ELP/27009/MOD C06
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2


OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET

06

REPLACEMENT OF ILLEGIBLE STRUCTURE NUMBER PLATES (SELF ADHESIVE PLASTIC TYPES)

COMPONENT Plastic self-adhesive structure number plates

PROBLEM Illegible structure number plates lead to lost time due to inaccurate location reports of incidents or defects; this is also a safety issue due to incorrect identification of switching or earth locations.



Reference Information

Ellipse standard job number	13006
Ellipse standard job description	Replace plastic structure number plate
Category	Structure
Priority	Yes (on structures with switches or DEPs)
Types of OLE affected	Mk3a; Mk3b
Original equipment dates	1973 - 1986



Documents
Document Sharing Hub

Ref:	NR/L2/ELP/27009/MOD C06
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
06	REPLACEMENT OF ILLEGIBLE STRUCTURE NUMBER PLATES (SELF ADHESIVE PLASTIC TYPES)
ACTION REQUIRED	<p>1. Replace the illegible structure number plates with die pressed aluminium plates to drawing 1/148/812.</p>  