


Ref:	NR/L2/ELP/27009/MOD C08
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
08	REPLACEMENT OF SOLID CORE PORCELAIN INSULATORS IN TERMINATIONS VULNERABLE TO VANDALISM CATASTROPHIC FAILURE
COMPONENT	Solid core porcelain insulators in termination arrangements.
PROBLEM	Any damage to the porcelain core of the insulator results in catastrophic failure and dewirement. 
ACTION REQUIRED	Replace solid core porcelain insulators in terminations with the appropriate equivalent polymeric insulator.

Reference Information	
Ellipse standard job number	13008
Ellipse standard job description	Replace solid core porcelain term. INS.
Category	Insulators
Priority	No
Types of OLE affected	Ex-DC; Mk1; Mk2; Mk3
Original equipment dates	Before 1976




Ref:	NR/L2/ELP/27009/MOD C08
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET

08

REPLACEMENT OF SOLID CORE PORCELAIN INSULATORS IN TERMINATIONS VULNERABLE TO VANDALISM CATASTROPHIC FAILURE



Part number 91/398 – equivalent to Item A21 (Mark 1 solid core tension insulator)