

Ref:	NR/L2/ELP/27009/MOD C19
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
19	REPLACEMENT OF STEATITE AND PORCELAIN PRODUCTS INSULATORS PRONE TO FAILURE
COMPONENT	Mark 1 porcelain insulators manufactured by “Steatite & Porcelain”.
PROBLEM	These insulators are prone to degradation of the porcelain over time. This includes longitudinal and circumferential cracking of the insulator body and loosening of the end caps. This leads to 25kV flashover and catastrophic failure. The insulators can be identified by the manufacturers logo:
ACTION REQUIRED	Replace with polymeric equivalent insulator.

Reference Information	
Ellipse standard job number	13019
Ellipse standard job description	Replace Steatite and Porcelain products INS
Category	Insulators
Priority	No
Types of OLE affected	Mk1
Original equipment dates	1960



Ref:	NR/L2/ELP/27009/MOD C19
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

Blank Page

Copyright Network Rail