


Ref:	NR/L2/ELP/27009/MOD C29
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
29	REMOVAL OF 'GOAL POST' UPLIFT STOP ASSEMBLIES FOR FLAT REGISTRATION ARMS
COMPONENT	'Goal post' uplift stops for flat registration arms, to drawing K12465.
PROBLEM	These uplift stops tend to rotate over time because of inadequate available uplift. This causes them to become foul of pantographs.
 <p>NOTE: DIM X TO BE DETERMINED BY USING THE FOLLOWING FORMULA.</p> $DIM X = 9\frac{1}{2} - [UPLIFT (AS REQD) + DIM A]$ <p>DRG NO K12465-99</p>	
ACTION REQUIRED	<ol style="list-style-type: none"> 1. Remove this type of uplift stop. 2. Where an uplift stop is needed, replace the registration arm for a tubular type.

Reference Information	
Ellipse standard job number	13029
Ellipse standard job description	Remove 'Goal Post' uplift stop assembly
Category	Registration arm
Priority	No
Types of OLE affected	Mk 1
Original equipment dates	1958 - 1967

Ref:	NR/L2/ELP/27009/MOD C29
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

[Blank page]