OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET

52	**CONVERSION OF OBSOLETE MARK 2 EQUIPMENT**
COMPONENT	Mark 2 overhead line equipment
PROBLEM	Most component parts for this equipment are now obsolete. Mark 2 is generally considered to have been a prototype for Mark 3 equipment.
ACTION REQUIRED	Replace components with the appropriate equivalent Mark 3 design. Remove stitch wires when working on the appropriate spans. Replace whole system with a current equivalent design.

Reference Information	
Ellipse standard job number	13052
Ellipse standard job description	Convert obsolete Mk 2 OLE
Category	System
Priority	No
Types of OLE affected	Mk 2
Original equipment dates	1969

--`,,,,,,`,,,,,,`,,`,,,,,,,,`-`-`,,`,,`,`,,`---

Documents
Document Sharing Hub

Copyright Network Rail
Provided by IHS under license with Network Rail
No reproduction or networking permitted without license from IHS

Licensee=Weston Williamson/5989497001, User=sam, albett
Not for Resale, 03/27/2016 20:34:35 MDT

Full document details: NR NR-L2-ELP-27009-MOD C52 I 2011

[Blank page]

--`,,,,,,`,,,,,,`,,`,,,,,,,,`-`-`,,`,,`,`,,`---

Documents
Document Sharing Hub

Copyright Network Rail
Provided by IHS under license with Network Rail
No reproduction or networking permitted without license from IHS

Licensee=Weston Williamson/5989497001, User=sam, albett
Not for Resale, 03/27/2016 20:34:35 MDT

Full document details: NR NR-L2-ELP-27009-MOD C52 I 2011