

Ref:	NR/L2/ELP/27009/MOD C60
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
60	MODIFICATION OF TRACK FEEDER WIRES WITH >3m UNSUPPORTED WIRE
COMPONENT	Aluminium track feeder cables to isolator connection plates, with unsupported lengths greater than 3 m.
PROBLEM	Movement of the track feeder wire in windy conditions stresses the bimetal lug connection to the isolator connection, leading to a risk of the lug failing at the friction weld interface.
ACTION REQUIRED	Fit additional support steelwork to the unsupported feeder.

Reference Information	
Ellipse standard job number	13060
Ellipse standard job description	Modify feeder cable >3.0m unsupported
Category	Conductors
Priority	Yes
Types of OLE affected	Mk3a; Mk3b; Mk3c
Original equipment dates	After 1976



Ref:	NR/L2/ELP/27009/MOD C60
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

Blank page

Copyright Network Rail