

Ref:	NR/L2/ELP/27009/MOD C67
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	1 of 2

OVERHEAD LINE CAMPAIGN CHANGES – DATA SHEET	
67	MODIFY BALANCE WEIGHT ANCHOR TUBES IN BALFOUR BEATTY SUNDERLAND DIRECT OLE EQUIPMENT
COMPONENT	Balance weight anchor tubes, Sunderland Direct 1500 V d.. OLE only.
PROBLEM	With the existing design, balance weights are not visible to maintenance staff and therefore it is difficult to check correct function.
ACTION REQUIRED	Install Perspex viewing windows in balance weight anchor tubes.

Reference Information	
Ellipse standard job number	13067
Ellipse standard job description	Modify BWA tubes 1500V – Perspex viewer
Category	Tube fittings
Priority	No
Types of OLE affected	Sunderland direct
Original equipment dates	After 2002



Documents
Document Sharing Hub

Ref:	NR/L2/ELP/27009/MOD C67
Issue:	1
Date:	03/12/2011
Compliance date:	03/03/2012
Page	2 of 2

Blank Page

Copyright Network Rail