


Ref:	NR/L3/ELP/27134
Issue:	3
Date:	26 August 2008
Compliance date:	26 August 2008

Level 3

Reporting of electric track equipment defects


Endorsement and Authorisation

Endorsed by:



Philip Frazer, Working Group Chair

Authorised by:



Kevin Lydford, Steering Group Chair

Accepted for issue by:



Mick McManus, National Standards Manager

This document is the property of Network Rail. It shall not be reproduced in whole or part nor disclosed to a third party without the written permission of Network Rail.

© Copyright 2008 Network Rail.

Uncontrolled copy once printed from its electronic source.

Published and Issued by Network Rail, 40 Melton Street, London NW1 2EE.

Network Rail



Documents

Document Sharing Hub

Ref:	NR/L3/ELP/27134
Issue:	3
Date:	26 August 2008
Compliance date:	26 August 2008

Issue record

Issue	Date	Comments
3	26 August 2008	Phase 2A / Engineering reorganisation responsibility change

Compliance

This Network Rail standard is mandatory and shall be complied with by Network Rail and its contractors if applicable from 26 August 2008.

When this standard is implemented, it is permissible for all projects that have formally completed GRIP Stage 4 to continue to comply with the Issue of any relevant Network Rail Standards current when GRIP Stage 4 was reached and not to comply with requirements contained herein, unless the designated Standard Owner has stipulated otherwise in the accompanying Briefing Note.

Disclaimer

In issuing this document for its stated purpose, Network Rail makes no warranties, express or implied, that compliance with all or any documents it issues is sufficient on its own to ensure safe systems of work or operation. Users are reminded of their own duties under health and safety legislation.

Supply

Copies of documents are available electronically, within Network Rail's organisation. Hard copies of this document may be available to Network Rail people on request to the relevant controlled publication distributor. Other organisations may obtain copies of this document from IHS (Technical Indexes Ltd) tel: 01344 328039.

Copyright Network Rail