

Title: Calibration Of Megger Series 4 Insulation And Continuity Tester

Scope

Work Instruction for the internal calibration of Megger Series 4 Insulation and Continuity Testers. To be used in the absence of a manufacturers calibration instruction.

Preparation

Calibration must be carried out using Category A Master instruments as required.

Equipment required;

- 1.1 45° instrument balance stand.
- 1.2 Keithley D.M.M. Model 136.
- 1.3 Megadek High Resistance Box.
- 1.4 J.J. Instruments Decade Resistance Box.

Method

- 2.1 All calibration results must be entered on the results sheets (see appendix A).
- 2.2 Note the lab. temperature / R.H. and enter onto the results sheet.
- 2.3 Carry out test 1 using item 1.1.
- 2.4 Carry out test 2 using item 1.2.
- 2.5 Carry out test 3.
- 2.6 Carry out tests 4 to 9 using item 1.3.
- 2.7 Carry out tests 10 to 17 using items listed in 1.4.
- 2.8 Complete the results sheet header and enter Pass / Fail.

- All records must be kept for audit purposes

References

Appendix A Calibration Results for Megger Series 4 Insulation and Continuity Tester

Title: Calibration Of Megger Series 4 Insulation And Continuity Tester

Appendix A

Calibration Results for Megger Series 4 Insulation and Continuity Tester

Model Serial No

Date Result

Lab Temp / RH Operator

User Location Certificate No

Accuracies quoted are from manufacturer's specifications or relevant British Standard.

Movement Check

Test 1 Instrument balance. The pointer must remain within the marked scale at 45° all planes Pass / Fail

Output Voltage into 10 Mohms

Test No	Allowed Limits	Actual Output	Result
2	450 - 550		Pass / Fail

Neon Indication Check

Test 3 Connect the UUT to a 240V mains supply. **Do Not Operate Button.** Does the live line neon illuminate Pass / Fail

Insulation Range Accuracy ± 0.9 mm of marked value

Test No	Resistor Value Mohms	Specified Accuracy	Result
4	INF	± 0.9 mm	Pass / Fail
5	10	± 0.9 mm	Pass / Fail
6	1	± 0.9 mm	Pass / Fail
7	0.1	± 0.9 mm	Pass / Fail
8	0.01	± 0.9 mm	Pass / Fail
9	0	± 0.9 mm	Pass / Fail

Continuity Test Accuracy ± 0.9 mm of marked scale

Test No	Resistor Value Mohms	Specified Accuracy	Result
10	100	± 0.9 mm	Pass / Fail
11	50	± 0.9 mm	Pass / Fail
12	20	± 0.9 mm	Pass / Fail
13	10	± 0.9 mm	Pass / Fail
14	5	± 0.9 mm	Pass / Fail
15	1	± 0.9 mm	Pass / Fail
16	0.1	± 0.9 mm	Pass / Fail
17	0	± 0.9 mm	Pass / Fail