

Task Risk Control Sheet

Dismantling of OLE and work under tension

RCS No: NR/L3/MTC/RCS0216/OLE07
Issue: 3



- **Electrocution**
- **Working at height**
- **Sudden release of OLE**

Personnel Involved

E&P	✓
S&T	
P/Way	
Off Track	
Property	

Tools / Equipment - Standard OHL tool kit - Rigging equipment

Plant - MEWP / Scaffold Tower / Train / Ladder

Key Risks	Controls	Implemented By
Electrocution	<ul style="list-style-type: none"> • See Risk Control Sheet NR/L3/MTC/RCS0216/OLE06 - High Level OLE Work • See Risk Control Sheet NR/L3/MTC/RCS0216/GA21 - Working Near Electrical Overhead Line Equipment 	Team Leader
Inadvertent release	<ul style="list-style-type: none"> • Training / briefing on correct techniques and associated risks 	Line Manager
Equipment failure	<ul style="list-style-type: none"> • Maintenance and inspection of tools, clamps and calibrated in date, rigging equipment 	All Staff
Entrapment	<ul style="list-style-type: none"> • Correctly identified rigging equipment / pull lifts 	Team leader
Radial loads	<ul style="list-style-type: none"> • Briefing of staff on method of work and rigging requirements 	Team leader
Incorrect rigging techniques	<ul style="list-style-type: none"> • Limbs/Loose clothing to be kept clear of operation of equipment • Stand safe side of radial load • Gloves shall be worn during rigging • Approved impact resistant eye protection shall be worn • Inspect tools prior to use 	All Staff
Working at height	<ul style="list-style-type: none"> • See Risk Control Sheet NR/L3/MTC/RCS0216/GH04 – Work at Height • Use of ladders see Risk Control Sheet NR/L3/MTC/RCS0216/OLE06 –High Level OLE Work • Safety harness shall be used where required by Risk Control Sheet 	
Struck by Train	<ul style="list-style-type: none"> • See Risk Control Sheet NR/L3/MTC/RCS0216/GA001 – Work On or Near the Line 	Team Leader / COSS

Task Risk Control Sheet

PPE Required by NR / Maintenance Policy



Wear Head Protection



Wear Foot Protection



Wear Hi Visibility Clothing



Wear Safety glasses to BS EN166.F

If safety glasses introduce a risk (ie weather conditions) then the Team Leader shall assess the risk. The outcome of the assessment shall be recorded on the SSOWPS pack and safety glasses may be removed.

This does not supersede the requirements for eye protection detailed on relevant Task Risk Control Sheets.

Additional PPE Required by Task Risk Control Sheet



Wear Hand Protection



Wear Safety Harness